



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 NISSAN PATROL

LE T2 | 136,442 KM

VIN: JN8AY2NY5J9353018

Car highlights



Power packed

Engine size of 5.6 Litres & 8.0 cylinders



Cruise control

Cruise control to drive with ease & comfort



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat, Ventilated Seats

Basic Details

 Kilometers	136442	 Specs	Yes
 Engine	5.6L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	8 Seats	 Number of keys	1 Keys
 VIN number	JN8AY2NY5J9353018		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Climate Control AC	
Rear Armrest with cupholder	
Power Folding Mirrors	
Power Tailgate/ Power Trunk	
Rear Defogger	
Cruise Control	
Steering Mounted Audio Controls	
Ventilated Seat	
Cool Box	
Central Armrest	

Remote Engine Start



Automatic Headlights

**Exteriors**

Fog Light Front



Running Lights



Rear Bumper Spoiler



Trailer Hook / Coupling



LED Headlights



Halogen Headlights

**Safety & Security**

Navigation



Parking Sensors Front



Parking Sensors Rear



Reverse Camera



Traction Control



Airbag Curtain Shield



Airbag Driver Front



ABS



Central Locking



Child Safety Locking

**Entertainment**

Rear Seat Entertainment



Bluetooth Player



USB Charging Port



Infotainment System



USB player

 **Performance**

Hill Descent Control



Differential Locks



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Frame Extension Cover: Scratch < 50mm

Front right door



Panel: Low Visibility Dent < 30mm, Light

Scuffing < 50mm

Rear left door



Panel: Dent < 30mm, Scratch < 50mm

Rear right door



Panel: Low Visual Dent < 30mm, Light

Scuffing < 50mm

Fenders Condition

Left Fender

Condition: Light Scuffing < 50 mm, Low Visual Dent < 30mm

Right Fender



Condition: Light Scuffing < 50mm

Quarter Panels Condition

Left Quarter Panel



Condition: Scratch < 50mm

Right Quarter Panel



Condition: Low Visual Dent < 30mm, Light Scuffing < 50mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood



Bonnet: Light Scuffing < 50mm

Trunk Condition

Trunk



Door Trim: Light Scuffing < 50mm

Trunk condition

Trunk



Roof Condition

Roof		
Pillars Condition		
Left A Pillar		Right A Pillar
Left A to B Pillar Beading		Right A to B Pillar Beading
Right A to B Pillar		Left B Pillar
Left B Pillar Trim		Left B to C Pillar Beading
Right C Pillar Trim		Right B to C Pillar Low Visual Dent < 50mm
Right B to C Pillar Beading		Left C Pillar Scratch < 50mm
Running Board Condition		
Left Running Board		Right Running Board
Front Left Sill Trim: Scratch < 80mm		Front Right Sill Trim: Light Scuffing < 80mm
Sunroof Glass Condition (If Equipped)		
Sun Roof Glass		
Windshield Condition		
Front Windshield		Rear Windshield
Structural Assessment		
Chassis Condition		Radiator Support
Apron		Boot Floor
Firewall Condition		Cowl Top
Head Light Support Condition		
Cowl Top		
Cowl Top		
Rear View Mirror Condition		
Left Hand Side Mirror		Left Side Mirror
Right Side Mirror		Right Hand Side Mirror
Alloy Wheel/ Rim		
Left Front Alloy/ Rim		Left Rear Alloy/ Rim
Right Front Alloy/ Rim		Right Rear Alloy/ Rim

Spare Alloy/ Rim Condition		
Wheel cover		Antenna
Grill Condition		Monogram
Window Glass		Wiper
Panel Condition		
Rear Trunk Panel		
Scratch < 50mm		

Engine & Transmission

Engine		
Engine Body		Engine Performance
Engine Oil (Condition & Level)		Exhaust System
Radiator Condition		Radiator Coolant
Battery		
Battery Terminal & Tightness		
Fuel System		
Fuel Cap		Fuel Tank
Transmission Operation		
Gear Shifting		Drive Axle
4*4 Condition (If Applicable)		Transmission Fluid

Steering, Suspension & Brakes

Steering		
Steering wheel		
Brake System		
Brake Master Cylinder		Brake Disc & Brake Pad
Brake Fluid		
Pedals		
Suspension		

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Navigation System



Music System



Sunroof Operation

Sunroof



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch	✓	Rear Left AC Vent	✓
Rear Defogger	✓	USB Charging Port	✓
Rear Entertainment	✓	Power/ Manual Windows	✓
Seat Heaters	✓		

Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Dashboard Upholstery: Minor Scuffing/ Crack/	!	Gear Shift Knob: minor imperfection	!
Fair Use Wear			
 Cup Holder	 ✓	Glove Box	
		Glove Box: Minor Scuffing/Defiguration/	!
		Melted	
 Steering Wheel	 ✓	Sunvisor	✓
 Seat Upholstery			
Driver Seat: Minor Smudge/ Cracks, Minor	!	Manual Seat Movement	✓
Leather/ Fabric Fair Use Wear/ Tears			
 Seat Belts	 ✓	Head Rest	✓
 Door Controls And Trim		Grab Handle	✓
Front Right Door: Light Scuffing	!		
 Carpet		Headliner	
Front Left Floor Mat: Smudge/Burn/Crack	!	Front Left: Light Smudge/Disfiguration	!
 Rear View Mirror	 ✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
 Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%

RHS Front Tyre

<75%

RHS Rear Tyre

<75%

Spare Tyre

<75%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE