



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



**2018 BMW 318i**

**EXCLUSIVE | 99,966 KM**

VIN: WBA8E3108JA671767

## Car highlights

### **Service History**

Service history available



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**

Enjoy your drive with bluetooth



### **Amazing Comfort**

Power driver seat

## Basic Details

 Kilometers	<b>99966</b>	 Specs	<b>Yes</b>
 Engine	<b>1.5L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Rear Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color White</b>
 Interior Trim	<b>Leather Trim</b>	 Number of Airbags	<b>6 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>1 Keys</b>
 VIN number	<b>WBA8E3108JA671767</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>	
Climate Control AC	
Rear Armrest with cupholder	
Power Folding Mirrors	
Steering Column Adjuster	
 <b>Exteriors</b>	

Fog Light Front		Running Lights	
LED Headlights			
<b>Safety &amp; Security</b>			
Parking Sensors Front		Parking Sensors Rear	
Reverse Camera		Traction Control	
Airbag Curtain Shield		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
<b>Entertainment</b>			
Bluetooth Player		Infotainment System	
USB player			

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Inner Handle: Color/Chrome Dullness

Front right door



Panel: Light Scuffing < 50mm, Low Visibility

Dent < 30mm, Paint Chip-off < 5mm

Rear left door



Rear right door



Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm

Fenders Condition

Left Fender



Condition: Scratch < 50mm

Right Fender



Right Fender: Scratch < 50mm, Paint Chip-off < 5mm

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm, Chip< 8mm

Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



## Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading Beading Crack/ Tear < 5mm	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	

## Running Board Condition

Left Running Board		Right Running Board	
--------------------	--	---------------------	--

## Sunroof Glass Condition (If Equipped)

Sun Roof Glass	
----------------	--

## Windshield Condition

Front Windshield		Rear Windshield	
------------------	--	-----------------	--

## Structural Assessment

Chassis Condition		Radiator Support	
-------------------	--	------------------	--

Apron		Boot Floor	
-------	--	------------	--

Firewall Condition		Cowl Top	
--------------------	--	----------	--

Head Light Support Condition	
------------------------------	--

## Cowl Top

Cowl Top	
Fair Use Wear/Crack<5mm	

## Rear View Mirror Condition

Left Hand Side Mirror		Left Side Mirror	
-----------------------	--	------------------	--

Right Side Mirror	
-------------------	--

## Alloy Wheel/ Rim

Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
-----------------------	--	----------------------	--

Right Front Alloy/ Rim		Right Rear Alloy/ Rim Rim: Alloy Face/ Scuff < 50mm	
------------------------	--	--	--

Wheel cover		Antenna	
-------------	--	---------	--

Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel			✓

---

## ⌚ Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓	Transmission Fluid	✓

---

## ⌚ Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

## Electricals, Controls & Lights

### Keys

Master Key		Spare Key(s)	
------------	---	--------------	---

### Door Locks

Child Safety Locking	
----------------------	---

### Dashboard

Instrument Panel	
------------------	---

### Airbags

Airbags	
---------	---

Controls		Cruise Control	
----------	---	----------------	---

Infotainment Display		Engine Sensors	
----------------------	---	----------------	---

OBD Connector		Music System	
---------------	---	--------------	---

Sunroof Operation			
-------------------	--	--	--

Sunroof	
---------	---

Lights			
--------	--	--	--

Headlight		Interior Lights	
-----------	---	-----------------	---

Tail Light Cluster		Daylight Running Lights	
--------------------	---	-------------------------	---

License Plate Light		Fog Lights	
---------------------	---	------------	---

Air Conditioning			
------------------	--	--	--

AC Cooling		AC Switch	
------------	---	-----------	---

AC System Leaks		Center AC Vent	
-----------------	---	----------------	---

Front Right AC Vent		Heater	
---------------------	---	--------	---

Parking Sensors		Rear Defogger		
		Not Working		

USB Charging Port		Power/ Manual Windows	
-------------------	---	-----------------------	---

 <b>Interiors &amp; Luggage</b>			
--	--	--	--

Dashboard And Instrument Panel		Central Console Box: Minor Crack/Fair Use Wear/ Scuffing, Minor Color Low Brightness	
Cup Holder		Glove Box	
Steering Wheel		Sunvisor	
Seat Upholstery		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	
Carpet		Headliner	
Rear View Mirror		Toolkit	

## Tyres

### Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	

### Tyres Depth (Remaining)

LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	No spare tyre		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE