



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2019 VOLKSWAGEN TIGUAN**

**R LINE | 75,548 KM**

VIN: WVGCD1AXXKW303253

## **Car highlights**



### **Panoramic Roof**

This car has a panoramic roof



### **Cruise control**

Cruise control to drive with ease & comfort



### **Apple play**
















Enjoy your drive with apple play



### **Amazing Comfort**












Power driver seat, Memory Seats





Basic Details

 Kilometers	75548	 Specs	Yes
 Engine	2.0L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	WVGCD1AXXKW303253		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Heads up Display		Climate Control AC	
Cruise Control		Memory Seats	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Power Folding Mirrors		Power Tailgate/ Power Trunk	
Rear Defogger		Central Armrest	

Automatic Headlights	✓		
 <b>Safety &amp; Security</b>			
360 degree Camera	✓	Navigation	✓
Parking Sensors Front	✓	Parking Sensors Rear	✓
Auto Park Assist	✓	Reverse Camera	✓
Traction Control	✓	Front Camera	✓
Side Camera	✓	Airbag Curtain Shield	✓
Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓
 <b>Exteriors</b>			
Fog Light Front	✓	Roof Rails	✓
Running Lights	✓	Rear Bumper Spoiler	✓
HID Headlights	✓		
 <b>Performance</b>			
Paddle Shift	✓		
 <b>Entertainment</b>			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓	USB Charging Port	✓
Infotainment System	✓	USB player	✓




# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door	
Moulding: Paint Chip-off < 5mm		Moulding: Scuffing > 50mm	
Rear left door		Rear right door	
Moulding: Paint Chip-off < 5mm		Panel: Low Visual Dent < 30mm, Paint Chip-off < 5mm	

### Fenders Condition

Left Fender		Right Fender	
Condition: Low Visual Dent < 30mm			

### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	-------------------------------------------------------------------------------------	---------------------	---------------------------------------------------------------------------------------

### Front Bumper Condition

Front Bumper	
--------------	-------------------------------------------------------------------------------------

### Rear Bumper Condition

Rear Bumper	
-------------	-------------------------------------------------------------------------------------

### Hood Condition

Hood	
Bonnet: Paint Chip-off < 5mm	

### Trunk Condition

Trunk	
-------	-------------------------------------------------------------------------------------

### Trunk conditon

Trunk	
-------	-------------------------------------------------------------------------------------

### Roof Condition

Roof	
------	-------------------------------------------------------------------------------------

### Pillars Condition

Left A Pillar		Right A Pillar	
---------------	-------------------------------------------------------------------------------------	----------------	---------------------------------------------------------------------------------------

Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	!
Right B to C Pillar Beading	✓	Low Visual Dent < 50mm	
Running Board Condition		Left C Pillar	✓
Left Running Board	✓	Right Running Board	!
Sunroof Glass Condition (If Equipped)		Front Right Sill Trim: Light Scuffing < 80mm	
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield			
Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm	!	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	!	Right Rear Alloy/ Rim	!
Rim: Alloy Face/ Scuff > 50mm		Rim: Alloy Edge/ Scuff > 80mm	
Spare Alloy/ Rim Condition	✓		

Antenna	✓	Grill Condition	✓
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	Transmission Fluid	✓

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Heads Up Display



Infotainment Display



Engine Sensors



OBD Connector



Navigation System



Music System



Sunroof Operation

Sunroof



Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Fair Use Wear



Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓
Seat Heaters	✓	Memory Seats	✓

## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Gear Shift Knob: Knob Fair Use Wear	!
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<55%		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE