



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2014 AUDI A4

TFSI | 131,490 KM

VIN: WAUACCF1EN012017

Car highlights



Supercharger/turbocharger

This car has a Supercharger/turbocharger



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat



Basic Details

| | | | |
|--|-------------------|---|----------------------|
|  Kilometers | 131490 |  Specs | Yes |
|  Engine | 1.8L |  Option Type | Semi Loaded |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SEDAN |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Black |
|  Interior Trim | Leather Trim |  Number of Airbags | 6 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | WAUACCFL1EN012017 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|----------------------|---|
|  Comfort & Convenience | | | |
| Climate Control AC |  | Cruise Control |  |
| Steering Mounted Audio Controls |  | Rear Defogger |  |
| Central Armrest |  | Automatic Headlights |  |
|  Exteriors | | | |
| Fog Light Front |  | Running Lights |  |

| | | |
|--|---|-----------------------|
| HID Headlights | ✓ | |
|  Safety & Security | | |
| Parking Sensors Rear | ✓ | Traction Control ✓ |
| Airbag Curtain Shield | ✓ | Airbag Driver Front ✓ |
| ABS | ✓ | Central Locking ✓ |
| Child Safety Locking | ✓ | |
|  Entertainment | | |
| Bluetooth Player | ✓ | Infotainment System ✓ |




150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior



Doors condition

| | | | |
|--|---|------------------------------|---|
| Front left door |  | Front right door |  |
| Handle: minor imperfection | | Handle: Paint Chip-off < 5mm | |
| Rear left door | | Rear right door | |
| Panel: Paint Chip-off < 5mm, Scratch < 50mm, Dent < 30mm |  | Handle: Paint Chip-off < 5mm |  |

Fenders Condition

| | | | |
|-----------------------------------|---|--|---|
| Left Fender |  | Right Fender |  |
| Condition: Light Scuffing < 50 mm | | Condition: Acid Marks/ Bird Dropping < 5mm | |


Quarter Panels Condition

| | | | |
|--|---|--|---|
| Left Quarter Panel | | Right Quarter Panel | |
| Condition: Dent < 30mm, Paint Chip-off < 5mm |  | Condition: Chip<5mm, Low Visual Dent < 30mm, Light Scuffing<50mm |  |

Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|---|---|
| Rear Bumper | |
| Rear Bumper: Light Scuffing < 80mm, Chip< 8mm |  |

Hood Condition

| | |
|---|---|
| Hood | |
| Bonnet: Paint Chip-off < 5mm, Light Scuffing < 50mm |  |

Trunk Condition

| | |
|-------|---|
| Trunk |  |
|-------|---|

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Pillars Condition

| | | | |
|--|---|--|---|
| Left A Pillar | ✓ | Right A Pillar | ✓ |
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board Condition: Low Visual Dent < 50mm, Light Scuffing < 80mm | ! |
| Windshield Condition | | | |
| Front Windshield Condition: Driver Side/Stone Chip Mark<5mm, Passenger Side/Stone Chip Mark<8mm | ! | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Radiator Support | ✓ |
| Apron | ✓ | Boot Floor | ✓ |
| Firewall Condition | ✓ | Cowl Top | ✓ |
| Head Light Support Condition | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror Body: minor imperfection | ! | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm | ! | Left Rear Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm | ! |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm | ! |
| Spare Alloy/ Rim Condition | ✓ | | |

| | | | |
|-----------------------|---|----------|---|
| Wheel cover | ✓ | Antenna | ✓ |
| Grill Condition | ! | Monogram | ✓ |
| Light Scuffing < 50mm | | | |
| Window Glass | ✓ | Wiper | ✓ |
| Panel Condition | | | |
| Rear Trunk Panel | ✓ | | |

Engine & Transmission

| | | | |
|--------------------------------|---|--------------------|---|
| Engine | | | |
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Turbocharger/ Supercharger | ✓ | Radiator Condition | ✓ |
| Radiator Coolant | ✓ | | |
| Battery | | | |
| Battery Terminal & Tightness | ✓ | | |
| Fuel System | | | |
| Fuel Tank | ✓ | | |
| Transmission Operation | | | |
| Gear Shifting | ✓ | Drive Axle | ✓ |
| Transmission Fluid | ✓ | | |

Steering, Suspension & Brakes

| | | | |
|------------------------|---|-----------------------|---|
| Steering | | | |
| Steering wheel | ✓ | | |
| Brake System | | | |
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |
| Pedals | ✓ | | |
| Suspension | | | |

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Lights

Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



Daylight Running Lights
Right DRL: Low Brightness



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Parking Sensors



Rear Defogger
Extensive Wear Of Strip



USB Charging Port

Rear: minor imperfection



Power/ Manual Windows



Interiors & Luggage

| | | | |
|---|---|--|---|
| Dashboard And Instrument Panel | ✓ | Central Console Arm Rest: Fabric Tear / Fair Use Wear | ! |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel Steering Wheel Fair Use Wear | ! | Sunvisor | ✓ |
| Seat Upholstery Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears, Minor Smudge/ Cracks | ! | Manual Seat Movement | ✓ |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim Front Left Door: Light Scuffing/ Disfiguration | ! | Grab Handle | ✓ |
| Carpet | ✓ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

| | | | |
|----------------------------|------|---------------------------|------|
| Tyres Condition | | | |
| Left Hand Side Front Tyre | ✓ | Left Hand Side Rear Tyre | ✓ |
| Right Hand Side Front Tyre | ✓ | Right Hand Side Rear Tyre | ✓ |
| Spare Tyre | ✓ | | |
| Tyres Depth (Remaining) | | | |
| LHS Front Tyre | <55% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <55% | RHS Rear Tyre | <55% |
| Spare Tyre | <65% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE