



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2016 INFINITI QX70**

**LUXE | 113,548 KM**

VIN: JNRCS1MW8GM660348

## **Car highlights**



### **Sunroof**

This car has a sunroof



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**












Power driver seat, Memory Seats & more

Basic Details

 Kilometers	113548	 Specs	Yes
 Engine	3.7L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	JNRCS1MW8GM660348		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Memory Seats		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Power Folding Mirrors	
Ventilated Seat		Power Tailgate/ Power Trunk	
Rear Defogger		Central Armrest	

Automatic Headlights	✓	Steering Column Adjuster	✓
 <b>Exteriors</b>			
Fog Light Front	✓	Roof Rails	✓
HID Headlights	✓		
 <b>Safety &amp; Security</b>			
Parking Sensors Front	✓	Parking Sensors Rear	✓
Reverse Camera	✓	Traction Control	✓
Airbag Curtain Shield	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		
 <b>Entertainment</b>			
Bluetooth Player	✓	Infotainment System	✓
USB player	✓		

# 150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition



Front left door		Front right door Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm	
-----------------	---	--	---

Rear left door		Rear right door Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm	
----------------	---	---	---

### Fenders Condition

Left Fender Condition: Dent < 30mm, Paint Chip-off < 5mm		Right Fender Right Fender: Paint Chip-off < 5mm, Scratch < 50mm	
---	---	--	---

### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel Condition: Scratch < 50mm, Paint Chip-off < 5mm	
--------------------	---	--	---

### Front Bumper Condition

Front Bumper	
--------------	---

### Rear Bumper Condition

Rear Bumper	
-------------	---

### Hood Condition

Hood Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm	
---	---

### Trunk Condition

Trunk	
-------	---

### Trunk conditon

Trunk	
-------	---

### Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	!	Left Rear Alloy/ Rim	!
Rim: Alloy Edge/ Scuff < 80mm		Rim: Alloy Face/ Scuff < 50mm	
Right Front Alloy/ Rim	!	Right Rear Alloy/ Rim	!
Rim: Alloy Face/ Scuff < 50mm		Rim: Alloy Face/ Scuff < 50mm	

Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition Light Scuffing < 50mm	!	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Sunroof Operation

Sunroof



Lights

Headlight



Interior Lights



Tail Light Cluster



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Parking Sensors



Rear Defogger





USB Charging Port



Power/ Manual Windows





Seat Heaters	✓	Memory Seats	✓
<hr/>			
<div>  <b>Interiors &amp; Luggage</b> </div>			
Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	!
		Glove Box: Minor Color Low Brightness	
Steering Wheel	!	Sunvisor	✓
Steering Wheel Fair Use Wear			
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓
<hr/>			
<div>  <b>Tyres</b> </div>			
Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<45%		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE