



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 MERCEDES BENZ GLE 400

AMG LINE | 116,797 KM

VIN: WDCDA5GB3GA620505

## Car highlights



### Panoramic Roof

This car has a panoramic roof



### Cruise control

Cruise control to drive with ease & comfort



### Bluetooth

Enjoy your drive with bluetooth



### Amazing Comfort

Power driver seat, Memory Seats & more

## Basic Details

|  |                          |   |                             |
|--|--------------------------|---|-----------------------------|
|  Kilometers       | <b>116797</b>            |  Specs             | <b>Yes</b>                  |
|  Engine           | <b>3.0L</b>              |  Option Type       | <b>Semi Loaded</b>          |
|  Transmission     | <b>Automatic</b>         |  Drive             | <b>All Wheel Drive</b>      |
|  Body Type        | <b>SUV</b>               |  Fuel              | <b>Petrol</b>               |
|  Wheel Type       | <b>Alloy Wheels</b>      |  Exterior Color    | <b>Exterior Color White</b> |
|  Interior Trim    | <b>Leatherette Trim</b>  |  Number of Airbags | <b>7 Airbags</b>            |
|  Seating Capacity | <b>5 Seats</b>           |  Number of keys    | <b>2 Keys</b>               |
|  VIN number      | <b>WDCDA5GB3GA620505</b> |   |                             |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  Safety & Security |   |                       |   |
|---|---|-----------------------|---|
| 360 degree Camera   |  | Navigation            |  |
| Parking Sensors Front   |  | Parking Sensors Rear  |  |
| Reverse Camera  |  | Blind Spot Monitor    |  |
| Traction Control  |  | Front Camera          |  |
| Side Camera   |  | Airbag Curtain Shield |  |

|                      |   |                     |   |
|----------------------|---|---------------------|---|
| Airbag Knees         | ✓ | Airbag Driver Front | ✓ |
| ABS                  | ✓ | Central Locking     | ✓ |
| Child Safety Locking | ✓ |                     |   |

#### **Comfort & Convenience**

|                                 |   |                             |   |
|---------------------------------|---|-----------------------------|---|
| Climate Control AC              | ✓ | Cruise Control              | ✓ |
| Memory Seats                    | ✓ | Rear Armrest with cupholder | ✓ |
| Steering Mounted Audio Controls | ✓ | Soft Door Close             | ✓ |
| Power Folding Mirrors           | ✓ | Power Tailgate/ Power Trunk | ✓ |
| Power Head Rest                 | ✓ | Rear Defogger               | ✓ |
| Central Armrest                 | ✓ | Automatic Headlights        | ✓ |
| Steering Column Adjuster        | ✓ |                             |   |

#### **Exteriors**

|                 |   |                     |   |
|-----------------|---|---------------------|---|
| Fog Light Front | ✓ | Roof Rails          | ✓ |
| Running Lights  | ✓ | Rear Bumper Spoiler | ✓ |
| LED Headlights  | ✓ |                     |   |

#### **Performance**

|              |   |                      |   |
|--------------|---|----------------------|---|
| Paddle Shift | ✓ | Hill Descent Control | ✓ |
|--------------|---|----------------------|---|

#### **Entertainment**

|                  |   |                     |   |
|------------------|---|---------------------|---|
| Bluetooth Player | ✓ | Infotainment System | ✓ |
| USB player       | ✓ |                     |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Handle: Paint Chip-off < 5mm

Rear left door



Rear right door



Panel: Low Visual Dent < 30mm, Paint Chip-off < 5mm

Fenders Condition

Left Fender



Right Fender



Condition: Paint Chip-off < 5mm

Right Fender: Paint Chip-off < 5mm

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Paint Chip-off < 5mm, Scratch < 50mm, Dent < 30mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood



Bonnet: Paint Chip-off < 5mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

|  |  |                             |  |
|--|--|-----------------------------|--|
| Left A Pillar                                  |  | Right A Pillar              |  |
| Left A to B Pillar Beading                     |  | Right A to B Pillar Beading |  |
| Right A to B Pillar                            |  | Left B Pillar               |  |
| Left B Pillar Trim                             |  | Left B to C Pillar Beading  |  |
| Right C Pillar Trim                            |  | Right B to C Pillar         |  |
| Right B to C Pillar Beading                    |  | Left C Pillar               |  |
| Running Board Condition                        |  |                             |  |
| Left Running Board                             |  | Right Running Board         |  |
| Sunroof Glass Condition (If Equipped)          |  |                             |  |
| Sun Roof Glass                                 |  |                             |  |
| Windshield Condition                           |  |                             |  |
| Front Windshield                               |  |                             |  |
| Beading: Mouldings Crack/ Fair Use Wear < 50mm |  | Rear Windshield             |  |
| Structural Assessment                          |  |                             |  |
| Chassis Condition                              |  | Radiator Support            |  |
| Apron  |  | Boot Floor                  |  |
| Firewall Condition                             |  | Cowl Top                    |  |
| Head Light Support Condition                   |  |                             |  |
| Cowl Top                                       |  |                             |  |
| Cowl Top                                       |  |                             |  |
| Rear View Mirror Condition                     |  |                             |  |
| Left Hand Side Mirror                          |  | Left Side Mirror            |  |
| Right Side Mirror                              |  |                             |  |
| Alloy Wheel/ Rim                               |  |                             |  |
| Left Front Alloy/ Rim                          |  | Left Rear Alloy/ Rim        |  |
| Right Front Alloy/ Rim                         |  | Right Rear Alloy/ Rim       |  |
| Spare Alloy/ Rim Condition                     |  |                             |  |
| Wheel cover                                    |  | Antenna                     |  |

|                  |   |          |   |
|------------------|---|----------|---|
| Grill Condition  | ✓ | Monogram | ✓ |
| Window Glass     | ✓ | Wiper    | ✓ |
| Panel Condition  |   |          |   |
| Rear Trunk Panel |   |          | ✓ |

---

## ⌚ Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Turbocharger/ Supercharger     | ✓ | Radiator Condition | ✓ |
| Radiator Coolant               | ✓ |                    |   |
| Battery                        |   |                    |   |
| Battery Terminal & Tightness   | ✓ |                    |   |
| Fuel System                    |   |                    |   |
| Fuel Tank                      | ✓ |                    |   |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Gear shift         | ✓ |
| Drive Axle                     | ✓ | Transmission Fluid | ✓ |

---

## ⌚ Steering, Suspension & Brakes

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Steering               |   |                       |   |
| Steering wheel         | ✓ |                       |   |
| Brake System           |   |                       |   |
| Parking Brake          | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid           | ✓ |
| Pedals                 | ✓ |                       |   |
| Suspension             |   |                       |   |
| Shock Absorbers        | ✓ |                       |   |

## Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)



### Door Locks

Child Safety Locking



### Dashboard

Instrument Panel



### Airbags

Airbags



### Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Radar (If Equipped)



Navigation System



Music System



### Sunroof Operation

Sunroof



### Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights



License Plate Light



### Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows



Memory Seats



## **Interiors & Luggage**

Dashboard And Instrument Panel



Central Console



Cup Holder



Glove Box



Steering Wheel



Steering Wheel Fair Use Wear

Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



## **Tyres**

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<85%

LHS Rear Tyre

<85%

RHS Front Tyre

<85%

RHS Rear Tyre

<85%

Spare Tyre

<65%



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE