



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2016 NISSAN TIIDA**

**S | 56,441 KM**

**VIN: MNTBC2C95G6011128**

## **Car highlights**



### **Great Parking Assistance**

Parking Sensors Front, Reverse Camera &  
more



### **Navigation**

Navigation to drive with ease & comfort



### **Bluetooth**

Enjoy your drive with bluetooth



### **Amazing Comfort**

Power driver seat

## Basic Details

 Kilometers	<b>56441</b>	 Specs	<b>Yes</b>
 Engine	<b>1.6L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>HATCHBACK</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Steel Wheels</b>	 Exterior Color	<b>Exterior Color Black</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>1 Keys</b>
 VIN number	<b>MNTBC2C95G6011128</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Navigation		Parking Sensors Front	
Parking Sensors Rear		Reverse Camera	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
 Comfort & Convenience			

Central Armrest



Steering Column Adjuster



### Entertainment

Bluetooth Player



Infotainment System



USB player



### Exteriors

Halogen Headlights



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Inner Handle: Color/Chrome Dullness

Rear left door



Front right door



Panel: Low Visibility Dent < 30mm, Light

Scuffing < 50mm, Paint Chip-off < 5mm

Rear right door



Handle: Scratch < 50mm, Paint Chip-off < 5mm

Fenders Condition

Left Fender



Condition: Light Scuffing < 50 mm, Paint Chip-off < 5mm

Right Fender



Condition: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Low Visual Dent < 30mm, Light Scuffing < 50mm, Chip < 5mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm, Chip < 8mm

Hood Condition

Hood

Bonnet: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Acid Marks/ Bird Dropping > 5mm



Trunk Condition

Trunk



Trunk condition

Trunk



## Roof Condition

Roof



## Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Right B to C Pillar Beading



Left C Pillar



## Running Board Condition

Left Running Board



Right Running Board



## Windshield Condition

Front Windshield

Condition: Driver Side/Stone Chip



Mark<5mm, Passenger Side/Stone Chip

Rear Windshield



Mark<8mm

## Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



minor imperfection

Cowl Top



## Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Body: minor imperfection

Alloy Wheel/ Rim



Spare Alloy/ Rim Condition



Wheel Arch

Wheel cover



Antenna	✓	Grill Condition Scuffing > 50mm	!
Monogram	✓	Window Glass	✓
Wiper	!	Operation: minor imperfection	
Panel Condition			
Rear Trunk Panel	✓		

---

## ⌚ Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

---

## ⌚ Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

## Electricals, Controls & Lights

### Keys

Master Key 

### Door Locks

Child Safety Locking 

### Dashboard

Instrument Panel 

### Airbags

Airbags 

### Controls

Fuel Door Release: minor imperfection 

Infotainment Display

Infotainment Display: Display Low Brightness 

Engine Sensors 

OBD Connector 

### Music System

Condition: minor imperfection 

Camera 

### Lights

#### Headlight

Left: Low Brightness lamps, Light Scuff Marks   
< 50mm

Interior Lights 

Tail Light Cluster 

License Plate Light 

### Air Conditioning

AC Cooling 

AC Switch 

AC System Leaks 

Center AC Vent  
minor imperfection 

Front Right AC Vent 

Heater 

Parking Sensors 

Rear Defogger  
Extensive Wear Of Strip 

USB Charging Port 

Power/ Manual Windows 

## Interiors & Luggage

Dashboard And Instrument Panel 

Central Console 

Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery Driver Seat: Minor Smudge/ Cracks	!	Manual Seat Movement	✓
Seat Belts Rear Left Seat: Smudge	!	Head Rest	✓
Door Controls And Trim Front Left Door: Light Scuffing/ Disfiguration	!	Grab Handle	✓
Carpet Front Right Floor Mat: minor imperfection	!	Headliner Front Left: Light Smudge/Disfiguration	!
Rear View Mirror	✓	Toolkit	✓

## Tyres

### Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

### Tyres Depth (Remaining)

LHS Front Tyre	<55%	LHS Rear Tyre	<65%
RHS Front Tyre	<45%	RHS Rear Tyre	<65%
Spare Tyre	<55%		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE