



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 MITSUBISHI ASX

GLX MID | 115,969 KM

VIN: JE4LP21U3HZ701148

## Car highlights



### Cruise control

Cruise control to drive with ease & comfort



### Great Parking Assistance

Reverse Camera, Parking Sensors Rear



### Bluetooth

Enjoy your drive with bluetooth



### Amazing Comfort

Power driver seat

## Basic Details

|  |                          |   |                           |
|--|--------------------------|---|---------------------------|
|  Kilometers       | <b>115969</b>            |  Specs             | <b>Yes</b>                |
|  Engine           | <b>2.0L</b>              |  Option Type       | <b>Semi Loaded</b>        |
|  Transmission     | <b>Automatic</b>         |  Drive             | <b>Front Wheel Drive</b>  |
|  Body Type        | <b>SUV</b>               |  Fuel              | <b>Petrol</b>             |
|  Wheel Type       | <b>Alloy Wheels</b>      |  Exterior Color    | <b>Exterior Color Red</b> |
|  Interior Trim    | <b>Fabric Trim</b>       |  Number of Airbags | <b>2 Airbags</b>          |
|  Seating Capacity | <b>5 Seats</b>           |  Number of keys    | <b>2 Keys</b>             |
|  VIN number      | <b>JE4LP21U3HZ701148</b> |   |                           |

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  |   |
|--|---|
|  <b>Comfort &amp; Convenience</b> |   |
| Climate Control AC   |    |
| Rear Armrest with cupholder  |    |
| Rear Defogger  |    |
|  <b>Exteriors</b>                 |   |
| Fog Light Front  |    |
|  |  |
| Roof Rails   |  |

|                              |   |                     |   |
|------------------------------|---|---------------------|---|
| Running Lights               |   | Rear Bumper Spoiler |   |
| Halogen Headlights           |  |                     |   |
| <b>Safety &amp; Security</b> |   |                     |   |
| Parking Sensors Rear         |  | Reverse Camera      |  |
| Traction Control             |  | Airbag Driver Front |  |
| ABS                          |  | Central Locking     |  |
| Child Safety Locking         |  |                     |   |
| <b>Entertainment</b>         |   |                     |   |
| Bluetooth Player             |  | Infotainment System |  |
| USB player                   |  |                     |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Frame: Light Scuffing < 50mm

Rear left door



Rear right door



Handle: Paint Chip-off < 5mm

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm

Fenders Condition

Left Fender



Right Fender



Condition: Paint Chip-off < 5mm

Condition: Light Scuffing < 50mm

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Dent < 30mm

Condition: Low Visual Dent < 30mm, Light Scuffing < 50mm

Front Bumper Condition

Front Bumper



Front Bumper Condition

Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood



Bonnet: Low Visibility Dent < 30mm

Trunk Condition

Trunk



Trunk condition

Trunk



Roof Condition

Roof



Pillars Condition

|                               |   |   |   |
|-------------------------------|---|---|---|
| Left A Pillar                 | ✓ | Right A Pillar                                | ✓ |
| Left A to B Pillar Beading    | ✓ | Right A to B Pillar Beading                   | ✓ |
| Right A to B Pillar           | ✓ | Left B Pillar                                 | ✓ |
| Left B Pillar Trim            | ✓ | Left B to C Pillar Beading                    | ✓ |
| Right C Pillar Trim           | ✓ | Right B to C Pillar                           | ✓ |
| Right B to C Pillar Beading   | ✓ | Left C Pillar                                 | ! |
|                               |   | Dent < 30mm                                   |   |
| Running Board Condition       |   |   |   |
| Left Running Board            | ✓ | Right Running Board                           |   |
|                               |   | Front Right Sill Trim: Low Visual Dent < 50mm | ! |
| Windshield Condition          |   |   |   |
| Front Windshield              | ✓ | Rear Windshield                               | ✓ |
| Structural Assessment         |   |   |   |
| Chassis Condition             | ✓ | Radiator Support                              | ✓ |
| Apron                         | ✓ | Boot Floor                                    | ✓ |
| Cowl Top                      | ✓ | Head Light Support Condition                  | ✓ |
| Cowl Top                      |   |   |   |
| Cowl Top                      | ✓ |   |   |
| Rear View Mirror Condition    |   |   |   |
| Left Hand Side Mirror         | ✓ | Left Side Mirror                              | ✓ |
| Right Side Mirror             | ✓ | Right Hand Side Mirror                        | ✓ |
| Alloy Wheel/ Rim              |   |   |   |
| Left Front Alloy/ Rim         | ✓ | Left Rear Alloy/ Rim                          | ✓ |
| Right Front Alloy/ Rim        | ! | Right Rear Alloy/ Rim                         | ✓ |
| Rim: Alloy Edge/ Scuff < 80mm |   |   |   |
| Spare Alloy/ Rim Condition    | ✓ |   |   |
| Wheel Arch                    | ✓ | Wheel cover                                   | ✓ |
| Antenna                       | ✓ | Grill Condition                               | ! |
|                               |   | Light Scuffing < 50mm                         |   |

|                      |   |              |   |
|----------------------|---|--------------|---|
| Monogram             | ✓ | Window Glass | ✓ |
| Wiper                | ✓ |              |   |
| Panel Condition      |   |              |   |
| Rear Trunk Panel     | ! |              |   |
| Paint Chip Off < 5mm |   |              |   |

---

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Radiator Condition             | ✓ | Radiator Coolant   | ✓ |
| Battery                        |   |                    |   |
| Battery Terminal & Tightness   | ✓ |                    |   |
| Fuel System                    |   |                    |   |
| Fuel Cap                       | ✓ | Fuel Tank          | ✓ |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |
| Transmission Fluid             | ✓ |                    |   |

---

## Steering, Suspension & Brakes

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Steering               |   |                       |   |
| Steering wheel         | ✓ |                       |   |
| Brake System           |   |                       |   |
| Parking Brake          | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid           | ✓ |
| Pedals                 | ✓ |                       |   |
| Suspension             |   |                       |   |
| Shock Absorbers        | ✓ |                       |   |

---

## Electricals, Controls & Lights

## Keys

|            |  |              |  |
|------------|--|--------------|--|
| Master Key |  | Spare Key(s) |  |
|------------|--|--------------|--|

## Door Locks

|                      |  |
|----------------------|--|
| Child Safety Locking |  |
|----------------------|--|

## Dashboard

|                  |  |
|------------------|--|
| Instrument Panel |  |
|------------------|--|

## Airbags

|         |  |
|---------|--|
| Airbags |  |
|---------|--|

|          |  |                |  |
|----------|--|----------------|--|
| Controls |  | Cruise Control |  |
|----------|--|----------------|--|

|                      |  |                |  |
|----------------------|--|----------------|--|
| Infotainment Display |  | Engine Sensors |  |
|----------------------|--|----------------|--|

|               |  |              |  |
|---------------|--|--------------|--|
| OBD Connector |  | Music System |  |
|---------------|--|--------------|--|

|        |  |
|--------|--|
| Camera |  |
|--------|--|

## Lights

|           |  |                 |  |
|-----------|--|-----------------|--|
| Headlight |  | Interior Lights |  |
|-----------|--|-----------------|--|

|                    |  |                         |  |
|--------------------|--|-------------------------|--|
| Tail Light Cluster |  | Daylight Running Lights |  |
|--------------------|--|-------------------------|--|

|                     |  |            |  |
|---------------------|--|------------|--|
| License Plate Light |  | Fog Lights |  |
|---------------------|--|------------|--|

## Air Conditioning

|            |  |           |  |
|------------|--|-----------|--|
| AC Cooling |  | AC Switch |  |
|------------|--|-----------|--|

|                 |  |                |  |
|-----------------|--|----------------|--|
| AC System Leaks |  | Center AC Vent |  |
|-----------------|--|----------------|--|

|                     |  |        |  |
|---------------------|--|--------|--|
| Front Right AC Vent |  | Heater |  |
|---------------------|--|--------|--|

|               |  |                   |  |
|---------------|--|-------------------|--|
| Rear Defogger |  | USB Charging Port |  |
|---------------|--|-------------------|--|

|                       |  |
|-----------------------|--|
| Power/ Manual Windows |  |
|-----------------------|--|

## Interiors & Luggage

|                                |  |                 |  |
|--------------------------------|--|-----------------|--|
| Dashboard And Instrument Panel |  | Central Console |  |
|--------------------------------|--|-----------------|--|

|            |  |           |  |
|------------|--|-----------|--|
| Cup Holder |  | Glove Box |  |
|------------|--|-----------|--|

|                                     |  |                      |  |
|-------------------------------------|--|----------------------|--|
| Steering Wheel                      |  | Sunvisor             |  |
| Seat Upholstery                     |  | Manual Seat Movement |  |
| Passenger Seat: Minor Smudge/Cracks |  |                      |  |
| Seat Belts                          |  | Head Rest            |  |
| Door Controls And Trim              |  | Grab Handle          |  |
| Carpet                              |  | Headliner            |  |
| Rear View Mirror                    |  | Toolkit              |  |

## Tyres

### Tyres Condition

|                            |  |                           |  |
|----------------------------|--|---------------------------|--|
| Left Hand Side Front Tyre  |  | Left Hand Side Rear Tyre  |  |
| Right Hand Side Front Tyre |  | Right Hand Side Rear Tyre |  |
| Spare Tyre                 |  |                           |  |

### Tyres Depth (Remaining)

|                |      |               |      |
|----------------|------|---------------|------|
| LHS Front Tyre | <55% | LHS Rear Tyre | <65% |
| RHS Front Tyre | <45% | RHS Rear Tyre | <55% |
| Spare Tyre     | <65% |               |      |



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE