



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2015 TOYOTA YARIS

SE / E | 101,349 KM

VIN: MHFBT9F36F6039353

Car highlights



Music System

Enjoy your drive with music system



Amazing Comfort

Power driver seat



Airbag safety

Airbag Driver Front



Central Arm Rest

Central arm rest for extra comfort

Basic Details

 Kilometers	101349	 Specs	Yes
 Engine	1.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Brown
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	3 Keys
 VIN number	MHFBT9F36F6039353		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Rear Defogger	
 Exteriors	
Halogen Headlights	
 Safety & Security	
Airbag Driver Front	
ABS	

Central Locking



Child Safety Locking



Entertainment

Infotainment System



USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door

Handle: Scratch < 50mm, Paint Chip-off < 5mm



Front right door

Handle: Paint Chip-off < 5mm



Rear left door

Handle: Paint Chip-off < 5mm



Rear right door

Handle: Paint Chip-off < 5mm



Fenders Condition

Left Fender



Right Fender

Right Fender: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm



Quarter Panels Condition

Left Quarter Panel

Condition: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm, Acid Marks/ Bird Dropping < 5mm



Right Quarter Panel

Condition: Dent < 30mm, Scratch < 50mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Crack/ Misaligned

Hood Condition

Hood

Bonnet: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof

Roof Moulding Condition: Minor Rubber



Beading Fair Use Wear

Pillars Condition

Left A Pillar



Right A Pillar



Inner Condition: Light Scuffing

Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Low Visual Dent < 30mm

Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Right B to C Pillar Beading



Left C Pillar



Running Board Condition

Left Running Board



Right Running Board



Front Left Sill Trim: Scratch < 80mm

Condition: Light Scuffing < 80mm

Windshield Condition

Front Windshield

Condition: Driver Side/Stone Chip



Rear Windshield



Mark<5mm, Passenger Side/Stone Chip

Mark<8mm

Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Body: Scratch < 50mm

Right Hand Side Mirror



Alloy Wheel/ Rim



Spare Alloy/ Rim Condition

Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition	✓
Monogram	✓	Window Glass	!
		Rear Left: Scratch < 50mm	
Wiper	✓		
Panel Condition			
Rear Trunk Panel	!		
Scratch < 50mm			

⌚ Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

⌚ Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		

Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Infotainment Display



Engine Sensors



OBD Connector



Music System



Lights

Headlight



Left: Light Scuff Marks < 50mm

Interior Lights



Tail Light Cluster



Right Tail Lamp: Light Scuffing < 50mm

License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder



Glove Box



Glove Box: Minor Scuffing/Crack/Fair Use

Wear, Glove Box Retainer Faulty

	Sunvisor	
Steering Wheel		Left: Sunvisor RHS Minor Crack/Damage, Sunvisor LHS Minor Disfiguration 
Seat Upholstery		Manual Seat Movement 
Seat Belts		Head Rest 
Door Controls And Trim		Grab Handle 
Carpet		Headliner
Front Passenger Floor Carpet: Smudge/Burn/Crack/Fair Use Wear		Front Left: Light Smudge/Disfiguration, Light Scuffing 
Rear View Mirror		Toolkit 

Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			

Tyres Depth (Remaining)

LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE