



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2017 HONDA CIVIC**

**DX PLUS | 114,831 KM**

VIN: NLAFC5652HW015681

## **Car highlights**



### **Cruise control**

Cruise control to drive with ease & comfort



### **Great Parking Assistance**

Parking Sensors Rear



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**










Power driver seat



Basic Details

 Kilometers	114831	 Specs	Yes
 Engine	1.6L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	NLAFC5652HW015681		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	
Remote Engine Start			
 <b>Exteriors</b>			

Fog Light Front	✓	Running Lights	✓
Halogen Headlights	✓		
 <b>Safety &amp; Security</b>			
Parking Sensors Rear	✓	Traction Control	✓
Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓
 <b>Entertainment</b>			
Bluetooth Player	✓	USB Charging Port	✓
Infotainment System	✓	USB player	✓

# 150 Point Detailed Inspection Report


We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality


Passed 

## Exterior

### Doors condition

Front left door 

Front right door  
Panel: Low Visibility Dent < 30mm, Paint Chip-off < 5mm, Light Scuffing < 50mm 

Rear left door  
Panel: Scratch < 50mm, Paint Chip-off < 5mm 


Rear right door  
Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm, Low Visual Dent < 30mm 


### Fenders Condition

Left Fender  
Condition: Paint Chip-off < 5mm 

Right Fender  
Right Fender: Dent < 30mm, Paint Chip-off < 5mm 

### Quarter Panels Condition

Left Quarter Panel  
Condition: Dent < 30mm 

Right Quarter Panel  
Condition: Dent < 30mm, Paint Chip-off < 5mm, Scratch < 50mm, Dent > 30mm 


### Front Bumper Condition

Front Bumper 

### Rear Bumper Condition

Rear Bumper  
Rear Bumper: Dent < 50mm, Light Scuffing < 80mm, Chip< 8mm, Crack/ Misaligned 

### Hood Condition

Hood  
Bonnet: Low Visibility Dent < 30mm, Paint Chip-off < 5mm 

### Trunk Condition

Trunk 

### Trunk conditon

Trunk 

## Roof Condition

Roof



## Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar  
Light Scuffing < 80mm



Right B to C Pillar Beading



Left C Pillar



## Running Board Condition

Left Running Board

Condition: Scratch < 80mm



Right Running Board

Condition: Light Scuffing < 80mm



## Windshield Condition

Front Windshield

Condition: Driver Side/Stone Chip  
Mark<5mm, Passenger Side/Stone Chip  
Mark<8mm



Rear Windshield



## Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



## Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror

Body: Scratch < 50mm



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim

Rim: Alloy Face/ Scuff < 50mm



Left Rear Alloy/ Rim

Rim: Alloy Edge/ Scuff < 80mm



Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim Rim: Alloy Face/ Scuff < 50mm	!
Spare Alloy/ Rim Condition	✓		
Grill Condition Light Scuffing < 50mm	!	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel Scratch < 50mm	!		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Lights

Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows







## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	!	Sunvisor	✓
Steering Wheel Fair Use Wear			
Seat Upholstery	!	Manual Seat Movement	✓
Driver Seat: Minor Smudge/ Cracks			
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	!	Headliner	✓
Front Left Floor Mat: Smudge/Burn/Crack			
Rear View Mirror	✓	Toolkit	✓



## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<75%		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE