



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 MITSUBISHI PAJERO

GLS TOP | 132,360 KM

VIN: JE4MR62M9JJ708498

Car highlights



Four wheel drive

This car has a Four wheel drive



Cruise control

Cruise control to drive with ease & comfort



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	132360	 Specs	Yes
 Engine	3.0L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	JE4MR62M9JJ708498		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Climate Control AC	
Rear Armrest with cupholder	
Power Folding Mirrors	
Central Armrest	
 Exteriors	

Fog Light Front		Roof Rails	
Running Lights		Rear Bumper Spoiler	
HID Headlights			



Safety & Security

Parking Sensors Rear		Reverse Camera	
Traction Control		Airbag Curtain Shield	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	



Performance

Differential Locks		
--------------------	---	--



Entertainment

Bluetooth Player		Infotainment System	
USB player			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door



Moulding: Low Visual Dent < 30mm

Rear left door



Rear right door



Moulding: Light Scuffing < 50mm

Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Trim: Light Scuffing < 80mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood

Bonnet: Acid Marks/ Bird Dropping < 5mm,



Light Scuffing < 50mm

Trunk Condition

Trunk



Door Trim: Light Scuffing < 50mm

Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	
Running Board Condition			
Left Running Board		Right Running Board	
		Right Foot Board: Light Scuffing < 80mm	
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass			
Windshield Condition			
Front Windshield		Rear Windshield	
Structural Assessment			
Chassis Condition		Apron	
Boot Floor		Firewall Condition	
Cowl Top		Head Light Support Condition	
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror			
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Spare Alloy/ Rim Condition			
Grill Condition			
Broken/ Fair Use Wear		Monogram	
Window Glass		Wiper	

Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



4*4 Condition (If Applicable)



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Remote Functions Not Responding

Door Locks

Child Safety Locking



Dashboard

Instrument Panel		
Airbags		
Airbags		
Controls		Cruise Control
Infotainment Display		OBD Connector
Music System		
Sunroof Operation		
Sunroof		
Camera		
Lights		
Headlight		Interior Lights
Tail Light Cluster		Daylight Running Lights
License Plate Light		Fog Lights
Air Conditioning		
AC Cooling		AC Switch
AC System Leaks		Center AC Vent
Front Right AC Vent		Heater
Rear Blower Switch		Rear Left AC Vent
Rear Defogger		USB Charging Port
Power/ Manual Windows		

Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Crack/ Fair Use Wear

Cup Holder

Steering Wheel

Central Console

Gear Shift Knob: Knob Fair Use Wear

Glove Box

Sunvisor

Seat Upholstery

Driver Seat: Minor Smudge/ Cracks, Minor
Leather/ Fabric Fair Use Wear/ Tears



Manual Seat Movement



Seat Belts



Head Rest

**Door Controls And Trim**

Front Left Door: Light Scuffing, Light Scuffing/
Disfiguration



Grab Handle



Carpet



Front Left Floor Mat: Smudge/Burn/Crack

Headliner



Front Left: Light Smudge/Disfiguration, Light
Scuffing

Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre

**Tyres Depth (Remaining)**

LHS Front Tyre

<95%

LHS Rear Tyre

<90%

RHS Front Tyre

<95%

RHS Rear Tyre

<95%

Spare Tyre

<75%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE