



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 INFINITI QX50

LUXE | 137,762 KM

VIN: 3PCAJ5M12KF135132

Car highlights



Supercharger/turbocharger

This car has a Supercharger/turbocharger



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat

Basic Details

 Kilometers	137762	 Specs	Yes
 Engine	2.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	3PCAJ5M12KF135132		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Power Folding Mirrors		Power Tailgate/ Power Trunk	
Rear Defogger		Central Armrest	
Automatic Headlights			



Safety & Security

Navigation



Parking Sensors Front



Parking Sensors Rear



Reverse Camera



Traction Control



Airbag Curtain Shield



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Performance

Paddle Shift



Exteriors

Running Lights



Rear Bumper Spoiler



HID Headlights



Entertainment

Bluetooth Player



USB Charging Port



Infotainment System



USB player







150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
		Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm	
Rear left door		Rear right door	
Panel: Scratch < 50mm		Panel: Paint Chip-off < 5mm	

Fenders Condition

Left Fender		Right Fender	
		Right Fender: Paint Chip-off < 5mm	

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Scratch < 50mm		Condition: Dent < 30mm, Scratch < 50mm	

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm	

Hood Condition

Hood	
Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm	

Trunk Condition

Trunk	
-------	---

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board Condition: Scratch < 80mm	!	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror Body: Scratch < 50mm	!	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm	!	Left Rear Alloy/ Rim Rim: Alloy Edge/ Scuff < 80mm	!
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓

Wiper	✓
Panel Condition	
Rear Trunk Panel	✓

Engine & Transmission

Engine		
Engine Body	✓	Engine Performance ✓
Engine Oil (Condition & Level)	✓	Exhaust System ✓
Turbocharger/ Supercharger	✓	Radiator Condition ✓
Radiator Coolant	✓	
Battery		
Battery Terminal & Tightness	✓	
Fuel System		
Fuel Cap	✓	Fuel Tank ✓
Transmission Operation		
Gear Shifting	✓	Gear shift ✓
Drive Axle	✓	Transmission Fluid ✓

Steering, Suspension & Brakes

Steering		
Steering wheel	✓	
Brake System		
Parking Brake	✓	Brake Master Cylinder ✓
Brake Disc & Brake Pad	✓	Brake Fluid ✓
Pedals	✓	
Suspension		
Shock Absorbers	✓	

Electricals, Controls & Lights

Keys

Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Navigation System	✓
Music System	✓	Camera	✓
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Turn Signal Lights Left ORVM: Light Scuffing < 50mm	!
Daylight Running Lights	✓	License Plate Light	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Box: Minor Color Low Brightness	!
--------------------------------	---	--	---

Cup Holder	✓	Glove Box	✓
Steering Wheel	!	Sunvisor	✓
Color Faded			
Seat Upholstery			
Driver Seat: Minor Leather/ Fabric Fair Use	!	Manual Seat Movement	✓
Wear/ Tears, Minor Fair Wear/Fade off			
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	!	Grab Handle	✓
Front Left Door: Light Scuffing/ Disfiguration			
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	No spare		
	tyre		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE