



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 MITSUBISHI ECLIPSE CROSS

GLX HIGHLINE | 72,972 KM

Car highlights



Panoramic Roof

This car has a panoramic roof



Supercharger/turbocharger

This car has a Supercharger/turbocharger



Amazing Comfort
















Power driver seat



Tilt Steering wheel









Tilt steering wheel for extra comfort








Basic Details

 Kilometers	72972	 Specs	Yes
 Engine	1.5L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Number of Airbags	7 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	JE4LS5142JZ702829		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

<div> Comfort & Convenience</div>				
Panoramic Sunroof		<div></div>	Cruise Control	<div></div>
Steering Mounted Audio Controls		<div></div>	Heads up Display	<div></div>
<div><div></div> Exteriors</div>				
Fog Light Front		<div></div>		
<div><div></div> Safety & Security</div>				

Parking Sensors Front 	Navigation 
Parking Sensors Rear 	Reverse Camera 
 Entertainment	
USB Charging Port 	Infotainment System 

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition



Front left door		Front right door	
		Handle: Paint Chip-off < 5mm	

Rear left door		Rear right door	
		Handle: Paint Chip-off < 5mm	

Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---


Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
		Glass: Beading Fair Use Wear/Disfiguration > 100mm	

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm, Chip< 8mm	

Hood Condition

Hood	
------	---

Trunk Condition

Trunk	
-------	---

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
Roof Moulding Condition: Colour fade	

Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓

Grill Condition	⚠	Monogram	✓
Light Scuffing < 50mm			
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

🔧 Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Gear shift	✓
Drive Axle	✓	Transmission Fluid	✓

🚗 Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		



Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Heads Up Display



Infotainment Display



Engine Sensors



OBD Connector



Radar (If Equipped)



Navigation System



Music System



Sunroof Operation

Sunroof



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Defogger



USB Charging Port



Not Working

Power/ Manual Windows



Seat Heaters



Interiors & Luggage

Dashboard And Instrument Panel



Central Console

Gear Shift Knob: Knob Fair Use Wear



Cup Holder



Glove Box



Steering Wheel



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<75%

LHS Rear Tyre

<85%

RHS Front Tyre

<75%

RHS Rear Tyre

<85%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE