



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2020 KIA PICANTO

LX | 73,585 KM

VIN: KNAB25123LT575242

Car highlights



Bluetooth

Enjoy your drive with bluetooth



Music System

Enjoy your drive with music system



Amazing Comfort

Power driver seat



Airbag safety

Airbag Driver Front

Basic Details

 Kilometers	73585	 Specs	Yes
 Engine	1.3L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	HATCHBACK	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	KNAB25123LT575242		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security				
Traction Control			Airbag Driver Front	
ABS			Central Locking	
Child Safety Locking				
 Comfort & Convenience				
Steering Mounted Audio Controls			Rear Defogger	

Steering Column Adjuster	✓	
 Entertainment		
Bluetooth Player	✓	Infotainment System ✓
USB player	✓	
 Exteriors		
Halogen Headlights	✓	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door



Front right door

Panel: Light Scuffing < 50mm, Low Visibility
Dent < 30mm



Rear left door



Rear right door

Panel: Light Scuffing < 50mm



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover Front Right: Edge/ Scuffs < 80mm	!
Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Infotainment Display	✓
Engine Sensors	✓	OBD Connector	✓
Music System	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	License Plate Light	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
USB Charging Port	✓	Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery Rear Left Seat: Minor Smudge/ Crack	⚠	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner Front Left: Light Smudge/Disfiguration, Light Scuffing	⚠

Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<75%

RHS Front Tyre

<65%

RHS Rear Tyre

<75%

Spare Tyre

<45%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE