



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2015 PORSCHE CAYENNE

S | 142,721 KM

VIN: WP1ZZZ92ZFLA58954

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort












Power driver seat

Basic Details

 Kilometers	142721	 Specs	Yes
 Engine	3.6L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	WP1ZZZ92ZFLA58954		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Climate Control AC		Cruise Control	
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Soft Door Close		Power Folding Mirrors	
Power Tailgate/ Power Trunk		Central Armrest	
Automatic Headlights		Steering Column Adjuster	



Exteriors

Fog Light Front



Running Lights



Rear Bumper Spoiler



LED Headlights



Safety & Security

Navigation



Parking Sensors Front



Parking Sensors Rear



Reverse Camera



Blind Spot Monitor



Traction Control



Airbag Curtain Shield



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Performance

Paddle Shift



Hill Descent Control



Differential Locks



Entertainment

Bluetooth Player



Infotainment System



USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
		Handle: Paint Chip-off < 5mm	

Rear left door		Rear right door	
		Handle: Scratch < 50mm	

Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---


Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	---	---------------------	---

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm	

Hood Condition

Hood	
------	---

Trunk Condition

Trunk	
-------	---

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading		Right A to B Pillar Beading	
----------------------------	---	-----------------------------	---

Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Antenna	✓	Grill Condition	✓
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Gear shift



Drive Axle



4*4 Condition (If Applicable)



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key

Button Faded



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Heads Up Display	✓	Infotainment Display	✓
OBD Connector	✓	Radar (If Equipped)	✓
Navigation System	✓	Music System	✓
Sunroof Operation			
Sunroof	✓		
Lights			
Headlight		Interior Lights	✓
Left Washer: Washer Cover/ Nozzle Missing	!		
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	✓	Fog Lights	!
		Right Fog Light: Light Scuff Marks < 50mm	
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	!	Heater	✓
Adjuster Clip Crack/Fair Use Wear			
Rear Left AC Vent	✓		
Parking Sensors	✓	Rear Defogger	!
		Not Working	
USB Charging Port	✓	Power/ Manual Windows	✓



Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓

Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<55%	LHS Rear Tyre	<45%
RHS Front Tyre	<55%	RHS Rear Tyre	<45%
Spare Tyre	<45%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE