



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2020 TOYOTA RAV4

ADVENTURE | 71,032 KM

VIN: JTMJ13FV9LJ032689

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort












Power driver seat

Basic Details

| | | | |
|--|-------------------|---|--------------------|
|  Kilometers | 71032 |  Specs | Yes |
|  Engine | 2.5L |  Option Type | Semi Loaded |
|  Transmission | Automatic |  Drive | Four Wheel Drive |
|  Body Type | SUV |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Red |
|  Interior Trim | Leather Trim |  Number of Airbags | 9 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | JTMJ13FV9LJ032689 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|---------------------------------|---|
|  Comfort & Convenience | | | |
| Climate Control AC |  | Cruise Control |  |
| Rear Armrest with cupholder |  | Steering Mounted Audio Controls |  |
| Power Folding Mirrors |  | Power Tailgate/ Power Trunk |  |
| Rear Defogger |  | Central Armrest |  |
| Automatic Headlights |  | Steering Column Adjuster |  |



Exteriors

Fog Light Front



Roof Rails



Running Lights



LED Headlights



Safety & Security

Navigation



Parking Sensors Front



Parking Sensors Rear



Reverse Camera



Traction Control



Airbag Curtain Shield



Airbag Knees



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



Performance

Hill Descent Control



Entertainment

Bluetooth Player



Infotainment System



USB player



150 Point Detailed Inspection Report

We’re quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

| | | | |
|-----------------|---|--|---|
| Front left door |  | Front right door |  |
| | | Panel: Paint Chip-off < 5mm, Light Scuffing < 50mm | |

| | | | |
|----------------|---|--|---|
| Rear left door |  | Rear right door |  |
| | | Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm | |

Fenders Condition

| | | | |
|---------------------------------|---|--------------|---|
| Left Fender |  | Right Fender |  |
| Condition: Paint Chip-off < 5mm | | | |


Quarter Panels Condition

| | | | |
|---------------------------|---|---------------------|---|
| Left Quarter Panel |  | Right Quarter Panel |  |
| Trim: Light Scuffing<80mm | | | |


Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|

Rear Bumper Condition

| | |
|---|---|
| Rear Bumper |  |
| Rear Bumper: Light Scuffing < 80mm, Chip< 8mm | |

Hood Condition

| | |
|--|---|
| Hood |  |
| Bonnet: Acid Marks/ Bird Dropping < 5mm, Light Scuffing < 50mm | |

Trunk Condition

| | |
|----------------------------------|---|
| Trunk |  |
| Door Trim: Light Scuffing < 50mm | |

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

| | | | |
|---------------------------------------|---|-----------------------------|---|
| Roof | ✓ | | |
| Pillars Condition | | | |
| Left A Pillar | ✓ | Right A Pillar | ✓ |
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Sunroof Glass Condition (If Equipped) | | | |
| Sun Roof Glass | ✓ | | |
| Windshield Condition | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Radiator Support | ✓ |
| Apron | ✓ | Boot Floor | ✓ |
| Firewall Condition | ✓ | Cowl Top | ✓ |
| Head Light Support Condition | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ! | Right Rear Alloy/ Rim | ✓ |
| Rim: Alloy Edge/ Scuff < 80mm | | | |
| Spare Alloy/ Rim Condition | ✓ | | |

| | | | |
|------------------|---|--|---|
| Antenna | ✓ | Grill Condition Light Scuffing < 50mm | ⚠ |
| Monogram | ✓ | Window Glass | ✓ |
| Wiper | ✓ | | |
| Panel Condition | | | |
| Rear Trunk Panel | ✓ | | |

🔧 Engine & Transmission

| | | | |
|--------------------------------|---|--------------------|---|
| Engine | | | |
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Radiator Condition | ✓ | Radiator Coolant | ✓ |
| Battery | | | |
| Battery Terminal & Tightness | ✓ | | |
| Fuel System | | | |
| Fuel Tank | ✓ | | |
| Transmission Operation | | | |
| Gear Shifting | ✓ | Drive Axle | ✓ |
| 4*4 Condition (If Applicable) | ✓ | Transmission Fluid | ✓ |

🚗 Steering, Suspension & Brakes

| | | | |
|------------------------|---|-----------------------|---|
| Steering | | | |
| Steering wheel | ✓ | | |
| Brake System | | | |
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |
| Pedals | ✓ | | |
| Suspension | | | |
| Shock Absorbers | ✓ | | |



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Navigation System



Music System



Sunroof Operation

Sunroof



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Fair Use Wear

Rear Blower Switch



Rear Defogger



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console

Cigarette Lighter: Cigarette Lighter Missing



Cup Holder



Glove Box



Steering Wheel



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet

Front Left Floor Mat: Smudge/Burn/Crack



Headliner

Rear Left: Smudge/Disfiguration



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre
minor imperfection



Right Hand Side Front Tyre
minor imperfection



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<55%

LHS Rear Tyre

<75%

RHS Front Tyre

<55%

RHS Rear Tyre

<75%

Spare Tyre

<40%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE