



### RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

### 1 Months Warranty

Enjoy peace of mind for your car purchase

### Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





**2016 MITSUBISHI LANCER EX**

**GLX | 208,073 KM**

VIN: JMYSTCY4AGU730006

## **Car highlights**



### **Great Parking Assistance**

Reverse Camera, Parking Sensors Rear



### **Running Lights**

This car has a Running lights



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**

Power driver seat

Basic Details

 Kilometers	208073	 Specs	Yes
 Engine	2.0L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	JMYSTCY4AGU730006		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

<div> Exteriors</div>				
Fog Light Front		<div></div>	Running Lights	<div></div>
Rear Bumper Spoiler		<div></div>	Halogen Headlights	<div></div>
<div> Comfort &amp; Convenience</div>				
Rear Armrest with cupholder		<div></div>	Rear Defogger	<div></div>
Central Armrest		<div></div>	Steering Column Adjuster	<div></div>



## Safety & Security

Parking Sensors Rear



Reverse Camera



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



## Entertainment

Bluetooth Player



Infotainment System



USB player



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door	
		Handle: Paint Chip-off < 5mm	

Rear left door		Rear right door	
		Panel: Scuffing > 50mm, Low Visual Dent < 30mm, Paint Chip-off < 5mm	

### Fenders Condition

Left Fender		Right Fender	
Condition: Light Scuffing < 50 mm, Paint Chip-off < 5mm		Condition: Light Scuffing < 50mm, Paint Chip-off < 5mm	

### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Dent		Condition: Low Visual Dent < 30mm, Light Scuffing<50mm, Chip<5mm	


### Front Bumper Condition

Front Bumper	
Condition: minor imperfection	

### Rear Bumper Condition

Rear Bumper	
Rear Bumper: Crack/ Misaligned, Dent < 50mm, Light Scuffing < 80mm, Chip< 8mm	

### Hood Condition

Hood	
Bonnet: Paint Damage/ Low Brightness, Low Visibility Dent < 30mm, Paint Chip-off < 5mm	

### Trunk Condition

Trunk	
-------	---

### Trunk conditon

Trunk	
-------	---

### Roof Condition

Roof	✓		
Pillars Condition			
Left A Pillar			
Inner Condition: Fair Use Wear	!	Right A Pillar	✓
Left A to B Pillar Beading			
Beading Crack/ Tear > 5mm	!	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board			
Front Left Sill Trim: Scuffing > 100mm	!	Right Running Board	✓
Windshield Condition			
Front Windshield			
Condition: Driver Side/Stone Chip			
Mark<5mm, Passenger Side/Stone Chip	!	Rear Windshield	✓
Mark<8mm			
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim			
Rim: Alloy Edge/ Scuff < 80mm	!	Left Rear Alloy/ Rim	!
		Rim: Alloy Edge/ Scuff < 80mm	
Right Front Alloy/ Rim			
Rim: Alloy Edge/ Scuff < 80mm, Alloy Face/	!	Right Rear Alloy/ Rim	✓


Scuff < 50mm			
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna minor imperfection	!	Grill Condition Scuffing > 50mm	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓

Pedals	✓		
Suspension			
Shock Absorbers	✓		
<hr/>			
<div>  <b>Electricals, Controls &amp; Lights</b> </div>			
Keys			
Master Key			
Button Faded	!		
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Infotainment Display Infotainment Display: Display Low Brightness	!
Engine Sensors	✓	OBD Connector	✓
Music System	✓	Camera	✓
Lights			
Headlight			
Left: Light Scuff Marks < 50mm	!	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	✓	Fog Lights	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent			
Crack/Fair Use Wear	!	Heater	✓
Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Power/ Manual Windows	✓





## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Box: Minor Crack/Fair Use Wear/ Scuffing	!
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery Driver Seat: Minor Smudge/ Cracks	!	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Front Right Door: Light Scuffing	!	Grab Handle	✓
Carpet Front Left Floor Mat: Smudge/Burn/Crack	!	Headliner Front Left: Light Smudge/Disfiguration, Light Scuffing	!
Rear View Mirror	✓	Toolkit	✓



## Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<85%	LHS Rear Tyre	<45%
RHS Front Tyre	<55%	RHS Rear Tyre	<45%
Spare Tyre	<55%		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE