



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 BMW X4

XDRIVE 35I M SPORT | 109,609 KM

VIN: WBAXW5107G0N51901

Car highlights

Service History

Service history available



Cruise control

Cruise control to drive with ease & comfort



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat, Memory Seats

Basic Details

 Kilometers	109609	 Specs	Yes
 Engine	3.0L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	WBAXW5107G0N51901		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Heads up Display	
Cruise Control	
Rear Armrest with cupholder	
Power Folding Mirrors	
Rear Defogger	
Climate Control AC	
Memory Seats	
Steering Mounted Audio Controls	
Power Tailgate/ Power Trunk	
Central Armrest	

Automatic Headlights 



Safety & Security

360 degree Camera 	Lane Departure Warning System 
Navigation 	Parking Sensors Front 
Parking Sensors Rear 	Reverse Camera 
Blind Spot Monitor 	Collision Warning System 
Traction Control 	Front Camera 
Side Camera 	Airbag Curtain Shield 
Airbag Driver Front 	ABS 
Central Locking 	Child Safety Locking 



Exteriors

Fog Light Front 	Roof Rails 
Running Lights 	LED Headlights 



Performance

Paddle Shift 	Hill Descent Control 
--	--



Entertainment

Bluetooth Player 	Infotainment System 
USB player 	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door



Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm

Rear left door



Rear right door



Panel: Paint Chip-off < 5mm

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm

Fenders Condition

Left Fender



Right Fender



Condition: Paint Chip-off < 5mm

Right Fender: Paint Chip-off < 5mm

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Dent < 30mm, Scratch < 50mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm, Chip < 8mm

Hood Condition

Hood



Bonnet: Paint Chip-off < 5mm

Trunk Condition

Trunk



Door Trim: Scuff/ Disfiguration < 50mm

Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	!
		Light Scuffing < 80mm	
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	!
		Condition: Light Scuffing < 80mm	
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	!	Left Rear Alloy/ Rim	!
Rim: Alloy Face/ Scuff < 50mm		Rim: Alloy Face/ Scuff < 50mm	
Right Front Alloy/ Rim	!	Right Rear Alloy/ Rim	!
Rim: Alloy Face/ Scuff < 50mm		Rim: Alloy Face/ Scuff < 50mm	
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition	!
		Light Scuffing < 50mm	

Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Gear shift



Drive Axle



4*4 Condition (If Applicable)



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key		Spare Key(s)	
------------	---	--------------	---

Door Locks

Child Safety Locking	
----------------------	---

Dashboard

Instrument Panel	
------------------	---

Airbags

Airbags	
---------	---

Controls		Cruise Control	
----------	---	----------------	---

Heads Up Display		Infotainment Display	
------------------	---	----------------------	---

Engine Sensors		OBD Connector	
----------------	---	---------------	---

Radar (If Equipped)		Navigation System	
---------------------	---	-------------------	---

Music System	
--------------	---

Sunroof Operation	
-------------------	---

Sunroof	
---------	---

Camera	
--------	---

Lights	
--------	---

Headlight		Interior Lights	
-----------	---	-----------------	---

Tail Light Cluster		Daylight Running Lights	
--------------------	---	-------------------------	---

License Plate Light		Fog Lights	
---------------------	---	------------	---

Air Conditioning	
------------------	---

AC Cooling		AC Switch	
------------	---	-----------	---

AC System Leaks		Center AC Vent	
-----------------	---	----------------	---

Front Right AC Vent		Adjuster Clip Crack/Fair Use Wear	
---------------------	---	-----------------------------------	---

Rear Blower Switch		Heater	
--------------------	---	--------	---

Rear Defogger		USB Charging Port	
---------------	--	-------------------	--

Power/ Manual Windows		Memory Seats	
-----------------------	--	--------------	--

Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
--------------------------------	--	-----------------	--

Cup Holder		Glove Box	
		Glove Box: Minor Scuffing/Crack/Fair Use Wear	

Steering Wheel		Sunvisor	
Steering Wheel Fair Use Wear			

Seat Upholstery		Manual Seat Movement	
-----------------	--	----------------------	--

Seat Belts		Head Rest	
------------	--	-----------	--

Door Controls And Trim		Carpet	
------------------------	--	--------	--

Headliner		Rear View Mirror	
-----------	--	------------------	--

Toolkit	
---------	--

Tyres

Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
---------------------------	--	--------------------------	--

Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
----------------------------	--	---------------------------	--

Tyres Depth (Remaining)

LHS Front Tyre	<45%	LHS Rear Tyre	<85%
----------------	------	---------------	------

RHS Front Tyre	<45%	RHS Rear Tyre	<85%
----------------	------	---------------	------

Spare Tyre	No spare
	tyre



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE