



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 MAZDA 3

S | 93,711 KM

VIN: JM7BN1SZ3H1146464

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Rear



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	93711	 Specs	Yes
 Engine	1.6L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color Silver
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	JM7BN1SZ3H1146464		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	
 Safety & Security			
Parking Sensors Rear		Traction Control	
Airbag Driver Front		ABS	

Central Locking	✓	Child Safety Locking	✓
 Entertainment			
Bluetooth Player	✓	Infotainment System	✓
USB player	✓		
 Exteriors			
Halogen Headlights	✓		

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door



Front right door

Panel: Light Scuffing < 50mm



Rear left door

Panel: Scratch < 50mm



Rear right door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel

Condition: Dent < 30mm



Right Quarter Panel

Condition: Dent < 30mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition	!
		Light Scuffing < 50mm	
Monogram	✓	Window Glass	✓

Wiper	✓	
Panel Condition		
Rear Trunk Panel	✓	

Engine & Transmission

Engine		
Engine Body	✓	Engine Performance ✓
Engine Oil (Condition & Level)	✓	Exhaust System ✓
Radiator Condition	✓	Radiator Coolant ✓
Battery		
Battery Terminal & Tightness	✓	
Fuel System		
Fuel Cap	✓	Fuel Tank ✓
Transmission Operation		
Gear Shifting	✓	Drive Axle ✓
Transmission Fluid	✓	

Steering, Suspension & Brakes

Steering		
Steering wheel	✓	
Brake System		
Parking Brake	✓	Brake Master Cylinder ✓
Brake Disc & Brake Pad	✓	Brake Fluid ✓
Pedals	✓	
Suspension		
Shock Absorbers	✓	

Electricals, Controls & Lights

Keys		
Master Key	✓	Spare Key(s) ✓

Door Locks		
Child Safety Locking	✓	
Dashboard		
Instrument Panel	✓	
Airbags		
Airbags	✓	
Controls	✓	Cruise Control ✓
Infotainment Display	✓	Engine Sensors ✓
OBD Connector	✓	Music System ✓
Lights		
Headlight	✓	Interior Lights ✓
Tail Light Cluster	✓	Turn Signal Lights ✓
License Plate Light	✓	
Air Conditioning		
AC Cooling	✓	AC Switch ✓
AC System Leaks	✓	Center AC Vent ✓
Front Right AC Vent	✓	Heater ✓
Parking Sensors	✓	Rear Defogger ✓
USB Charging Port	✓	Power/ Manual Windows ✓

Interiors & Luggage

Dashboard And Instrument Panel		
Dashboard Upholstery: Minor Scuffing/ Disfiguration/ Melted	!	Central Console ✓
Glove Box	✓	Steering Wheel ✓
Sunvisor	✓	Seat Upholstery ✓
Manual Seat Movement	✓	Seat Belts ✓

Head Rest	✓	Door Controls And Trim	✓
Grab Handle	✓	Carpet	✓
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition

Left Hand Side Rear Tyre	✓	Right Hand Side Front Tyre	✓
Right Hand Side Rear Tyre	✓	Spare Tyre	✓

Tyres Depth (Remaining)

LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<55%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE