



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 BMW X5

X DRIVE 35 I | 95,596 KM

VIN: WBAKR0104H0V06050

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat, Memory Seats & more

Basic Details

 Kilometers	95596	 Specs	Yes
 Engine	3.0L	 Option Type	Mid Option
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	WBAKR0104H0V06050		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
360 degree Camera		Navigation	
Parking Sensors Front		Parking Sensors Rear	
Reverse Camera		Blind Spot Monitor	
Traction Control		Front Camera	
Side Camera		Airbag Curtain Shield	

Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
Comfort & Convenience			
Climate Control AC		Cruise Control	
Memory Seats		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Soft Door Close	
Power Folding Mirrors		Power Tailgate/ Power Trunk	
Power Head Rest		Rear Defogger	
Central Armrest		Automatic Headlights	
Exteriors			
Fog Light Front		Roof Rails	
Running Lights		Rear Bumper Spoiler	
LED Headlights			
Performance			
Paddle Shift		Hill Descent Control	
Entertainment			
Bluetooth Player		Infotainment System	
USB player			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door

Panel: Low Visibility Dent < 30mm, Partially



Repainted

Rear left door

Panel: Partially Repainted, Low Visual Dent < 30mm

Rear right door

Inner Beading: Rubber Crack/ Tear < 5mm



Fenders Condition

Left Fender



Right Fender

Condition: Partially Repainted



Condition: Partially Repainted

Quarter Panels Condition

Left Quarter Panel

Condition: Light Scuffing<50mm, Partially
Repainted

Right Quarter Panel

Condition: Low Visual Dent < 30mm, Light
Scuffing<50mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm, Partially
Repainted



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof		
Pillars Condition		
Left A Pillar		Right A Pillar
Left A to B Pillar Beading		Right A to B Pillar Beading
Right A to B Pillar		Left B Pillar
Left B Pillar Trim		Left B to C Pillar Beading
Right C Pillar Trim		Right B to C Pillar
Right B to C Pillar Beading		Left C Pillar
Running Board Condition		
Left Running Board		Right Running Board
Rear Left Sill Trim: Light Scuffing < 80mm		Right Foot Board: Light Scuffing < 80mm
Sunroof Glass Condition (If Equipped)		
Sun Roof Glass		
Windshield Condition		
Front Windshield		Rear Windshield
Structural Assessment		
Chassis Condition		Radiator Support
Apron		Boot Floor
Firewall Condition		Cowl Top
Head Light Support Condition		
Cowl Top		
Cowl Top		
Rear View Mirror Condition		
Left Hand Side Mirror		Left Side Mirror
Right Side Mirror		Right Hand Side Mirror
Alloy Wheel/ Rim		
Left Front Alloy/ Rim		Left Rear Alloy/ Rim
Rim: Alloy Edge Scuffing > 50mm, Alloy Face		Rim: Alloy Face Light Scuffing < 50mm, Alloy Edge Scuffing > 50mm
Light Scuffing < 50mm		
Right Front Alloy/ Rim		Right Rear Alloy/ Rim

Rim: Alloy Edge Scuffing < 80mm, Alloy Face

Light Scuffing < 50mm

Wheel cover



Rim: Alloy Edge/Scuffing<80mm, Alloy

Face/Light Scuffing<50mm

Grill Condition

Light Scuffing < 50mm



Antenna



Window Glass



Monogram



Panel Condition

Rear Trunk Panel



Wiper



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Gear shift



Drive Axle



4*4 Condition (If Applicable)



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Heads Up Display



Infotainment Display



Engine Sensors



OBD Connector



Radar (If Equipped)



Navigation System



Music System



Sunroof Operation

Sunroof



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	!
Front Right AC Vent	✓	Adjuster Clip Crack/Fair Use Wear	
Rear Blower Switch	!	Heater	✓
Heater Not Working			
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓	Memory Seats	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<65%
RHS Front Tyre	<75%	RHS Rear Tyre	<65%
Spare Tyre	No spare		
	tyre		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE