



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2015 JEEP GRAND CHEROKEE

LIMITED | 100,182 KM

VIN: 1C4RJFBGXFC612098

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat, Memory Seats & more

Basic Details

 Kilometers	100182	 Specs	Yes
 Engine	3.6L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Leather Trim	 Number of Airbags	7 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	1C4RJFBGXFC612098		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Climate Control AC	
Memory Seats	
Steering Mounted Audio Controls	
Ventilated Seat	
Rear Defogger	
Cruise Control	
Rear Armrest with cupholder	
Power Folding Mirrors	
Power Tailgate/ Power Trunk	
Central Armrest	

Remote Engine Start		Automatic Headlights	
Steering Column Adjuster			
Externiors			
Fog Light Front		Roof Rails	
Running Lights		Rear Bumper Spoiler	
HID Headlights			
Safety & Security			
Navigation		Parking Sensors Front	
Parking Sensors Rear		Reverse Camera	
Traction Control		Airbag Curtain Shield	
Airbag Knees		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
Performance			
Paddle Shift		Hill Descent Control	
Entertainment			
Bluetooth Player		Infotainment System	
USB player			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door

Panel: Low Visibility Dent < 30mm, Paint



Chip-off < 5mm, Light Scuffing < 50mm

Rear left door



Rear right door

Moulding: Light Scuffing < 50mm



Fenders Condition

Left Fender

Condition: Low Visual Dent < 30mm, Paint



Chip-off < 5mm, Light Scuffing < 50 mm

Right Fender

Condition: Paint Chip-off < 5mm, Low Visual



Dent < 30mm

Quarter Panels Condition

Left Quarter Panel

Trim: Light Scuffing < 80mm



Right Quarter Panel

Condition: Light Scuffing < 50mm, Low Visual



Dent < 30mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Dent < 50mm



Hood Condition

Hood

Bonnet: Low Visibility Dent < 30mm, Paint



Chip-off < 5mm, Light Scuffing < 50mm

Trunk Condition

Trunk

Door Trim: Light Scuffing < 50mm



Trunk conditon

Trunk



Roof Condition

Roof		
Pillars Condition		
Left A Pillar		Right A Pillar
Left A to B Pillar Beading		Right A to B Pillar Beading
Right A to B Pillar		Left B Pillar
Left B Pillar Trim		Left B to C Pillar Beading
Right C Pillar Trim		Right B to C Pillar
Right B to C Pillar Beading		Left C Pillar
Running Board Condition		
Left Running Board		Right Running Board
		Right Foot Board: Light Scuffing < 80mm
Sunroof Glass Condition (If Equipped)		
Sun Roof Glass		
Windshield Condition		
Front Windshield		
Condition: Driver Side/Stone Chip		
Mark<5mm, Passenger Side/Stone Chip		Rear Windshield
Mark<8mm		
Structural Assessment		
Chassis Condition		Radiator Support
Apron		Boot Floor
Firewall Condition		Cowl Top
		Beading: Crack/Fair Use Wear<50mm
Head Light Support Condition		
Cowl Top		
Cowl Top		
Rear View Mirror Condition		
Left Hand Side Mirror		Left Side Mirror
Right Side Mirror		
Alloy Wheel/ Rim		
Left Front Alloy/ Rim		Left Rear Alloy/ Rim
Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/		Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/

Scuff < 80mm	Scuff < 80mm		
Right Front Alloy/ Rim	Right Rear Alloy/ Rim		
Rim: Alloy Face/ Scuff < 50mm	!	Rim: Alloy Face/ Scuff < 50mm	!
Spare Alloy/ Rim Condition	✓		
Antenna	✓		
Monogram	✓		
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine	
Engine Body	✓
Engine Oil (Condition & Level)	✓
Radiator Condition	✓
Engine Performance	✓
Exhaust System	✓
Radiator Coolant	✓
Battery	
Battery Terminal & Tightness	✓
Fuel System	
Fuel Tank	✓
Transmission Operation	
Gear Shifting	✓
Drive Axle	✓
Gear shift	✓
4*4 Condition (If Applicable)	✓
Transmission Fluid	✓

Steering, Suspension & Brakes

Steering	
Steering wheel	✓
Brake System	
Parking Brake	✓
Brake Master Cylinder	✓

Brake Disc & Brake Pad
Rear Right: minor imperfection



Brake Fluid



Pedals



Suspension



Shock Absorbers

Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)
Buttons Faded



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Navigation System



Music System



Sunroof Operation

Sunroof



Camera



Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓	Seat Heaters	✓
Memory Seats	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	!	Manual Seat Movement	✓
Driver Seat: Minor Smudge/ Cracks			
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre minor imperfection	!	Left Hand Side Rear Tyre minor imperfection	!
Right Hand Side Front Tyre minor imperfection	!	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<55%

Spare Tyre

<90%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE