



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2017 JEEP CHEROKEE**

**SPORT | 87,438 KM**

VIN: 1C4PJMAS5HW574881

## **Car highlights**



### **Four wheel drive**

This car has a Four wheel drive



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**











Power driver seat

Basic Details

|  |                   |   |                      |
|--|-------------------|---|----------------------|
|  Kilometers       | 87438             |  Specs             | Yes                  |
|  Engine           | 3.2L              |  Option Type       | Semi Loaded          |
|  Transmission     | Automatic         |  Drive             | Four Wheel Drive     |
|  Body Type        | SUV               |  Fuel              | Petrol               |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color White |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 9 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 1 Keys               |
|  VIN number      | 1C4PJMAS5HW574881 |   |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  |   |                             |   |
|--|---|-----------------------------|---|
|  <b>Comfort &amp; Convenience</b> |   |                             |   |
| Cruise Control   |  | Rear Armrest with cupholder |  |
| Steering Mounted Audio Controls  |  | Rear Defogger               |  |
| Central Armrest  |  | Steering Column Adjuster    |  |
|  <b>Safety &amp; Security</b>     |   |                             |   |
| Parking Sensors Rear   |  | Reverse Camera              |  |

|  |   |                       |   |
|--|---|-----------------------|---|
| Traction Control   | ✓ | Airbag Curtain Shield | ✓ |
| Airbag Knees   | ✓ | Airbag Driver Front   | ✓ |
| ABS  | ✓ | Central Locking       | ✓ |
| Child Safety Locking   | ✓ |                       |   |
|  <b>Exteriors</b>     |   |                       |   |
| Roof Rails   | ✓ | HID Headlights        | ✓ |
|  <b>Entertainment</b> |   |                       |   |
| Bluetooth Player   | ✓ | Infotainment System   | ✓ |
| USB player   | ✓ |                       |   |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition



|                 |   |                  |   |
|-----------------|---|------------------|---|
| Front left door |  | Front right door |  |
|-----------------|---|------------------|---|

|                |   |                              |   |
|----------------|---|------------------------------|---|
| Rear left door |  | Rear right door              |  |
|                |   | Panel: Light Scuffing < 50mm |   |

### Fenders Condition

|  |   |              |   |
|--|---|--------------|---|
| Left Fender                            |  | Right Fender |  |
| Condition: Dent < 30mm, Scratch < 50mm |   |              |   |


### Quarter Panels Condition

|                    |  |   |  |
|--------------------|--|---|--|
| Left Quarter Panel |  | Right Quarter Panel                             |  |
|                    |  | Condition: Scratch < 50mm, Paint Chip-off < 5mm |  |

### Front Bumper Condition

|              |   |
|--------------|---|
| Front Bumper |  |
|--------------|---|

### Rear Bumper Condition

|                                    |   |
|------------------------------------|---|
| Rear Bumper                        |  |
| Rear Bumper: Light Scuffing < 80mm |   |

### Hood Condition

|   |   |
|---|---|
| Hood  |  |
| Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm, Low Visibility Dent < 30mm |   |

### Trunk Condition

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

### Trunk conditon

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

### Roof Condition

|      |   |
|------|---|
| Roof |  |
|------|---|

### Pillars Condition

|                              |   |                             |   |
|------------------------------|---|-----------------------------|---|
| Left A Pillar                | ✓ | Right A Pillar              | ✓ |
| Left A to B Pillar Beading   | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar          | ✓ | Left B Pillar               | ✓ |
| Left B Pillar Trim           | ✓ | Left B to C Pillar Beading  | ✓ |
| Right C Pillar Trim          | ✓ | Right B to C Pillar         | ✓ |
| Right B to C Pillar Beading  | ✓ | Left C Pillar               | ✓ |
| Running Board Condition      |   |                             |   |
| Left Running Board           | ✓ | Right Running Board         | ✓ |
| Windshield Condition         |   |                             |   |
| Front Windshield             | ✓ | Rear Windshield             | ✓ |
| Structural Assessment        |   |                             |   |
| Chassis Condition            | ✓ | Radiator Support            | ✓ |
| Apron                        | ✓ | Boot Floor                  | ✓ |
| Firewall Condition           | ✓ | Cowl Top                    | ✓ |
| Head Light Support Condition | ✓ |                             |   |
| Cowl Top                     |   |                             |   |
| Cowl Top                     | ! |                             |   |
| Fair Use Wear/Crack<5mm      |   |                             |   |
| Rear View Mirror Condition   |   |                             |   |
| Left Hand Side Mirror        | ✓ | Left Side Mirror            | ✓ |
| Right Side Mirror            | ✓ |                             |   |
| Alloy Wheel/ Rim             |   |                             |   |
| Left Front Alloy/ Rim        | ✓ | Left Rear Alloy/ Rim        | ✓ |
| Right Front Alloy/ Rim       | ✓ | Right Rear Alloy/ Rim       | ✓ |
| Spare Alloy/ Rim Condition   | ✓ |                             |   |
| Wheel Arch                   | ✓ | Wheel cover                 | ✓ |
| Antenna                      | ✓ | Grill Condition             | ! |
|                              |   | Light Scuffing < 50mm       |   |

|                  |   |              |   |
|------------------|---|--------------|---|
| Monogram         | ✓ | Window Glass | ✓ |
| Wiper            | ✓ |              |   |
| Panel Condition  |   |              |   |
| Rear Trunk Panel | ✓ |              |   |

## Engine & Transmission

|                                |   |                    |   |
|--------------------------------|---|--------------------|---|
| Engine                         |   |                    |   |
| Engine Body                    | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System     | ✓ |
| Turbocharger/ Supercharger     | ✓ | Radiator Condition | ✓ |
| Radiator Coolant               | ✓ |                    |   |
| Battery                        |   |                    |   |
| Battery Terminal & Tightness   | ✓ |                    |   |
| Fuel System                    |   |                    |   |
| Fuel Tank                      | ✓ |                    |   |
| Transmission Operation         |   |                    |   |
| Gear Shifting                  | ✓ | Drive Axle         | ✓ |
| 4*4 Condition (If Applicable)  | ✓ | Transmission Fluid | ✓ |

## Steering, Suspension & Brakes

|                        |   |                       |   |
|------------------------|---|-----------------------|---|
| Steering               |   |                       |   |
| Steering wheel         | ✓ |                       |   |
| Brake System           |   |                       |   |
| Parking Brake          | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid           | ✓ |
| Pedals                 | ✓ |                       |   |
| Suspension             |   |                       |   |
| Shock Absorbers        | ✓ |                       |   |



## Electricals, Controls & Lights

### Keys

Master Key



### Door Locks

Child Safety Locking



### Dashboard

Instrument Panel



### Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System

Condition: Button(s) Faded



Camera



### Lights

Headlight



Interior Lights



Tail Light Cluster



License Plate Light



### Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Defogger



USB Charging Port



Power/ Manual Windows



## Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Trim: Light Scuffing/Disfiguration



Central Console

Gear Shift Knob: Knob Fair Use Wear





|   |   |   |   |
|---|---|---|---|
| Cup Holder  | ✓ | Glove Box                                     | ! |
|   |   | Glove Box: Minor Scuffing/Crack/Fair Use Wear |   |
| Steering Wheel  | ! | Sunvisor                                      | ✓ |
| Steering Wheel Fair Use Wear  |   |   |   |
| Seat Upholstery   | ! | Manual Seat Movement                          | ✓ |
| Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears, Minor Smudge/ Cracks, Minor Fair Wear/Fade off |   |   |   |
| Seat Belts  | ✓ | Head Rest                                     | ✓ |
| Door Controls And Trim  | ✓ | Grab Handle                                   | ✓ |
| Carpet  | ! | Headliner                                     | ! |
| Front Left Floor Mat: Smudge/Burn/Crack   |   | Rear Left: Smudge/Disfiguration               |   |
| Rear View Mirror  | ✓ | Toolkit                                       | ✓ |

## Tyres

|                            |      |                           |      |
|----------------------------|------|---------------------------|------|
| Tyres Condition            |      |                           |      |
| Left Hand Side Front Tyre  | ✓    | Left Hand Side Rear Tyre  | ✓    |
| Right Hand Side Front Tyre | ✓    | Right Hand Side Rear Tyre | ✓    |
| Spare Tyre                 | ✓    |                           |      |
| Tyres Depth (Remaining)    |      |                           |      |
| LHS Front Tyre             | <55% | LHS Rear Tyre             | <85% |
| RHS Front Tyre             | <85% | RHS Rear Tyre             | <85% |
| Spare Tyre                 | <75% |                           |      |



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE