



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2015 HYUNDAI TUCSON

GLS | 125,279 KM

VIN: KMHJT81E8FU033426

## Car highlights



### Four wheel drive

This car has a Four wheel drive



### Great Parking Assistance

Reverse Camera, Parking Sensors Rear



### Bluetooth

Enjoy your drive with bluetooth



### Amazing Comfort

Power driver seat

## Basic Details

 Kilometers	<b>125279</b>	 Specs	<b>Yes</b>
 Engine	<b>2.0L</b>	 Option Type	<b>Semi Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Four Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color White</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>KMHJT81E8FU033426</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Exteriors</b>			
Fog Light Front		Roof Rails	
Halogen Headlights			
 <b>Comfort &amp; Convenience</b>			
Rear Armrest with cupholder		Steering Mounted Audio Controls	
Rear Defogger		Central Armrest	



## Safety & Security

Parking Sensors Rear		Reverse Camera	
Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	



## Performance

Differential Locks		
--------------------	--	--



## Entertainment

Bluetooth Player		Infotainment System	
USB player			

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Panel: Low Visual Dent < 30mm, Light

Scuffing < 50mm

Fenders Condition

Left Fender

Condition: Scratch < 50mm, Paint Chip-off < 5mm

Right Fender

Condition: Scratch < 50mm, Paint Chip-off < 5mm

Quarter Panels Condition

Left Quarter Panel

Condition: Dent < 30mm



Right Quarter Panel

Condition: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip < 8mm



Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



#### Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	

#### Running Board Condition

Left Running Board		Right Running Board	
--------------------	--	---------------------	--

#### Sunroof Glass Condition (If Equipped)

Sun Roof Glass	
----------------	--

#### Windshield Condition

Front Windshield		Rear Windshield	
------------------	--	-----------------	--

#### Structural Assessment

Chassis Condition		Radiator Support	
Apron		Boot Floor	
Firewall Condition		Cowl Top	
Head Light Support Condition			

#### Cowl Top

Cowl Top	
----------	--

#### Rear View Mirror Condition

Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror		Right Hand Side Mirror	

#### Alloy Wheel/ Rim

Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	

#### Spare Alloy/ Rim Condition

Wheel cover		Antenna	
-------------	--	---------	--

Grill Condition  
Light Scuffing < 50mm



Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



4\*4 Condition (If Applicable)



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



## Electricals, Controls & Lights

## Keys

Master Key



Spare Key(s)



## Door Locks

Child Safety Locking



## Dashboard

Instrument Panel



## Airbags

Airbags



## Controls



Infotainment Display



Engine Sensors



OBD Connector



## Music System

Condition: Button(s) Faded



## Sunroof Operation

Sunroof



Camera



## Lights

Headlight



Interior Lights



Tail Light Cluster



Turn Signal Lights



Right ORVM: Light Scuffing < 50mm

License Plate Light



Fog Lights



## Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Defogger



USB Charging Port



Power/ Manual Windows



## **Interiors & Luggage**

### Dashboard And Instrument Panel

Dashboard Upholstery: Minor Color Dullness,  Central Console   
Minor Scuffing/ Crack/ Fair Use Wear

Cup Holder		Glove Box	
Steering Wheel		Sunvisor	
Seat Upholstery		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	
Carpet		Headliner	
Rear View Mirror		Toolkit	

## **Tyres**

### Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			

### Tyres Depth (Remaining)

LHS Front Tyre	<65%	LHS Rear Tyre	<65%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<55%		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE