



### RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

### 1 Months Warranty

Enjoy peace of mind for your car purchase

### Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2016 NISSAN ALTIMA

S | 174,610 KM

VIN: 1N4AL3A95GC106470

## Car highlights



### Cruise control

Cruise control to drive with ease & comfort



### Great Parking Assistance

Reverse Camera



### Bluetooth

Enjoy your drive with bluetooth



### Amazing Comfort

Power driver seat

## Basic Details

 Kilometers	<b>174610</b>	 Specs	<b>Yes</b>
 Engine	<b>2.5L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>SEDAN</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Steel Wheels</b>	 Exterior Color	<b>Exterior Color White</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>1N4AL3A95GC106470</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Cruise Control		Rear Armrest with cupholder	
Steering Mounted Audio Controls		Rear Defogger	
Central Armrest		Steering Column Adjuster	
 <b>Safety &amp; Security</b>			
Reverse Camera		Traction Control	

Airbag Driver Front		ABS	
Central Locking		Child Safety Locking	
<b>Entertainment</b>			
Bluetooth Player		Infotainment System	
USB player			
<b>Exteriors</b>			
Halogen Headlights			

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door

Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm, Low Visibility Dent < 30mm



Rear left door



Rear right door

Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm, Low Visual Dent < 30mm



Fenders Condition

Left Fender

Condition: Scratch < 50mm, Dent < 30mm, Paint Chip-off < 5mm



Right Fender

Right Fender: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Scratch < 50mm, Paint Chip-off < 5mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Chip< 8mm



Hood Condition

Hood

Bonnet: Paint Chip-off < 5mm, Low Visibility Dent < 30mm



Trunk Condition

Trunk



Trunk conditon

Trunk



## Roof Condition

Roof



## Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Right B to C Pillar Beading



Left C Pillar



## Running Board Condition

Left Running Board



Right Running Board



## Windshield Condition

Front Windshield



Rear Windshield



## Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top



## Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Alloy Wheel/ Rim



Spare Alloy/ Rim Condition



Wheel Arch

Wheel cover



Grill Condition



Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



## Door Locks

Child Safety Locking 

## Dashboard

Instrument Panel 

## Airbags

Airbags 

## Controls



Cruise Control



Infotainment Display 

Engine Sensors



OBD Connector 

Navigation System



Condition: Available - SD Card Missing

Music System 

Camera



## Lights

Headlight 

Interior Lights



Tail Light Cluster 

License Plate Light



## Air Conditioning

AC Cooling 

AC Switch



AC System Leaks 

Center AC Vent



Front Right AC Vent 

Heater



Rear Blower Switch 

Rear Defogger 

USB Charging Port



Power/ Manual Windows 

## Interiors & Luggage

Dashboard And Instrument Panel 

Central Console



Cup Holder 

Glove Box



Steering Wheel 

Steering Wheel Fair Use Wear

Sunvisor



## Seat Upholstery

Driver Seat: Minor Leather/ Fabric Fair Use



Wear/ Tears, Minor Smudge/ Cracks

Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Rear Left Door: Light Scuffing

Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<45%

RHS Front Tyre

<65%

RHS Rear Tyre

<45%

Spare Tyre

<55%



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE