



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2014 MITSUBISHI OUTLANDER

GLX BASIC | 175,892 KM

VIN: JMYXTGF3WEZ700491

Car highlights



Four wheel drive

This car has a Four wheel drive



Great Parking Assistance

Parking Sensors Rear



Amazing Comfort
















Power driver seat



Airbag safety












Airbag Driver Front

Basic Details

 Kilometers	175892	 Specs	Yes
 Engine	2.4L	 Option Type	Basic
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color Brown
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	7 Seats	 Number of keys	1 Keys
 VIN number	JMYXTGF3WEZ700491		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Rear Armrest with cupholder			
Central Armrest			
 Safety & Security			
Parking Sensors Rear			
ABS			
		Airbag Driver Front	
		Central Locking	

Child Safety Locking	✓	
 Exteriors		
Roof Rails	✓	Halogen Headlights ✓
 Performance		
Differential Locks	✓	
 Entertainment		
USB player	✓	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



Exterior

Doors condition

Front left door

Handle: Scratch < 50mm



Front right door

Frame: Light Scuffing < 50mm



Rear left door

Handle: Scratch < 50mm



Rear right door

Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm



Fenders Condition

Left Fender

Condition: Dent > 30mm, Paint Chip-off < 5mm, Light Scuffing < 50 mm



Right Fender

Condition: Light Scuffing < 50mm



Quarter Panels Condition

Left Quarter Panel

Condition: Dent < 30mm, Scratch < 50mm



Right Quarter Panel

Condition: Dent > 30mm, Scuffing>50mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Crack/ Misaligned, Light Scuffing < 80mm



Hood Condition

Hood

Bonnet: Paint Damage/ Low Brightness, Low Visibility Dent < 30mm, Light Scuffing < 50mm, Paint Chip-off < 5mm



Trunk Condition

Trunk

Door Trim: Scuff/ Disfiguration< 50mm, Light Scuffing < 50mm



Trunk conditon

Trunk



Roof Condition

Roof

Roof Moulding Condition: minor imperfection



Pillars Condition

Left A Pillar



Left A to B Pillar Beading



Right A to B Pillar



Left B Pillar Trim

Light Scuffing



Right C Pillar Trim



Right B to C Pillar Beading



Right A Pillar



Right A to B Pillar Beading

Beading Crack/ Tear < 5mm



Left B Pillar

Condition: Dent < 30mm, Scratch < 50mm



Left B to C Pillar Beading



Right B to C Pillar

Light Scuffing < 80mm



Left C Pillar



Running Board Condition

Left Running Board

Front Left Floor Trim: Light Scuffing < 80mm



Right Running Board

Front Right Sill Trim: Low Visual Dent < 50mm



Windshield Condition

Front Windshield



Rear Windshield



Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top

Fair Use Wear/Crack>5mm



Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Alloy Wheel/ Rim

Spare Alloy/ Rim Condition



Wheel Arch



Wheel cover



Antenna	⚠	Grill Condition	⚠
minor imperfection		Light Scuffing < 50mm	
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Acid Marks/ Bird Dropping < 5mm	⚠		

🔧 Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓	Transmission Fluid	✓

🚗 Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		



Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Infotainment Display



Engine Sensors



OBD Connector



Music System



Lights

Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



Turn Signal Lights

Right ORVM: Light Scuffing < 50mm



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent

Adjustable Knobs Limited Movement



Heater



Rear Defogger

Extensive Wear Of Strip



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/



Central Console



Disfiguration/ Melted

Cup Holder



Glove Box



Steering Wheel



Sunvisor



Steering Wheel Fair Use Wear

Seat Upholstery

Driver Seat: Minor Leather/ Fabric Fair Use
Wear/ Tears, Minor Smudge/ Cracks



Manual Seat Movement

Driver Seat: minor imperfection



Seat Belts



Head Rest

Driver Seat: Fair Use Wear



Door Controls And Trim

Front Left Door: Fair Use Wear, Light Scuffing



Grab Handle



Carpet

Front Left Floor Mat: Smudge/Burn/Crack



Headliner

Front Left: Light Smudge/Disfiguration



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<85%

LHS Rear Tyre

<75%

RHS Front Tyre

<85%

RHS Rear Tyre

<85%

Spare Tyre

<55%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE