



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2020 HONDA HR V

LX | 64,260 KM

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Great Parking Assistance

Parking Sensors Rear



Bluetooth
















Enjoy your drive with bluetooth



Amazing Comfort











Power driver seat



Basic Details

| | | | |
|--|-------------------|---|--------------------|
|  Kilometers | 64260 |  Specs | Yes |
|  Engine | 1.8L |  Option Type | Semi Loaded |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SUV |  Fuel | Petrol |
|  Wheel Type | Alloy Wheels |  Exterior Color | Exterior Color Red |
|  Interior Trim | Fabric Trim |  Number of Airbags | 2 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | MRJRU5857LP010395 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|--|---|---------------------------------|---|
|  Comfort & Convenience | | | |
| Cruise Control |  | Steering Mounted Audio Controls |  |
| Rear Defogger |  | Central Armrest |  |
|  Safety & Security | | | |
| Parking Sensors Rear |  | Traction Control |  |
| Airbag Driver Front |  | ABS |  |

| | | | |
|--|---|----------------------|---|
| Central Locking | ✓ | Child Safety Locking | ✓ |
|  Exteriors | | | |
| Running Lights | ✓ | Rear Bumper Spoiler | ✓ |
| LED Headlights | ✓ | | |
|  Entertainment | | | |
| Bluetooth Player | ✓ | Infotainment System | ✓ |
| USB player | ✓ | | |

150 Point Detailed Inspection Report



We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

| | | | |
|-----------------|---|--|---|
| Front left door |  | Front right door |  |
| | | Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm | |

| | | | |
|--|---|---|---|
| Rear left door |  | Rear right door |  |
| Panel: Dent < 30mm, Scratch < 50mm, Paint Chip-off < 5mm | | Panel: Light Scuffing < 50mm, Acid Marks/ Bird Dropping < 5mm | |

Fenders Condition

| | | | |
|--|---|---|---|
| Left Fender |  | Right Fender |  |
| Condition: Dent < 30mm, Paint Chip-off < 5mm | | Right Fender: Dent < 30mm, Scratch < 50mm | |


Quarter Panels Condition

| | | | |
|--|---|------------------------|---|
| Left Quarter Panel |  | Right Quarter Panel |  |
| Condition: Dent < 30mm, Scratch < 50mm | | Condition: Dent < 30mm | |


Front Bumper Condition

| | |
|--------------|---|
| Front Bumper |  |
|--------------|---|


Rear Bumper Condition

| | |
|---|---|
| Rear Bumper |  |
| Rear Bumper: Light Scuffing < 80mm, Chip< 8mm | |

Hood Condition

| | |
|--|---|
| Hood |  |
| Bonnet: Low Visibility Dent < 30mm, Paint Chip-off < 5mm | |

Trunk Condition

| | |
|----------------------------------|---|
| Trunk |  |
| Door Trim: Light Scuffing < 50mm | |

Trunk conditon

| | |
|-------|---|
| Trunk |  |
|-------|---|

Roof Condition

| | | | |
|--|---|-------------------------------|---|
| Roof | ✓ | | |
| Pillars Condition | | | |
| Left A Pillar | ✓ | Right A Pillar | ✓ |
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ! | Left B to C Pillar Beading | ✓ |
| Light Scuffing | | | |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar Dent < 30mm | ! |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Windshield Condition | | | |
| Front Windshield | | | |
| Beading: Mouldings Crack/ Fair Use Wear < 50mm | ! | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Radiator Support | ✓ |
| Apron | ✓ | Boot Floor | ✓ |
| Firewall Condition | ✓ | Cowl Top | ✓ |
| Head Light Support Condition | ✓ | | |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ! | Left Rear Alloy/ Rim | ! |
| Rim: Alloy Edge/ Scuff < 80mm | | Rim: Alloy Edge/ Scuff < 80mm | |
| Right Front Alloy/ Rim | ! | Right Rear Alloy/ Rim | ! |
| Rim: Alloy Edge/ Scuff < 80mm | | Rim: Alloy Edge/ Scuff < 80mm | |
| Spare Alloy/ Rim Condition | ✓ | | |

| | | | |
|------------------|---|--|---|
| Wheel Arch | ✓ | Wheel cover | ✓ |
| Antenna | ✓ | Grill Condition Light Scuffing < 50mm | ! |
| Monogram | ✓ | Window Glass | ✓ |
| Wiper | ✓ | | |
| Panel Condition | | | |
| Rear Trunk Panel | ✓ | | |

Engine & Transmission

| | | | |
|--------------------------------|---|--------------------|---|
| Engine | | | |
| Engine Body | ✓ | Engine Performance | ✓ |
| Engine Oil (Condition & Level) | ✓ | Exhaust System | ✓ |
| Radiator Condition | ✓ | Radiator Coolant | ✓ |
| Battery | | | |
| Battery Terminal & Tightness | ✓ | | |
| Fuel System | | | |
| Fuel Cap | ✓ | Fuel Tank | ✓ |
| Transmission Operation | | | |
| Gear Shifting | ✓ | Drive Axle | ✓ |
| Transmission Fluid | ✓ | | |

Steering, Suspension & Brakes

| | | | |
|------------------------|---|-----------------------|---|
| Steering | | | |
| Steering wheel | ✓ | | |
| Brake System | | | |
| Parking Brake | ✓ | Brake Master Cylinder | ✓ |
| Brake Disc & Brake Pad | ✓ | Brake Fluid | ✓ |
| Pedals | ✓ | | |
| Suspension | | | |

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Lights

Headlight

Left: Light Scuff Marks < 50mm



Interior Lights



Tail Light Cluster



Daylight Running Lights
Right DRL: Low Brightness



License Plate Light



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cigarette Lighter: Cigarette Lighter Missing

Cup Holder



Glove Box



Steering Wheel

Steering Wheel Fair Use Wear



Sunvisor



Seat Upholstery

Driver Seat: Minor Leather/ Fabric Fair Use
Wear/ Tears



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet

Front Left Floor Mat: Floor Mat Lock Damage,
Smudge/Burn/Crack



Headliner

Rear Left: Smudge/Disfiguration



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE