



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2015 JEEP GRAND CHEROKEE

LAREDO | 115,333 KM

VIN: 1C4RJFAG2FC178261

## Car highlights



### Four wheel drive

This car has a Four wheel drive



### Cruise control

Cruise control to drive with ease & comfort



### Bluetooth

Enjoy your drive with bluetooth



### Amazing Comfort

Power driver seat

## Basic Details

 Kilometers	<b>115333</b>	 Specs	<b>Yes</b>
 Engine	<b>3.6L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Four Wheel Drive</b>
 Body Type	<b>SUV</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color White</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>7 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>1C4RJFAG2FC178261</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>	
Climate Control AC	
Rear Armrest with cupholder	
Power Folding Mirrors	
Central Armrest	
 <b>Exteriors</b>	

Fog Light Front		Roof Rails	
Running Lights		HID Headlights	
 <b>Performance</b>			
Paddle Shift		Hill Descent Control	
 <b>Safety &amp; Security</b>			
Parking Sensors Front		Parking Sensors Rear	
Traction Control		Airbag Curtain Shield	
Airbag Knees		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
 <b>Entertainment</b>			
Bluetooth Player		Infotainment System	
USB player			

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door

Panel: Low Visual Dent < 30mm, Light  
Scuffing < 50mm



Panel: Low Visibility Dent < 30mm, Light  
Scuffing < 50mm, Paint Chip-off < 5mm



Rear left door

Panel: Low Visual Dent < 30mm, Light  
Scuffing < 50mm

Rear right door

Panel: Low Visual Dent < 30mm, Light  
Scuffing < 50mm



Fenders Condition

Left Fender

Condition: Low Visual Dent < 30mm, Light  
Scuffing < 50 mm



Right Fender

Condition: Light Scuffing < 50mm, Low Visual  
Dent < 30mm



Quarter Panels Condition

Left Quarter Panel

Condition: Low Visual Dent < 30mm, Light  
Scuffing < 50mm



Right Quarter Panel

Condition: Light Scuffing < 50mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm, Dent <  
50mm



Hood Condition

Hood

Bonnet: Low Visibility Dent < 30mm, Light  
Scuffing < 50mm



Trunk Condition

Trunk



Trunk condition

Trunk



## Roof Condition

Roof



## Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Right B to C Pillar Beading



Left C Pillar



## Running Board Condition

Left Running Board



Right Running Board



Front Left Sill Trim: Scratch < 80mm

## Windshield Condition

Front Windshield



Rear Windshield



## Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top



## Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



## Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Rim: Alloy Face Light Scuffing < 50mm

Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Rim: Alloy Edge Scuffing < 80mm

Rim: Alloy Face/Light Scuffing<50mm

Spare Alloy/ Rim Condition



Wheel Arch		Antenna	
Grill Condition		Monogram	
Light Scuffing < 50mm			
Window Glass		Wiper	
Panel Condition			
Rear Trunk Panel			

---

## Engine & Transmission

Engine			
Engine Body		Engine Performance	
Engine Oil (Condition & Level)		Exhaust System	
Radiator Condition		Radiator Coolant	
Battery			
Battery Terminal & Tightness			
Fuel System			
Fuel Cap		Fuel Tank	
Transmission Operation			
Gear Shifting		Gear shift	
Drive Axle		4*4 Condition (If Applicable)	
Transmission Fluid			

---

## Steering, Suspension & Brakes

Steering			
Steering wheel			
Brake System			
Brake Master Cylinder		Brake Disc & Brake Pad	
Brake Fluid			
Pedals			
Suspension			

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Lights

Headlight



Left Washer: Not Working

Interior Lights



Tail Light Cluster



Turn Signal Lights



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Parking Sensors



Rear Defogger



USB Charging Port



Power/ Manual Windows



## **Interiors & Luggage**

Dashboard And Instrument Panel		Central Console	
Cup Holder		Glove Box	
Steering Wheel		Sunvisor	
Color Faded			
Seat Upholstery		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim		Grab Handle	
Carpet		Headliner	
Rear View Mirror		Toolkit	

## **Tyres**

### Tyres Condition

Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Spare Tyre			

### Tyres Depth (Remaining)

LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<55%		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE