



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2017 JEEP WRANGLER**

**RUBICON RECON | 145,539 KM**

VIN: 1C4BJWFG8HL628914

## **Car highlights**



### **Four wheel drive**

This car has a Four wheel drive



### **Cruise control**

Cruise control to drive with ease & comfort



### **Bluetooth**
















Enjoy your drive with bluetooth



### **Amazing Comfort**











Power driver seat

Basic Details

 Kilometers	145539	 Specs	Yes
 Engine	3.6L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	1C4BJWFG8HL628914		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>			
Climate Control AC		Cruise Control	
Steering Mounted Audio Controls		Rear Defogger	
Central Armrest		Automatic Headlights	
 <b>Exteriors</b>			
Fog Light Front		LED Headlights	



## Performance

Hill Descent Control



Differential Locks



## Safety & Security

Reverse Camera



Traction Control



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



## Entertainment

Bluetooth Player



Infotainment System



USB player







# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door	
Inner Frame: Scratch < 50mm		Weather Strip: Minor Rubber Fare Use Wear	
Rear left door		Rear right door	
Panel: Scratch < 50mm			

### Fenders Condition

Left Fender		Right Fender	
Condition: Scratch < 50mm			

### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Trim: Light Scuffing<80mm		Condition: Paint Chip-off < 5mm	

### Front Bumper Condition

Front Bumper	
--------------	---

### Rear Bumper Condition

Rear Bumper	
-------------	---

### Hood Condition

Hood	
------	---







### Trunk Condition

Trunk	
Door Trim: Light Scuffing < 50mm	

### Trunk conditon

Trunk	
-------	---

### Pillars Condition

Left A Pillar		Right A Pillar	
Right A to B Pillar		Left B Pillar	
Right B to C Pillar		Left C Pillar	
Light Scuffing < 80mm			

## Running Board Condition

Left Running Board

Front Left Floor Trim: Light Scuffing < 80mm



Right Running Board

Front Right Floor Trim: Light Scuffing < 80mm



## Windshield Condition

Front Windshield

Condition: Driver Side/Stone Chip

Mark<5mm, Passenger Side/Stone Chip

Mark<8mm



Rear Windshield



## Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



## Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Right Front Alloy/ Rim



Right Rear Alloy/ Rim



Spare Alloy/ Rim Condition



Wheel cover



Antenna



Grill Condition

Light Scuffing < 50mm



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓	Transmission Fluid	✓

## Steering, Suspension & Brakes

### Steering

Steering wheel ✓

### Brake System

Parking Brake ✓ Brake Master Cylinder ✓

Brake Disc & Brake Pad ✓ Brake Fluid ✓

Pedals ✓

### Suspension

Shock Absorbers ✓

## Electricals, Controls & Lights

### Keys

Master Key ✓ Spare Key(s) ✓

### Door Locks

Child Safety Locking ✓

### Dashboard

Instrument Panel ✓

### Airbags

Airbags	✓		
Controls	!	Cruise Control	✓
Horn: Colour Low Brightness			
Infotainment Display	✓	Engine Sensors	✓
OBD Connector	✓	Music System	✓
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	License Plate Light	✓
Fog Lights	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater Heater Not Working	!
Power/ Manual Windows	✓	Seat Heaters	✓

## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Glove Box	✓	Steering Wheel Steering Wheel Fair Use Wear	!
Sunvisor	✓	Seat Upholstery Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears, Minor Fair Wear/Fade off	!
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim Front Left Door: Light Scuffing	!
Grab Handle	✓	Carpet Trunk Floor Carpet: Wear & Tear < 80mm	!



Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

## Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<95%		



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE