



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 NISSAN MICRA

S | 131,496 KM

VIN: MDHAK3CR6KG000802

## Car highlights



### Amazing Comfort

Power driver seat



### Airbag safety

Airbag Driver Front



### Tilt Steering wheel

Tilt steering wheel for extra comfort



### Central Locking

Central locking for extra comfort

## Basic Details

 Kilometers	<b>131496</b>	 Specs	<b>Yes</b>
 Engine	<b>1.5L</b>	 Option Type	<b>Basic</b>
 Transmission	<b>Automatic</b>	 Drive	<b>Front Wheel Drive</b>
 Body Type	<b>HATCHBACK</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Steel Wheels</b>	 Exterior Color	<b>Exterior Color White</b>
 Interior Trim	<b>Fabric Trim</b>	 Number of Airbags	<b>2 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>2 Keys</b>
 VIN number	<b>MDHAK3CR6KG000802</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Traction Control		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
 Comfort & Convenience			
Rear Defogger			



## Exteriors

Halogen Headlights



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Front right door

Panel: Low Visibility Dent < 30mm, Light



Scuffing < 50mm

Rear left door



Rear right door

Panel: Dent < 30mm, Paint Chip-off < 5mm

Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm, Low Visual Dent < 30mm



Fenders Condition

Left Fender



Right Fender

Right Fender: Paint Chip-off < 5mm, Scratch < 50mm



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel

Condition: Dent < 30mm, Scratch < 50mm



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood

Bonnet: Light Scuffing < 50mm, Paint Chip-off < 5mm



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof		
Pillars Condition		
Left A Pillar		Right A Pillar
Left A to B Pillar Beading		Right A to B Pillar Beading
Right A to B Pillar		Left B Pillar
Left B Pillar Trim		Left B to C Pillar Beading
Right C Pillar Trim		Right B to C Pillar
Right B to C Pillar Beading		Left C Pillar
Running Board Condition		
Left Running Board		Right Running Board
Rear Left Sill Trim: Scratch < 80mm		
Windshield Condition		
Front Windshield		Rear Windshield
Structural Assessment		
Chassis Condition		Radiator Support
Apron		Boot Floor
Firewall Condition		Cowl Top
Head Light Support Condition		
Cowl Top		
Cowl Top		
Rear View Mirror Condition		
Left Hand Side Mirror		Left Side Mirror
Right Side Mirror		Right Hand Side Mirror
Alloy Wheel/ Rim		
Right Rear Alloy/ Rim		Spare Alloy/ Rim Condition
Wheel Arch		Wheel cover Front Right: Face/ Scuffs < 50mm
Antenna		Grill Condition Light Scuffing < 50mm

Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel			
Scratch < 50mm	!		

---

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Cap	✓	Fuel Tank	✓
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

---

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		
Suspension			
Shock Absorbers	✓		

---

## Electricals, Controls & Lights

## Keys

Master Key  Spare Key(s) 

## Door Locks

Child Safety Locking 

## Dashboard

Instrument Panel 

## Airbags

Airbags 

Controls  Infotainment Display 

Engine Sensors  OBD Connector 

Music System 

## Sunroof Operation

Sunroof 

## Lights

Headlight  Interior Lights 

Left: Light Scuff Marks < 50mm

Tail Light Cluster  License Plate Light 

## Air Conditioning

AC Cooling  AC Switch 

AC System Leaks  Center AC Vent 

Front Right AC Vent  Heater 

Rear Defogger  USB Charging Port 

Power/ Manual Windows 

## Interiors & Luggage

Dashboard And Instrument Panel  Central Console 

Cup Holder  Glove Box 

Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

## Tyres

### Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		

### Tyres Depth (Remaining)

LHS Front Tyre	<75%	LHS Rear Tyre	<55%
RHS Front Tyre	<65%	RHS Rear Tyre	<65%
Spare Tyre	<55%		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE