



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 6 Months Warranty

This car comes with 6 months or 10,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





## 2022 HYUNDAI CRETA

GL | 32,709 KM

### Car highlights



#### Low Mileage

This car has been driven less than 15,000 km  
a year



#### Cruise control

Cruise control to drive with ease & comfort



#### Apple play

Enjoy your drive with apple play



#### Amazing Comfort

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                      |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|----------------------|
|  Kilometers       | 32709             |  Specs             | Yes                  |
|  Engine           | 1.5L              |  Option Type       | Basic                |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive    |
|  Body Type        | SUV               |  Fuel              | Petrol               |
|  Wheel Type       | Steel Wheels      |  Exterior Color    | Exterior Color Black |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 2 Airbags            |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys               |
|  VIN number     | MALPB8120NM238449 |                                                                                                     |                      |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                      |                                                                                     |                             |                                                                                       |
|----------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----------------------------|---------------------------------------------------------------------------------------|
|  <b>Comfort &amp; Convenience</b> |                                                                                     |                             |                                                                                       |
| Cruise Control                                                                                                       |  | Rear Armrest with cupholder |  |
| Steering Mounted Audio Controls                                                                                      |  | Rear Defogger               |  |
| Central Armrest                                                                                                      |  | Automatic Headlights        |  |
| Steering Column Adjuster                                                                                             |  |                             |                                                                                       |
|  <b>Safety &amp; Security</b>     |                                                                                     |                             |                                                                                       |

|                                                                                                        |   |                     |   |
|--------------------------------------------------------------------------------------------------------|---|---------------------|---|
| Parking Sensors Rear                                                                                   | ✓ | Reverse Camera      | ✓ |
| Traction Control                                                                                       | ✓ | Airbag Driver Front | ✓ |
| ABS                                                                                                    | ✓ | Central Locking     | ✓ |
| Child Safety Locking                                                                                   | ✓ |                     |   |
|  <b>Exteriors</b>     |   |                     |   |
| Roof Rails                                                                                             | ✓ | Rear Bumper Spoiler | ✓ |
| Halogen Headlights                                                                                     | ✓ |                     |   |
|  <b>Entertainment</b> |   |                     |   |
| Bluetooth Player                                                                                       | ✓ | Apple Play          | ✓ |
| Android Auto Play                                                                                      | ✓ | USB Charging Port   | ✓ |
| Infotainment System                                                                                    | ✓ | USB player          | ✓ |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                 |                                                                                   |                                                                              |                                                                                     |
|-----------------|-----------------------------------------------------------------------------------|------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Front left door |  | Front right door<br>Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm |  |
|-----------------|-----------------------------------------------------------------------------------|------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|

|                |                                                                                   |                                                                       |                                                                                     |
|----------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Rear left door |  | Rear right door<br>Panel: Light Scuffing < 50mm, Paint Chip-off < 5mm |  |
|----------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------|-------------------------------------------------------------------------------------|

### Fenders Condition

|             |                                                                                   |              |                                                                                     |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|
| Left Fender |  | Right Fender |  |
|-------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|

### Quarter Panels Condition

|                    |                                                                                     |                                                   |                                                                                       |
|--------------------|-------------------------------------------------------------------------------------|---------------------------------------------------|---------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel<br>Condition: Low Visual Dent |  |
|--------------------|-------------------------------------------------------------------------------------|---------------------------------------------------|---------------------------------------------------------------------------------------|

### Front Bumper Condition

|              |                                                                                     |
|--------------|-------------------------------------------------------------------------------------|
| Front Bumper |  |
|--------------|-------------------------------------------------------------------------------------|

### Rear Bumper Condition

|                                    |                                                                                     |
|------------------------------------|-------------------------------------------------------------------------------------|
| Rear Bumper                        |  |
| Rear Bumper: Light Scuffing < 80mm |                                                                                     |

### Hood Condition

|                               |                                                                                     |
|-------------------------------|-------------------------------------------------------------------------------------|
| Hood                          |  |
| Bonnet: Light Scuffing < 50mm |                                                                                     |

### Trunk Condition

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Trunk conditon

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

### Roof Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Roof |  |
|------|-------------------------------------------------------------------------------------|

### Pillars Condition

|                             |   |                                                             |   |
|-----------------------------|---|-------------------------------------------------------------|---|
| Left A Pillar               | ✓ | Right A Pillar                                              | ✓ |
| Left A to B Pillar Beading  | ✓ | Right A to B Pillar Beading<br>Fair Use Wear/ Disfiguration | ! |
| Right A to B Pillar         | ✓ | Left B Pillar                                               | ✓ |
| Left B Pillar Trim          | ✓ | Left B to C Pillar Beading                                  | ✓ |
| Right C Pillar Trim         | ✓ | Right B to C Pillar                                         | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar                                               | ✓ |
| Running Board Condition     |   |                                                             |   |
| Left Running Board          | ✓ | Right Running Board                                         | ✓ |
| Windshield Condition        |   |                                                             |   |
| Front Windshield            | ✓ | Rear Windshield                                             | ✓ |
| Structural Assessment       |   |                                                             |   |
| Chassis Condition           | ✓ | Apron                                                       | ✓ |
| Boot Floor                  | ✓ | Firewall Condition                                          | ✓ |
| Cowl Top                    | ✓ | Head Light Support Condition                                | ✓ |
| Cowl Top                    |   |                                                             |   |
| Cowl Top                    | ✓ |                                                             |   |
| Rear View Mirror Condition  |   |                                                             |   |
| Left Hand Side Mirror       | ✓ | Left Side Mirror                                            | ✓ |
| Right Side Mirror           | ✓ |                                                             |   |
| Alloy Wheel/ Rim            |   |                                                             |   |
| Left Front Alloy/ Rim       | ✓ | Left Rear Alloy/ Rim                                        | ✓ |
| Right Front Alloy/ Rim      | ✓ | Right Rear Alloy/ Rim                                       | ✓ |
| Spare Alloy/ Rim Condition  | ✓ |                                                             |   |
| Wheel cover                 | ✓ | Antenna                                                     | ✓ |
| Grill Condition             | ✓ | Monogram                                                    | ✓ |
| Window Glass                | ✓ | Wiper                                                       | ✓ |
| Panel Condition             |   |                                                             |   |

Rear Trunk Panel



## Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

|                      |   |                       |   |
|----------------------|---|-----------------------|---|
| Airbags              | ✓ |                       |   |
| Controls             | ✓ | Cruise Control        | ✓ |
| Infotainment Display | ✓ | OBD Connector         | ✓ |
| Music System         | ✓ | Camera                | ✓ |
| Lights               |   |                       |   |
| Headlight            | ✓ | Interior Lights       | ✓ |
| Tail Light Cluster   | ✓ | License Plate Light   | ✓ |
| Air Conditioning     |   |                       |   |
| AC Cooling           | ✓ | AC Switch             | ✓ |
| AC System Leaks      | ✓ | Center AC Vent        | ✓ |
| Front Right AC Vent  | ✓ | Heater                | ✓ |
| Rear Blower Switch   | ✓ |                       |   |
| Parking Sensors      | ✓ | Rear Defogger         | ✓ |
| USB Charging Port    | ✓ | Power/ Manual Windows | ✓ |

## Interiors & Luggage

|                                |   |                      |   |
|--------------------------------|---|----------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console      | ✓ |
| Cup Holder                     | ✓ | Glove Box            | ✓ |
| Steering Wheel                 | ✓ | Sunvisor             | ✓ |
| Seat Upholstery                | ✓ | Manual Seat Movement | ✓ |
| Seat Belts                     | ✓ | Head Rest            | ✓ |
| Door Controls And Trim         | ✓ | Grab Handle          | ✓ |
| Carpet                         | ✓ | Headliner            | ✓ |
| Rear View Mirror               | ✓ | Toolkit              | ✓ |

## Tyres

### Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



### Life remaining

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<85%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE