



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2018 VOLKSWAGEN GOLF

R | 133,821 KM

VIN: WVWGP2AU5JW200605

## Car highlights



### Supercharger/turbocharger

This car has a Supercharger/turbocharger



### Cruise control

Cruise control to drive with ease & comfort



### Apple play

Enjoy your drive with apple play



### Amazing Comfort

Power driver seat, Memory Seats & more

## Basic Details

 Kilometers	<b>133821</b>	 Specs	<b>Yes</b>
 Engine	<b>2.0L</b>	 Option Type	<b>Fully Loaded</b>
 Transmission	<b>Automatic</b>	 Drive	<b>All Wheel Drive</b>
 Body Type	<b>HATCHBACK</b>	 Fuel	<b>Petrol</b>
 Wheel Type	<b>Alloy Wheels</b>	 Exterior Color	<b>Exterior Color Grey</b>
 Interior Trim	<b>Leather Trim</b>	 Number of Airbags	<b>7 Airbags</b>
 Seating Capacity	<b>5 Seats</b>	 Number of keys	<b>1 Keys</b>
 VIN number	<b>WVWGP2AU5JW200605</b>		

## Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 <b>Comfort &amp; Convenience</b>	
Climate Control AC	
Memory Seats	
Steering Mounted Audio Controls	
Ventilated Seat	
Central Armrest	
Cruise Control	
Rear Armrest with cupholder	
Power Folding Mirrors	
Rear Defogger	
Automatic Headlights	



## Performance

Paddle Shift



## Safety & Security

Parking Sensors Front



Parking Sensors Rear



Auto Park Assist



Reverse Camera



Blind Spot Monitor



Traction Control



Airbag Curtain Shield



Airbag Knees



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



## Exteriors

Running Lights



Rear Bumper Spoiler



LED Headlights



## Entertainment

Bluetooth Player



Apple Play



Android Auto Play



Infotainment System



USB player



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



## 🚗 Exterior

Doors condition

Front left door



Handle: Paint Chip-off < 5mm

Front right door



Handle: Paint Chip-off < 5mm

Rear left door



Panel: Paint Chip-off < 5mm, Dent < 30mm

Rear right door



Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm

Fenders Condition

Left Fender



Condition: Paint Chip-off < 5mm

Right Fender



Right Fender: Dent < 30mm, Paint Chip-off < 5mm

Quarter Panels Condition

Left Quarter Panel



Condition: Scratch < 50mm

Right Quarter Panel



Condition: Scratch < 50mm, Paint Chip-off < 5mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood



Bonnet: Paint Chip-off < 5mm

Trunk Condition

Trunk



Door Trim: Light Scuffing < 50mm

Trunk conditon

Trunk



Roof Condition

Roof



## Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Low Visual Dent < 50mm	
		Left C Pillar	

## Running Board Condition

Left Running Board		Right Running Board	
Rear Left Sill Trim: Scratch < 80mm		Condition: Light Scuffing < 80mm	

## Sunroof Glass Condition (If Equipped)

Sun Roof Glass	
----------------	--

## Windshield Condition

Front Windshield		Rear Windshield	
Beading: Mouldings Crack/ Fair Use Wear < 50mm			

## Structural Assessment

Chassis Condition		Radiator Support	
Apron		Boot Floor	
Firewall Condition		Cowl Top	
Head Light Support Condition			
Cowl Top			
Cowl Top			

## Rear View Mirror Condition

Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror		Right Hand Side Mirror	

## Alloy Wheel/ Rim

Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Rim: Alloy Edge/ Scuff < 80mm		Rim: Alloy Edge/ Scuff < 80mm	

Spare Alloy/ Rim Condition			
Wheel cover		Antenna	
Grill Condition		Monogram	
Light Scuffing < 50mm			
Window Glass		Wiper	
Panel Condition			
Rear Trunk Panel			

## Engine & Transmission

Engine			
Engine Body		Engine Performance	
Engine Oil (Condition & Level)		Exhaust System	
Turbocharger/ Supercharger		Radiator Condition	
Radiator Coolant			
Battery			
Battery Terminal & Tightness			
Fuel System			
Fuel Tank			
Transmission Operation			
Gear Shifting		Gear shift	
Drive Axle		4*4 Condition (If Applicable)	
Transmission Fluid			

## Steering, Suspension & Brakes

Steering			
Steering wheel			
Brake System			
Parking Brake		Brake Master Cylinder	
Brake Disc & Brake Pad		Brake Fluid	

Pedals 

Suspension

Shock Absorbers 

---

## Electricals, Controls & Lights

Keys

Master Key 

Button Faded

Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

Airbags 

Controls 

Cruise Control 

Infotainment Display 

Engine Sensors 

OBD Connector 

Radar (If Equipped) 

Music System 

Sunroof Operation

Sunroof 

Curtain: Curtain Fair Use Wear

Camera 

Lights

Headlight 

Interior Lights 

Tail Light Cluster

Left Tail Lamp: Light Scuffing < 50mm 

Turn Signal Lights 

Daylight Running Lights 

License Plate Light 

Air Conditioning

AC Cooling 

AC Switch 

AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch Crack	!		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓	Seat Heaters	✓
Memory Seats	✓		

## **Interiors & Luggage**

Dashboard And Instrument Panel		Central Console	
Dashboard And Instrument Panel: Light Scuffing/Crack	!	Box: Minor Disfiguration	!
Cup Holder	✓	Glove Box	
		Glove Box: Minor Scuffing/Crack/Fair Use Wear	!
Steering Wheel	!	Sunvisor	✓
Steering Wheel Fair Use Wear			
Seat Upholstery		Manual Seat Movement	✓
Driver Seat: Minor Leather/ Fabric Fair Use Wear/ Tears	!		
Seat Belts	✓	Head Rest	✓
Door Controls And Trim		Grab Handle	✓
Front Left Door: Light Scuffing	!		
Carpet		Headliner	✓
Front Left Floor Mat: Smudge/Burn/Crack	!		
Rear View Mirror	✓	Toolkit	✓

## **Tyres**

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓

Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre	<75%	LHS Rear Tyre	<85%
RHS Front Tyre	<75%	RHS Rear Tyre	<75%
Spare Tyre	<45%		



**A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE