



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 NISSAN KICKS

SV | 51,840 KM

VIN: 3N1CP5C98KL466252

Car highlights



Great Parking Assistance

Reverse Camera



Navigation

Navigation to drive with ease & comfort



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	51840	 Specs	Yes
 Engine	1.6L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Black
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	3N1CP5C98KL466252		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors	
Fog Light Front	
 Safety & Security	
Navigation	
Traction Control	
ABS	
Roof Rails	
Reverse Camera	
Airbag Driver Front	
Central Locking	

Child Safety Locking



Comfort & Convenience

Steering Mounted Audio
Controls



Rear Defogger



Automatic Headlights



Entertainment

Bluetooth Player



Infotainment System



USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Handle: Paint Chip-off < 5mm

Front right door



Handle: Paint Chip-off < 5mm

Rear left door



Panel: Dent < 30mm, Paint Chip-off < 5mm

Rear right door



Panel: Low Visual Dent < 30mm, Paint Chip-off < 5mm

Fenders Condition

Left Fender



Condition: Scratch < 50mm

Right Fender



Right Fender: Paint Chip-off < 5mm, Dent < 30mm

Quarter Panels Condition

Left Quarter Panel



Condition: Dent < 30mm

Right Quarter Panel



Condition: Dent < 30mm

Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm, Chip < 8mm

Hood Condition

Hood



Bonnet: Paint Chip-off < 5mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
Right B to C Pillar Beading		Left C Pillar	
Running Board Condition			
Left Running Board		Right Running Board	
Windshield Condition			
Front Windshield		Rear Windshield	
Structural Assessment			
Chassis Condition		Radiator Support	
Apron		Boot Floor	
Firewall Condition		Cowl Top	
Head Light Support Condition			
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Right Side Mirror		Right Hand Side Mirror	
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Spare Alloy/ Rim Condition			
Wheel cover		Antenna	
Grill Condition			
Light Scuffing < 50mm		Monogram	
Window Glass		Wiper	
Panel Condition			

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard		
Instrument Panel	✓	
Airbags		
Airbags	✓	
Controls	✓	Infotainment Display
Engine Sensors	✓	OBD Connector
Navigation System	✓	Music System
Camera	✓	
Lights		
Headlight	✓	Interior Lights
Tail Light Cluster	✓	License Plate Light
Fog Lights	✓	
Air Conditioning		
AC Cooling	✓	AC Switch
AC System Leaks	✓	Center AC Vent
Front Right AC Vent	✓	Heater
USB Charging Port	✓	Power/ Manual Windows

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	
		Left: Sunvisor LHS Minor Crack/Fair Use	!
		Wear, Sunvisor RHS Minor Crack/Damage	
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓

Door Controls And Trim



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<75%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<90%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE