



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2017 KIA SPORTAGE

GT LINE | 97,432 KM

VIN: U5YPK81C6HL112945

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat, Ventilated Seats

Basic Details

 Kilometers	97432	 Specs	Yes
 Engine	2.4L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	U5YPK81C6HL112945		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Climate Control AC	
Rear Armrest with cupholder	
Ventilated Seat	
Rear Defogger	
Automatic Headlights	
Cruise Control	
Steering Mounted Audio Controls	
Power Tailgate/ Power Trunk	
Central Armrest	



Exteriors

Fog Light Front	✓	Roof Rails	✓
Running Lights	✓	Rear Bumper Spoiler	✓
Halogen Headlights	✓		



Safety & Security

Navigation	✓	Parking Sensors Front	✓
Parking Sensors Rear	✓	Auto Park Assist	✓
Reverse Camera	✓	Traction Control	✓
Airbag Curtain Shield	✓	Airbag Driver Front	✓
ABS	✓	Central Locking	✓
Child Safety Locking	✓		



Performance

Paddle Shift	✓	Hill Descent Control	✓
Differential Locks	✓		



Entertainment

Bluetooth Player	✓	USB Charging Port	✓
Infotainment System	✓	USB player	✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Inner Frame: minor imperfection

Front right door



Handle: Light Scuffing < 50mm

Rear left door



Handle: Light Scuffing < 50mm

Rear right door



Panel: Paint Chip-off < 5mm, Light Scuffing <

50mm, Low Visual Dent < 30mm

Fenders Condition

Left Fender



Right Fender



Condition: Low Visual Dent < 30mm, Light

Scuffing < 50mm

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Chip<5mm, Light Scuffing<50mm

Front Bumper Condition

Front Bumper



Condition: Fair Use Wear

Rear Bumper Condition

Rear Bumper



Hood Condition

Hood



Bonnet: Paint Chip-off < 5mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	
Right A to B Pillar		Left B Pillar	
Left B Pillar Trim		Left B to C Pillar Beading	
Right C Pillar Trim		Right B to C Pillar	
		Paint Defect	
Right B to C Pillar Beading		Left C Pillar	
Running Board Condition			
Left Running Board		Right Running Board	
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass			
Windshield Condition			
Front Windshield		Rear Windshield	
Structural Assessment			
Chassis Condition		Radiator Support	
Apron		Boot Floor	
Firewall Condition		Cowl Top	
Head Light Support Condition			
Cowl Top			
Cowl Top			
Rear View Mirror Condition			
Left Hand Side Mirror		Left Side Mirror	
Condition: Mirror Adjustment Issue			
Right Side Mirror		Right Hand Side Mirror	
Alloy Wheel/ Rim			
Left Front Alloy/ Rim		Left Rear Alloy/ Rim	
Right Front Alloy/ Rim		Right Rear Alloy/ Rim	
Spare Alloy/ Rim Condition			
Wheel cover		Antenna	

Grill Condition
Scuffing > 50mm



Monogram



Window Glass



Wiper



Front Left: Crack/ Fair Use Wear

Panel Condition
Rear Trunk Panel
Scratch < 50mm



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Cap



Fuel Tank



Transmission Operation

Gear Shifting



Gear shift



Drive Axle



4*4 Condition (If Applicable)



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key  Spare Key(s) 

Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

Airbags 

Controls  Cruise Control 

Infotainment Display  Engine Sensors 

OBD Connector  Radar (If Equipped) 

Navigation System  Music System 

Sunroof Operation 

Sunroof 

Lights 

Headlight  Interior Lights 

Tail Light Cluster  Turn Signal Lights 

Left Tail Lamp: Crack / Fair Use Wear < 5mm  License Plate Light 

Daylight Running Lights  Turn Signal Lights 

Fog Lights  License Plate Light 

Air Conditioning 

AC Cooling  AC Switch 

AC System Leaks  Center AC Vent 

Front Right AC Vent  Heater 

Rear Blower Switch 

Parking Sensors  Rear Defogger 

USB Charging Port



Power/ Manual Windows



Seat Heaters



Interiors & Luggage

Dashboard And Instrument Panel



Central Console



Cup Holder



Glove Box



Steering Wheel



Sunvisor



Seat Upholstery



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<85%

LHS Rear Tyre

<90%

RHS Front Tyre

<75%

RHS Rear Tyre

<90%

Spare Tyre

<75%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE