



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 FORD EXPLORER

LIMITED | 145,666 KM

Car highlights



Panoramic Roof

This car has a panoramic roof



Cruise control

Cruise control to drive with ease & comfort



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat, Memory Seats & more

Basic Details

 Kilometers	145666	 Specs	Yes
 Engine	3.5L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	All Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Leather Trim	 Number of Airbags	6 Airbags
 Seating Capacity	7 Seats	 Number of keys	3 Keys
 VIN number	1FM5K8F81GGA68140		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Climate Control AC	
Memory Seats	
Steering Mounted Audio Controls	
Ventilated Seat	
Rear Defogger	
Cruise Control	
Rear Armrest with cupholder	
Power Folding Mirrors	
Power Tailgate/ Power Trunk	
Central Armrest	

Remote Engine Start		Automatic Headlights	
Steering Column Adjuster			
Externiors			
Fog Light Front		Roof Rails	
Running Lights		Rear Bumper Spoiler	
HID Headlights			
Safety & Security			
Navigation		Parking Sensors Front	
Parking Sensors Rear		Reverse Camera	
Blind Spot Monitor		Airbag Curtain Shield	
ABS		Central Locking	
Child Safety Locking			
Performance			
Paddle Shift		Hill Descent Control	
Entertainment			
Rear Seat Entertainment		Bluetooth Player	
Infotainment System		USB player	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door



Handle: Paint Chip-off < 5mm

Rear left door



Rear right door



Panel: Low Visual Dent < 30mm, Light

Scuffing < 50mm, Paint Chip-off < 5mm

Fenders Condition

Left Fender



Condition: Scratch < 50mm, Dent < 30mm

Right Fender



Right Fender: Dent < 30mm, Paint Chip-off < 5mm

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Scratch < 50mm, Dent < 30mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm, Chip < 8mm

Hood Condition

Hood



Bonnet: Low Visibility Dent < 30mm, Light

Scuffing < 50mm, Paint Chip-off < 5mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof		
Pillars Condition		
Left A Pillar		Right A Pillar
Left A to B Pillar Beading		Right A to B Pillar Beading
Right A to B Pillar		Left B Pillar
Left B Pillar Trim		Left B to C Pillar Beading
Right C Pillar Trim		Right B to C Pillar
Right B to C Pillar Beading		Left C Pillar
Running Board Condition		
Left Running Board		Right Running Board Front Right Sill Trim: Light Scuffing < 80mm
Sunroof Glass Condition (If Equipped)		
Sun Roof Glass		
Windshield Condition		
Front Windshield		
Beading: Mouldings Crack/ Fair Use Wear < 50mm		Rear Windshield
Structural Assessment		
Chassis Condition		Radiator Support
Apron		Boot Floor
Firewall Condition		Cowl Top
Head Light Support Condition		
Cowl Top		
Cowl Top		
Rear View Mirror Condition		
Left Hand Side Mirror		Left Side Mirror
Right Side Mirror		
Alloy Wheel/ Rim		
Left Front Alloy/ Rim		Left Rear Alloy/ Rim
Right Front Alloy/ Rim		Right Rear Alloy/ Rim

Spare Alloy/ Rim Condition



Wheel cover



Antenna



Grill Condition



Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Gear shift



Drive Axle



4*4 Condition (If Applicable)



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Radar (If Equipped)



Navigation System

Condition: Available - SD Card Missing



Music System



Sunroof Operation

Sunroof



Lights

Headlight



Interior Lights



Tail Light Cluster



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater



Rear Blower Switch



Rear Left AC Vent



Parking Sensors	✓	Rear Defogger	✓
USB Charging Port	✓	Rear Entertainment	✓
Power/ Manual Windows	✓	Seat Heaters	✓
Memory Seats	✓		

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	!	Sunvisor	✓
Steering Wheel Fair Use Wear			
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	!	Grab Handle	✓
Rear Right Door: Light Scuffing			
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<75%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<75%
Spare Tyre	<45%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE