



RTA Standards

RTA-certified structural integrity is good, any damages have been repaired to RTA standards and maybe mentioned in the RTA reports.

1 Months Warranty

Enjoy peace of mind for your car purchase

Car has been refurbished

We guarantee that structural integrity is good for all the value cars, any damages have been repaired to RTA standards.





2016 TOYOTA YARIS

SE | 159,395 KM

VIN: MHFBT9F30G6082541

Car highlights



Bluetooth

Enjoy your drive with bluetooth



Amazing Comfort

Power driver seat



Airbag safety
















Airbag Driver Front



Central Arm Rest









Central arm rest for extra comfort

Basic Details

 Kilometers	159395	 Specs	Yes
 Engine	1.5L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	MHFBT9F30G6082541		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience				
Rear Defogger			Central Armrest	
 Entertainment				
Bluetooth Player			USB player	
 Exteriors				
Halogen Headlights				



Safety & Security

Airbag Driver Front



ABS



Central Locking



Child Safety Locking







150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
Handle: Paint Chip-off < 5mm		Handle: Paint Chip-off < 5mm	
Rear left door		Rear right door	
Handle: Paint Chip-off < 5mm		Handle: Scratch < 50mm	

Fenders Condition

Left Fender		Right Fender	
Condition: Scratch < 50mm, Dent < 30mm		Right Fender: Dent < 30mm, Dent > 30mm	


Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Dent < 30mm, Paint Chip-off < 5mm, Scratch < 50mm		Condition: Scratch < 50mm	


Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm	

Hood Condition

Hood	
Bonnet: Paint Chip-off < 5mm	

Trunk Condition

Trunk	
-------	---

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar	✓	Right A Pillar	✓
Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar Light Scuffing < 80mm	!
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board Condition: Scratch < 80mm	!	Right Running Board Condition: Light Scuffing < 80mm, Low Visual Dent < 50mm	!
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓	Right Hand Side Mirror	✓
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover Rear Right: Face/ Scuffs < 50mm	!
Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓

Wiper	✓	
Panel Condition		
Rear Trunk Panel	✓	

Engine & Transmission

Engine		
Engine Body	✓	Engine Performance ✓
Engine Oil (Condition & Level)	✓	Exhaust System ✓
Radiator Condition	✓	Radiator Coolant ✓
Battery		
Battery Terminal & Tightness	✓	
Fuel System		
Fuel Cap	✓	Fuel Tank ✓
Transmission Operation		
Gear Shifting	✓	Drive Axle ✓
Transmission Fluid	✓	

Steering, Suspension & Brakes

Steering		
Steering wheel	✓	
Brake System		
Parking Brake	✓	Brake Master Cylinder ✓
Brake Disc & Brake Pad	✓	Brake Fluid ✓
Pedals	✓	
Suspension		
Shock Absorbers	✓	

Electricals, Controls & Lights

Keys	
Master Key	✓

Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Infotainment Display	✓
Engine Sensors	✓	OBD Connector	✓
Music System	✓		
Lights			
Headlight			
Left: Light Scuff Marks < 50mm	!	Interior Lights	✓
Tail Light Cluster	✓	License Plate Light	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
USB Charging Port	✓	Power/ Manual Windows	✓

Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
Dashboard And Instrument Panel: Light Scuffing/Crack	!	Cigarette Lighter: Cigarette Lighter Missing	!
Glove Box	✓	Steering Wheel	
		Color Faded	!
Sunvisor	✓	Seat Upholstery	
		Passenger Seat: Minor Smudge/Cracks	!
Manual Seat Movement	✓	Seat Belts	✓
Head Rest	✓	Door Controls And Trim	✓

Grab Handle	✓	Carpet	ⓘ
		Front Left Floor Mat: Smudge/Burn/Crack	
Headliner	✓	Rear View Mirror	✓
Toolkit	✓		

Tyres

Tyres Condition			
Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Tyres Depth (Remaining)			
LHS Front Tyre	<65%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<75%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE