



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 FORD FIGO

TREND | 76,343 KM

VIN: MAJTKNGE2GTJ21679

Car highlights



Bluetooth

Enjoy your drive with bluetooth



Music System

Enjoy your drive with music system



Amazing Comfort

Power driver seat



Airbag safety

Airbag Driver Front

Basic Details

 Kilometers	76343	 Specs	Yes
 Engine	1.5L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	HATCHBACK	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Red
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	MAJTKNGE2GTJ21679		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors	
Fog Light Front	
 Safety & Security	
Traction Control	
ABS	
Child Safety Locking	
Airbag Driver Front	
Central Locking	



Comfort & Convenience

Rear Defogger



Steering Column Adjuster



Entertainment

Bluetooth Player



Infotainment System



USB player



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Light Scuffing<50mm

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm

Hood Condition

Hood



Bonnet: Light Scuffing < 50mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Condition: Repainted

Right A Pillar



Condition: Repainted

Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	!
Low Visual Dent < 50mm		Left C Pillar	✓
Right B to C Pillar Beading	✓	Running Board Condition	
Left Running Board	!	Right Running Board	!
Condition: minor imperfection		Condition: minor imperfection	
Windshield Condition		Front Windshield	
Condition: Passenger Side/Light		Rear Windshield	✓
Scuffing<50mm, Driver Side/Stone Chip	!	Condition: Passenger Side/Light	
Mark<5mm		Scuffing<50mm, Driver Side/Stone Chip	
Structural Assessment		Condition: Passenger Side/Light	
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	!
Beading: Crack/Fair Use Wear<50mm		Beading: Crack/Fair Use Wear<50mm	
Head Light Support Condition	✓	Cowl Top	
Cowl Top		Boot Floor	
Cowl Top	✓	Radiator Support	
Rear View Mirror Condition		Condition: Passenger Side/Light	
Left Hand Side Mirror	✓	Condition: Passenger Side/Light	
Right Side Mirror	✓	Scuffing<50mm, Driver Side/Stone Chip	
Alloy Wheel/ Rim		Condition: Passenger Side/Light	
Left Front Alloy/ Rim	!	Scuffing<50mm, Driver Side/Stone Chip	
Rim: Alloy Edge/ Scuff < 80mm		Condition: Passenger Side/Light	
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	!
Rim: Alloy Edge/ Scuff < 80mm		Right Rear Alloy/ Rim	
Spare Alloy/ Rim Condition	✓	Condition: Passenger Side/Light	
Antenna	✓	Scuffing<50mm, Driver Side/Stone Chip	
Grill Condition		Condition: Passenger Side/Light	
Light Scuffing < 50mm		Scuffing<50mm, Driver Side/Stone Chip	

Monogram



Window Glass



Wiper



Panel Condition

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key 

Door Locks

Child Safety Locking 

Dashboard

Instrument Panel 

Airbags

Airbags 

Controls  Infotainment Display 

Engine Sensors  OBD Connector 

Music System 

Lights

Headlight  Interior Lights 

Tail Light Cluster  License Plate Light 

Fog Lights 

Air Conditioning

AC Cooling  AC Switch 

AC System Leaks  Center AC Vent 

Front Right AC Vent  Heater 

USB Charging Port  Power/ Manual Windows 

Interiors & Luggage

Dashboard And Instrument Panel

Dashboard Upholstery: Minor Scuffing/ Crack/  Fair Use Wear

Cup Holder  Glove Box 

Steering Wheel  Sunvisor 

Central Console

Gear Shift Knob: Knob Fair Use Wear 

Color Faded

Seat Upholstery

Driver Seat: Minor Smudge/ Cracks



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim



Grab Handle



Carpet



Headliner



Front Left: Light Smudge/Disfiguration

Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE