



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

1 Months Warranty

This car comes with 1 months or 1,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2016 TOYOTA YARIS

SE / E | 113,462 KM

VIN: MR2KW9F30G1113456

Car highlights



Great Parking Assistance

Parking Sensors Rear



Bluetooth

Enjoy your drive with bluetooth



Music System

Enjoy your drive with music system



Amazing Comfort

Power driver seat

Basic Details

 Kilometers	113462	 Specs	Yes
 Engine	1.3L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	HATCHBACK	 Fuel	Petrol
 Wheel Type	Steel Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	MR2KW9F30G1113456		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Parking Sensors Rear		Airbag Driver Front	
ABS		Central Locking	
Child Safety Locking			
 Comfort & Convenience			
Rear Defogger			



Entertainment

Bluetooth Player



Infotainment System



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Moulding: Scratch < 50mm

Front right door



Handle: Light Scuffing < 50mm

Rear left door



Moulding: Paint Chip-off < 5mm

Rear right door



Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm

Fenders Condition

Left Fender



Condition: Scratch < 50mm, Dent > 30mm

Right Fender



Right Fender: Dent < 30mm, Scratch < 50mm

Quarter Panels Condition

Left Quarter Panel



Condition: Dent < 30mm, Scratch < 50mm

Right Quarter Panel



Condition: Dent < 30mm, Scratch < 50mm

Front Bumper Condition

Front Bumper



Condition: Fair Use Wear

Rear Bumper Condition

Rear Bumper



Rear Bumper: Light Scuffing < 80mm, Dent < 50mm, Chip< 8mm, Paint Faded

Hood Condition

Hood



Bonnet: Light Scuffing < 50mm, Low Visibility

Dent < 30mm, Paint Chip-off < 5mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading	!	Right A to B Pillar Beading	✓
Fair Use Wear/ Defiguration			
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	
Condition: Driver Side/Stone Chip Mark<5mm	!	Front Right Sill Trim: Low Visual Dent < 50mm, Light Scuffing < 80mm	!
Windshield Condition			
Front Windshield		Rear Windshield	✓
Condition: Driver Side/Stone Chip Mark<5mm	!		
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Firewall Condition	✓	Cowl Top	✓
Head Light Support Condition	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	!	Right Hand Side Mirror	✓
Body: Scratch < 50mm			
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Wheel cover	!	Antenna	✓
Front Right: Face/ Scuffs > 50mm			
Grill Condition	!	Monogram	✓
Scuffing > 50mm			
Window Glass	✓	Wiper	✓

Engine & Transmission

Engine

Engine Body  Engine Performance 

Engine Oil (Condition & Level)  Exhaust System 

Radiator Condition  Radiator Coolant 

Battery

Battery Terminal & Tightness 

Fuel System

Fuel Cap  Fuel Tank 

Transmission Operation

Gear Shifting  Drive Axle 

Transmission Fluid 

Steering, Suspension & Brakes

Steering

Steering wheel 

Brake System

Parking Brake  Brake Master Cylinder 

Brake Disc & Brake Pad  Brake Fluid 

Pedals 

Suspension

Shock Absorbers 

Electricals, Controls & Lights

Keys

Master Key 

Door Locks

Child Safety Locking 

Dashboard

Instrument Panel		
Airbags		
Airbags		
Controls		Cruise Control
Infotainment Display		Engine Sensors
OBD Connector		Navigation System
		Condition: Available - Google Map Only
Music System		Camera
Lights		
Headlight		Interior Lights
Right: Scuff Marks > 50mm		
Tail Light Cluster		License Plate Light
Air Conditioning		
AC Cooling		AC Switch
		Button(s) Faded
AC System Leaks		Center AC Vent
Front Right AC Vent		Heater
Parking Sensors		Rear Defogger
Power/ Manual Windows		

Interiors & Luggage

Dashboard And Instrument Panel		Central Console
		Cigarette Lighter: Cigarette Lighter Missing
Cup Holder		Glove Box
Steering Wheel		Sunvisor
Seat Upholstery		Manual Seat Movement
Rear Left Seat: Minor Cigarette Burn		
Seat Belts		Head Rest

Door Controls And Trim



Grab Handle



Carpet



Headliner



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<65%

LHS Rear Tyre

<75%

RHS Front Tyre

<65%

RHS Rear Tyre

<75%

Spare Tyre

<55%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE