



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2014 BMW 650i

GRAN COUPE | 96,232 KM

Car highlights



Power packed

Engine size of 4.4 Litres & 8.0 cylinders



Boosted Engine

This car has a Boosted Engine



Amazing Comfort
















Power driver seat



Tilt Steering wheel









Tilt steering wheel for extra comfort

Basic Details

 Kilometers	96232	 Specs	Yes
 Engine	4.4L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Rear Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Gold
 Interior Trim	Leather Trim	 Number of Airbags	10 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	WBA6B2105ED145224		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience				
Sunroof			Cruise Control	
Memory Seats			Steering Mounted Audio Controls	
Heads up Display				
 Exteriors				
Fog Light Front				



Safety & Security

Parking Sensors Front



Navigation



Parking Sensors Rear



Reverse Camera



Side Camera



Entertainment

USB Charging Port



Infotainment System



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
-----------------	---	------------------	---

Rear left door		Rear right door	
----------------	---	-----------------	---

Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---


Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	---	---------------------	---

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm	

Hood Condition

Hood	
------	---

Trunk Condition

Trunk	
-------	---

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading		Right A to B Pillar Beading	
----------------------------	---	-----------------------------	---

Right A to B Pillar		Left B Pillar	
---------------------	---	---------------	---

Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield Windsheild Beadings < 50mm	!
Structural Assessment			
Chassis Condition	✓	Radiator Support	✓
Apron	✓	Boot Floor	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Wheel cover	✓	Antenna	✓
Grill Condition		Monogram	✓
Broken/ Fair Use Wear	!		
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Battery

Battery Terminal & Tightness



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Gear shift



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Pedals



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Door Locks

Child Safety Locking



Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓
Heads Up Display	✓	Infotainment Display	✓
Engine Sensors	✓	OBD Connector	✓
Radar (If Equipped)	✓	Navigation System	✓
Music System	✓		
Sunroof Operation			
Sunroof	✓		
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	✓	Fog Lights	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent Crack/Fair Use Wear	!
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓	Memory Seats	✓

Dashboard And Instrument Panel

Dashboard And Instrument Panel: Light
Scuffing/ Disfiguration/Melted



Central Console



Cup Holder



Glove Box



Steering Wheel



Sunvisor



Seat Upholstery

Driver Seat: Minor Leather/ Fabric Fair Use
Wear/ Tears



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim

Front Left Door: Fair Use Wear



Carpet



Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Rear Tyre



Life remaining

LHS Front Tyre

<55%

LHS Rear Tyre

<55%

RHS Front Tyre

<75%

RHS Rear Tyre

<55%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE