



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2015 VOLKSWAGEN JETTA

TREND | 133,715 KM

Car highlights



Cruise control

Cruise control to drive with ease & comfort



Music System

Enjoy your drive with music system



Amazing Comfort

Power driver seat



Airbag safety

Airbag Curtain, Airbag Driver Front

Basic Details

 Kilometers	133715	 Specs	Yes
 Engine	2.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color White
 Interior Trim	Fabric Trim	 Number of Airbags	6 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	WVWRV1AJ1FM200800		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Cruise Control		Rear Defogger	
Central Armrest		Steering Column Adjuster	
 Safety & Security			
Traction Control		Airbag Curtain Shield	
Airbag Driver Front		ABS	

Central Locking



Child Safety Locking



Exteriors

Halogen Headlights



Infotainment System



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed



🚗 Exterior

Doors condition

Front left door



Front right door



Panel: Paint Chip-off < 5mm

Rear left door



Rear right door



Panel: Low Visual Dent < 30mm, Light Scuffing < 50mm

Fenders Condition

Left Fender



Right Fender



Condition: Paint Chip-off

Right Fender: Paint Chip-off

Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Condition: Low Visual Dent, Light Scuffing

Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper



Rear Bumper: Chip< 8mm, Scuffing > 80mm

Hood Condition

Hood



Bonnet: Paint Chip-off < 5mm

Trunk Condition

Trunk



Trunk conditon

Trunk



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Spare Alloy/ Rim Condition	✓		
Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys		
Master Key	✓	Spare Key(s) Buttons Faded
Door Locks		!
Child Safety Locking	✓	
Dashboard		
Instrument Panel	✓	
Airbags		
Airbags	✓	
Controls	✓	Cruise Control
Infotainment Display	✓	OBD Connector

Music System			
Lights			
Headlight		Interior Lights	
Tail Light Cluster		License Plate Light	
Air Conditioning			
AC Cooling		AC Switch	
AC System Leaks		Center AC Vent	
Front Right AC Vent		Heater	
Rear Blower Switch		Heater Not Working	
Crack			
USB Charging Port		Power/ Manual Windows	
Rear: Dummy Cap Missing			

Interiors & Luggage

Dashboard And Instrument Panel		Central Console	
		Cigarette Lighter: Cigarette Lighter Missing	
Cup Holder		Glove Box	
		Glove Box: Minor Scuffing/Crack/Fair Use Wear	
Steering Wheel		Sunvisor	
Steering Wheel Fair Use Wear			
Seat Upholstery			
Driver Seat: Minor Smudge/ Cracks, Minor Fair Wear/Fade off		Manual Seat Movement	
Seat Belts		Head Rest	
Door Controls And Trim			
Front Left Door: Light Scuffing/ Disfiguration, Light Scuffing		Grab Handle	
Carpet		Headliner	
Rear View Mirror		Toolkit	

 **Tyres**

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Tyres Depth (Remaining)

LHS Front Tyre

<85%

LHS Rear Tyre

<45%

RHS Front Tyre

<85%

RHS Rear Tyre

<45%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE