



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





## 2017 RENAULT DUSTER

SE | 135,451 KM

VIN: VF1HSRCH1HA502393

### Car highlights



#### Cruise control

Cruise control to drive with ease & comfort



#### Running Lights

This car has a Running lights



#### Bluetooth
















Enjoy your drive with bluetooth



#### Amazing Comfort










Power driver seat

Basic Details

 Kilometers	135451	 Specs	Yes
 Engine	2.0L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	 Fuel	Petrol
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Grey
 Interior Trim	Leather Trim	 Number of Airbags	2 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	VF1HSRCH1HA502393		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Exteriors			
Fog Light Front		Roof Rails	
Running Lights		Halogen Headlights	
 Comfort & Convenience			
Cruise Control		Steering Mounted Audio Controls	
Rear Defogger			



## Entertainment

Bluetooth Player



Infotainment System



USB player



## Safety & Security

Airbag Driver Front



ABS



Central Locking



Child Safety Locking







# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

Front left door		Front right door	
Inner Frame: Scratch < 50mm		Panel: Light Scuffing < 50mm, Low Visibility	
		Dent < 30mm, Paint Chip-off < 5mm	
Rear left door		Rear right door	

### Fenders Condition

Left Fender		Right Fender	
Condition: Scratch < 50mm, Paint Chip-off < 5mm, Acid Marks/ Bird Dropping < 5mm		Right Fender: Paint Chip-off < 5mm, Scratch < 50mm	


### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
Condition: Dent < 30mm			

### Front Bumper Condition

Front Bumper	
--------------	---

### Rear Bumper Condition

Rear Bumper	
Rear Bumper: Light Scuffing < 80mm, Chip< 8mm	

### Hood Condition

Hood	
Bonnet: Light Scuffing < 50mm, Acid Marks/ Bird Dropping < 5mm	

### Trunk Condition

Trunk	
-------	---

### Trunk conditon

Trunk	
-------	---

### Roof Condition

Roof	
Roof Moulding Condition: Minor Rubber	

## Beading Fair Use Wear

### Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Beading Crack/ Tear > 5mm

Beading Crack/ Tear > 5mm

Right A to B Pillar



Left B Pillar



Left B Pillar Trim



Left B to C Pillar Beading



Right C Pillar Trim



Right B to C Pillar



Right B to C Pillar Beading



Left C Pillar



### Running Board Condition

Left Running Board



Right Running Board



Rear Left Sill Trim: Scratch < 80mm

Rear Right Sill Trim: Light Scuffing < 80mm

### Windshield Condition

Front Windshield

Condition: Driver Side/Stone Chip



Rear Windshield



Mark<5mm, Passenger Side/Stone Chip

Mark<8mm

### Structural Assessment

Chassis Condition



Radiator Support



Apron



Boot Floor



Firewall Condition



Cowl Top



Head Light Support Condition



Cowl Top

Cowl Top



### Rear View Mirror Condition

Left Hand Side Mirror



Left Side Mirror



Right Side Mirror



Right Hand Side Mirror



Alloy Wheel/ Rim

Left Front Alloy/ Rim



Left Rear Alloy/ Rim



Rim: Alloy Face/ Scuff < 50mm

Right Front Alloy/ Rim

Rim: Alloy Face/ Scuff < 50mm, Alloy Edge/



Right Rear Alloy/ Rim



Scuff < 80mm

Spare Alloy/ Rim Condition	✓		
Wheel Arch	✓	Wheel cover	✓
Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

## Engine & Transmission

Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Battery			
Battery Terminal & Tightness	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

## Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Pedals	✓		

Suspension

Shock Absorbers



## Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls



Cruise Control



Infotainment Display



Engine Sensors



OBD Connector



Music System



Lights

Headlight



Interior Lights



Tail Light Cluster

Rear Windscreen Brake Lamp: Cracked/ Fair Use Wear



Daylight Running Lights



License Plate Light



Fog Lights



Air Conditioning

AC Cooling

AC Temperature: Temp in Idling/Drive < 14°C



AC Switch



AC System Leaks



Center AC Vent



Front Right AC Vent



Heater

Heater Not Working



Rear Defogger

Extensive Wear Of Strip



USB Charging Port



Power/ Manual Windows







## Interiors & Luggage

### Dashboard And Instrument Panel

Dashboard And Instrument Panel: Light  
Scuffing/Crack



Central Console



Glove Box



Steering Wheel

Color Faded



Sunvisor



Seat Upholstery

Driver Seat: Minor Fair Wear/Fade off



Manual Seat Movement



Seat Belts



Head Rest



Door Controls And Trim

Front Right Door: Light Scuffing



Grab Handle



Carpet

Trunk Floor Carpet: Wear & Tear < 80mm



Headliner



Rear View Mirror



Toolkit



## Tyres

### Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



### Tyres Depth (Remaining)

LHS Front Tyre

<55%

LHS Rear Tyre

<75%

RHS Front Tyre

<55%

RHS Rear Tyre

<75%

Spare Tyre

<75%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE