



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2019 TOYOTA YARIS

SE | 100,337 KM

Car highlights

Fuel Efficient

Fuel efficient with 18.8 km/L



Great Parking Assistance

Reverse Camera, Parking Sensors Rear

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Bluetooth















Enjoy your drive with bluetooth



Amazing Comfort










Power driver seat

Basic Details

| | | | |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|-----------------------|
|  Kilometers | 100337 |  Specs | Yes |
|  Engine | 1.3L |  Option Type | Basic |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | HATCHBACK | Fuel Efficiency | 18.8 km/L mileage |
|  Wheel Type | Steel Wheels |  Exterior Color | Exterior Color Silver |
|  Interior Trim | Fabric Trim |  Number of Airbags | 2 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | MR2K19F30K1054142 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | |
|------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------|---------------------|--------------------------------------------------------------------------------------------------|
| <div> Safety & Security</div> | | | |
| Parking Sensors Rear | <div></div> | Reverse Camera | <div></div> |
| Traction Control | <div></div> | Airbag Driver Front | <div></div> |
| ABS | <div></div> | Central Locking | <div></div> |
| Child Safety Locking | <div></div> | | |
| <div><div></div>Comfort & Convenience</div> | | | |

| | | | |
|--------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|
| Rear Defogger |  | Central Armrest |  |
| Steering Column Adjuster |  | | |
|  Entertainment | | | |
| Bluetooth Player |  | Infotainment System |  |
| USB player |  | | |
|  Exteriors | | | |
| Halogen Headlights |  | | |





150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

| | | | |
|-----------------|-----------------------------------------------------------------------------------|--------------------------------------------------|-------------------------------------------------------------------------------------|
| Front left door |  | Front right door Panel: Light Scuffing < 50mm |  |
| Rear left door |  | Rear right door |  |

Fenders Condition

| | | | |
|-----------------------------------------------------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|
| Left Fender Condition: Low Visual Dent, Light Scuffing |  | Right Fender |  |
|-----------------------------------------------------------|-----------------------------------------------------------------------------------|--------------|-------------------------------------------------------------------------------------|

Quarter Panels Condition

| | | | |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|

Front Bumper Condition

| | |
|--------------|-------------------------------------------------------------------------------------|
| Front Bumper |  |
|--------------|-------------------------------------------------------------------------------------|

Rear Bumper Condition

| | |
|----------------------------------------------------------------|-------------------------------------------------------------------------------------|
| Rear Bumper Rear Bumper: Dent < 50mm, Light Scuffing < 80mm |  |
|----------------------------------------------------------------|-------------------------------------------------------------------------------------|

Hood Condition

| | |
|------|-------------------------------------------------------------------------------------|
| Hood |  |
|------|-------------------------------------------------------------------------------------|

Trunk Condition

| | |
|-------------------------------------------|-------------------------------------------------------------------------------------|
| Trunk Door Trim: Clips/ Screws Missing |  |
|-------------------------------------------|-------------------------------------------------------------------------------------|

Trunk conditon

| | |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

Roof Condition

| | |
|------|-------------------------------------------------------------------------------------|
| Roof |  |
|------|-------------------------------------------------------------------------------------|

Pillars Condition

| | | | |
|---------------|-------------------------------------------------------------------------------------|----------------|---------------------------------------------------------------------------------------|
| Left A Pillar |  | Right A Pillar |  |
|---------------|-------------------------------------------------------------------------------------|----------------|---------------------------------------------------------------------------------------|

| | | | |
|-----------------------------|---|------------------------------|---|
| Left A to B Pillar Beading | ✓ | Right A to B Pillar Beading | ✓ |
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Windshield Condition | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Cowl Top | ✓ | Head Light Support Condition | ✓ |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel cover | ✓ | Antenna | ✓ |
| Grill Condition | | Monogram | ✓ |
| Light Scuffing < 50mm | ! | | |
| Window Glass | ✓ | Wiper | ✓ |
| Panel Condition | | | |
| Rear Trunk Panel | ✓ | | |



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags








| | | | |
|----------------------|---|-----------------------|---|
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | OBD Connector | ✓ |
| Music System | ✓ | Camera | ✓ |
| Lights | | | |
| Headlight | ✓ | Interior Lights | ✓ |
| Tail Light Cluster | ✓ | License Plate Light | ✓ |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Parking Sensors | ✓ | Rear Defogger | ✓ |
| USB Charging Port | ✓ | Power/ Manual Windows | ✓ |

Interiors & Luggage

| | | | |
|--------------------------------|---|-------------------------------------------------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console Box: Minor Crack/Fair Use Wear/ Scuffing | ⚠ |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel | ✓ | Sunvisor | ✓ |
| Seat Upholstery | ✓ | Manual Seat Movement | ✓ |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ✓ | Grab Handle | ✓ |
| Carpet | ✓ | Headliner | ✓ |
| Rear View Mirror | ✓ | Toolkit | ✓ |

Tyres

Tyres Condition

| | | | |
|----------------------------|-----------------------------------------------------------------------------------|---------------------------|-------------------------------------------------------------------------------------|
| Left Hand Side Front Tyre |  | Left Hand Side Rear Tyre |  |
| Right Hand Side Front Tyre |  | Right Hand Side Rear Tyre |  |
| Spare Tyre |  | | |
| Crack/ Uneven Wear | | | |
| Life remaining | | | |
| LHS Front Tyre | <55% | LHS Rear Tyre | <55% |
| RHS Front Tyre | <45% | RHS Rear Tyre | <55% |
| Spare Tyre | <55% | | |



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE