



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2021 JEEP COMPASS**

**LONGITUDE | 72,076 KM**

## **Car highlights**



### **Four wheel drive**

This car has a Four wheel drive



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Bluetooth**















Enjoy your drive with bluetooth



### **Amazing Comfort**

Power driver seat

Basic Details

 Kilometers	72076	 Specs	Yes
 Engine	2.4L	 Option Type	Basic
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	Fuel Efficiency	12.2 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Ashen
 Interior Trim	Fabric Trim	 Number of Airbags	4 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	3C4NJDBB5MT542213		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

<div> <b>Comfort &amp; Convenience</b></div>				
Climate Control AC			Cruise Control	
Rear Armrest with cupholder			Steering Mounted Audio Controls	
Power Folding Mirrors			Rear Defogger	
Central Armrest			Automatic Headlights	
Steering Column Adjuster				



## Exteriors

Fog Light Front



Roof Rails



Running Lights



Rear Bumper Spoiler



Halogen Headlights



## Safety & Security

Parking Sensors Rear



Traction Control



Airbag Curtain Shield



Airbag Driver Front



ABS



Central Locking



Child Safety Locking



## Performance

Differential Locks



## Entertainment

Bluetooth Player



USB Charging Port



Infotainment System



USB player



# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition


Front left door		Front right door Panel: Low Visibility Dent < 30mm, Light Scuffing < 50mm	
-----------------	---	--	---

Rear left door		Rear right door	
----------------	---	-----------------	---

### Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---

### Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	---	---------------------	---

### Front Bumper Condition

Front Bumper			
--------------	---	--	--


### Rear Bumper Condition

Rear Bumper			
Rear Bumper: Dent < 50mm, Light Scuffing < 80mm			

### Hood Condition

Hood			
------	---	--	--

### Trunk Condition

Trunk			
Door Trim: Light Scuffing < 50mm			

### Trunk conditon

Trunk			
-------	---	--	--

### Roof Condition

Roof			
------	---	--	--

### Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Antenna	✓
Grill Condition	✓	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		



## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



### Fuel System

Fuel Tank



### Transmission Operation

Gear Shifting



Drive Axle



4\*4 Condition (If Applicable)



Transmission Fluid



## Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



### Suspension

Shock Absorbers



## Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



Controls	✓	Cruise Control	✓
Infotainment Display	✓	OBD Connector	✓
Music System	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	✓	Fog Lights	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		

## Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console Arm Rest: Minor Disfiguration, Fabric Tear	!
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim Front Left Door: Light Scuffing/ Disfiguration, Light Scuffing	!	Grab Handle	✓
Carpet	✓	Headliner	✓



Rear View Mirror



Toolkit

Jack Availability: Toe Hook Not Available



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<90%

LHS Rear Tyre

<75%

RHS Front Tyre

<90%

RHS Rear Tyre

<90%

Spare Tyre

<65%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE