



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2019 HONDA ACCORD**

**LX | 114,495 KM**

## **Car highlights**

### **Service History**

Service history available



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Bluetooth**















Enjoy your drive with bluetooth



### **Amazing Comfort**











Power driver seat


Basic Details

|  |                   |   |                     |
|--|-------------------|---|---------------------|
|  Kilometers       | 114495            |  Specs             | Yes                 |
|  Engine           | 1.5L              |  Option Type       | Basic               |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive   |
|  Body Type        | SEDAN             | Fuel Efficiency   | 15.2 km/L mileage   |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Blue |
|  Interior Trim    | Leather Trim      |  Number of Airbags | 8 Airbags           |
|  Seating Capacity | 5 Seats           |  Number of keys    | 2 Keys              |
|  VIN number     | 1HGCV161XKA602696 |   |                     |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|  |   |                                 |   |
|--|---|---------------------------------|---|
|  <b>Comfort &amp; Convenience</b> |   |                                 |   |
| Climate Control AC   |  | Cruise Control                  |  |
| Rear Armrest with cupholder  |  | Steering Mounted Audio Controls |  |
| Rear Defogger  |  | Central Armrest                 |  |
| Remote Engine Start  |  | Steering Column Adjuster        |  |
|  <b>Safety &amp; Security</b>     |   |                                 |   |

|  |   |                      |   |
|--|---|----------------------|---|
| Parking Sensors Rear   | ✓ | Traction Control     | ✓ |
| Airbag Curtain Shield  | ✓ | Airbag Knees         | ✓ |
| Airbag Driver Front  | ✓ | ABS                  | ✓ |
| Central Locking  | ✓ | Child Safety Locking | ✓ |
|  <b>Exteriors</b>     |   |                      |   |
| Running Lights   | ✓ | LED Headlights       | ✓ |
| Halogen Headlights   | ✓ |                      |   |
|  <b>Performance</b>   |   |                      |   |
| Hydraulic Suspensions  | ✓ |                      |   |
|  <b>Entertainment</b> |   |                      |   |
| Bluetooth Player   | ✓ | Infotainment System  | ✓ |
| USB player   | ✓ |                      |   |





# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

### Doors condition

|                 |   |   |   |
|-----------------|---|---|---|
| Front left door |  | Front right door<br>Handle: Light Scuffing < 50mm |  |
| Rear left door  |  | Rear right door<br>Handle: Scratch < 50mm         |  |

### Fenders Condition

|  |   |              |   |
|--|---|--------------|---|
| Left Fender<br>Condition: Light Scuffing |  | Right Fender |  |
|--|---|--------------|---|

### Quarter Panels Condition

|                    |  |   |  |
|--------------------|--|---|--|
| Left Quarter Panel |  | Right Quarter Panel<br>Condition: Low Visual Dent, Light Scuffing |  |
|--------------------|--|---|--|


### Front Bumper Condition

|              |   |
|--------------|---|
| Front Bumper |  |
|--------------|---|

### Rear Bumper Condition

|   |   |
|---|---|
| Rear Bumper                                     |   |
| Rear Bumper: Dent < 50mm, Light Scuffing < 80mm |  |

### Hood Condition

|                               |   |
|-------------------------------|---|
| Hood                          |   |
| Bonnet: Light Scuffing < 50mm |  |





### Trunk Condition

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

### Trunk conditon

|       |   |
|-------|---|
| Trunk |  |
|-------|---|

### Pillars Condition

|                            |   |                             |   |
|----------------------------|---|-----------------------------|---|
| Left A Pillar              |  | Right A Pillar              |  |
| Left A to B Pillar Beading |  | Right A to B Pillar Beading |  |

|                                   |   |                              |   |
|-----------------------------------|---|------------------------------|---|
| Right A to B Pillar               | ✓ | Left B Pillar                | ✓ |
| Left B Pillar Trim                | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim               | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading       | ✓ | Left C Pillar                | ✓ |
| Running Board Condition           |   |                              |   |
| Left Running Board                | ✓ | Right Running Board          | ✓ |
| Windshield Condition              |   |                              |   |
| Front Windshield                  | ✓ | Rear Windshield              | ✓ |
| Structural Assessment             |   |                              |   |
| Chassis Condition                 | ✓ | Apron                        | ✓ |
| Boot Floor                        | ✓ | Firewall Condition           | ✓ |
| Cowl Top                          |   | Head Light Support Condition | ✓ |
| Beading: Crack/Fair Use Wear<50mm | ! |                              |   |
| Cowl Top                          |   |                              |   |
| Cowl Top                          | ✓ |                              |   |
| Rear View Mirror Condition        |   |                              |   |
| Left Hand Side Mirror             | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror                 | ✓ |                              |   |
| Alloy Wheel/ Rim                  |   |                              |   |
| Left Front Alloy/ Rim             | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim            | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Spare Alloy/ Rim Condition        | ✓ |                              |   |
| Antenna                           | ✓ | Grill Condition              |   |
|                                   |   | Light Scuffing < 50mm        | ! |
| Monogram                          | ✓ | Window Glass                 | ✓ |
| Wiper                             | ✓ |                              |   |
| Panel Condition                   |   |                              |   |
| Rear Trunk Panel                  | ✓ |                              |   |



## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



### Fuel System

Fuel Tank



### Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



### Suspension

Shock Absorbers



## Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

|                      |   |                         |   |
|----------------------|---|-------------------------|---|
| Airbags              | ✓ |                         |   |
| Controls             | ✓ | Cruise Control          | ✓ |
| Infotainment Display | ✓ | OBD Connector           | ✓ |
| Music System         | ✓ |                         |   |
| Sunroof Operation    |   |                         |   |
| Sunroof              | ✓ |                         |   |
| Lights               |   |                         |   |
| Headlight            | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster   | ✓ | Daylight Running Lights | ✓ |
| License Plate Light  | ✓ |                         |   |
| Air Conditioning     |   |                         |   |
| AC Cooling           | ✓ | AC Switch               | ✓ |
| AC System Leaks      | ✓ | Center AC Vent          | ✓ |
| Front Right AC Vent  | ✓ | Heater                  | ✓ |
| Rear Blower Switch   | ✓ |                         |   |
| Parking Sensors      | ✓ | Rear Defogger           | ✓ |
| USB Charging Port    | ✓ | Power/ Manual Windows   | ✓ |

## Interiors & Luggage

|                                |   |                      |   |
|--------------------------------|---|----------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console      | ✓ |
| Cup Holder                     | ✓ | Glove Box            | ✓ |
| Steering Wheel                 | ✓ | Sunvisor             | ✓ |
| Seat Upholstery                | ✓ | Manual Seat Movement | ✓ |
| Seat Belts                     | ✓ | Head Rest            | ✓ |
| Door Controls And Trim         | ✓ | Grab Handle          | ✓ |



## Carpet

Front Left Floor Mat: Smudge/Burn/Crack



Headliner



Rear View Mirror



Toolkit



## Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<65%

LHS Rear Tyre

<65%

RHS Front Tyre

<65%

RHS Rear Tyre

<65%

Spare Tyre

<55%



## **A whole new world of cars**

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE