



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2021 BMW X2

SDRIVE 20i | 72,287 KM

VIN: WBAYH3A02M5T01967

Car highlights

Service History

Service history available



Great condition

Car has low imperfections

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K
applicable



Amazing Comfort

Power driver seat



Tilt Steering wheel

Tilt steering wheel for extra comfort

Basic Details

 Kilometers	72287	 Specs	Yes
 Engine	2L	 Option Type	Basic
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SUV	Fuel Efficiency	15.6 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	5 Seats	 Number of keys	1 Keys
 VIN number	WBAYH3A02M5T01967		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience	
Cruise Control 	Steering Mounted Audio Controls 
 Exteriors	
Fog Light Front 	
 Safety & Security	

Parking Sensors Front		Navigation	
Parking Sensors Rear		Reverse Camera	
 Entertainment			
USB Charging Port		Infotainment System	

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door Panel: Light Scuffing < 50mm	
Rear left door		Rear right door Panel: Light Scuffing < 50mm	

Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	---	---------------------	---

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
-------------	---

Hood Condition

Hood	
------	---

Trunk Condition

Trunk	
-------	---

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar		Right A Pillar	
Left A to B Pillar Beading		Right A to B Pillar Beading	

Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Wheel cover	✓	Antenna	✓
Grill Condition			
Light Scuffing < 50mm	!	Monogram	✓
Window Glass	✓	Wiper	✓
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission

Engine

Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Turbocharger/ Supercharger	✓	Radiator Condition	✓
Radiator Coolant	✓		
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
Transmission Fluid	✓		

Steering, Suspension & Brakes

Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Suspension			
Shock Absorbers	✓		

Electricals, Controls & Lights

Keys			
Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		
Controls	✓	Cruise Control	✓

Infotainment Display	✓	OBD Connector	✓
Navigation System	✓	Music System	✓
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	✓	Fog Lights	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓		



Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓



Tyres

Tyres Condition			
Left Hand Side Front Tyre		Left Hand Side Rear Tyre	
Right Hand Side Front Tyre		Right Hand Side Rear Tyre	
Life remaining			
LHS Front Tyre	<65%	LHS Rear Tyre	<75%
RHS Front Tyre	<65%	RHS Rear Tyre	<75%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE