



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2018 VOLKSWAGEN PASSAT

S | 112,744 KM

Car highlights



Amazing Comfort

Power driver seat

















Tilt Steering wheel

Tilt steering wheel for extra comfort

Convenience Fee Applicable








Extra fee ranging from AED 2.5K-4K applicable

Basic Details

| | | | |
|--|-------------------|---|----------------------|
|  Kilometers | 112744 |  Specs | Yes |
|  Engine | 2.5L |  Option Type | Basic |
|  Transmission | Automatic |  Drive | Front Wheel Drive |
|  Body Type | SEDAN | Fuel Efficiency | 10.6 km/L mileage |
|  Wheel Type | Steel Wheels |  Exterior Color | Exterior Color White |
|  Interior Trim | Fabric Trim |  Number of Airbags | 8 Airbags |
|  Seating Capacity | 5 Seats |  Number of keys | 2 Keys |
|  VIN number | WVWAR7A35JC020322 | | |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| | | | | |
|--|--|---|---------------------------------|---|
|  Comfort & Convenience | | | | |
| Cruise Control | |  | Steering Mounted Audio Controls |  |
|  Safety & Security | | | | |
| Parking Sensors Front | |  | Parking Sensors Rear |  |
|  Entertainment | | | | |

USB Charging Port



Infotainment System



150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door



Front right door

Panel: Light Scuffing < 50mm, Paint Defect



Rear left door



Rear right door

Panel: Light Scuffing < 50mm, Paint Defect



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



| | | | |
|-----------------------------|---|------------------------------|---|
| Right A to B Pillar | ✓ | Left B Pillar | ✓ |
| Left B Pillar Trim | ✓ | Left B to C Pillar Beading | ✓ |
| Right C Pillar Trim | ✓ | Right B to C Pillar | ✓ |
| Right B to C Pillar Beading | ✓ | Left C Pillar | ✓ |
| Running Board Condition | | | |
| Left Running Board | ✓ | Right Running Board | ✓ |
| Windshield Condition | | | |
| Front Windshield | ✓ | Rear Windshield | ✓ |
| Structural Assessment | | | |
| Chassis Condition | ✓ | Apron | ✓ |
| Boot Floor | ✓ | Firewall Condition | ✓ |
| Cowl Top | ✓ | Head Light Support Condition | ✓ |
| Cowl Top | | | |
| Cowl Top | ✓ | | |
| Rear View Mirror Condition | | | |
| Left Hand Side Mirror | ✓ | Left Side Mirror | ✓ |
| Right Side Mirror | ✓ | | |
| Alloy Wheel/ Rim | | | |
| Left Front Alloy/ Rim | ✓ | Left Rear Alloy/ Rim | ✓ |
| Right Front Alloy/ Rim | ✓ | Right Rear Alloy/ Rim | ✓ |
| Spare Alloy/ Rim Condition | ✓ | | |
| Wheel cover | ✓ | Antenna | ✓ |
| Grill Condition | | Monogram | ✓ |
| Light Scuffing < 50mm | ! | | |
| Window Glass | ✓ | Wiper | ✓ |
| Panel Condition | | | |
| Rear Trunk Panel | ✓ | | |



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags



| | | | |
|-----------------------|---|--|---|
| Controls | ✓ | Cruise Control | ✓ |
| Infotainment Display | ✓ | OBD Connector | ✓ |
| Music System | ✓ | | |
| Lights | | | |
| Headlight | ✓ | Interior Lights | |
| | | Front Map Reading Light: Centre Roof Light Cover Faded | ! |
| Tail Light Cluster | ✓ | Daylight Running Lights | ✓ |
| License Plate Light | ✓ | | |
| Air Conditioning | | | |
| AC Cooling | ✓ | AC Switch | ✓ |
| AC System Leaks | ✓ | Center AC Vent | ✓ |
| Front Right AC Vent | ✓ | Heater | ✓ |
| Rear Blower Switch | ✓ | | |
| Rear Defogger | ✓ | USB Charging Port | ✓ |
| Power/ Manual Windows | ✓ | | |



Interiors & Luggage

| | | | |
|--|---|----------------------|---|
| Dashboard And Instrument Panel | ! | Central Console | ✓ |
| Dashboard Upholstery: Minor Color Dullness | | | |
| Cup Holder | ✓ | Glove Box | ✓ |
| Steering Wheel | ! | Sunvisor | ✓ |
| Steering Wheel Fair Use Wear | | | |
| Seat Upholstery | ✓ | Manual Seat Movement | ✓ |
| Seat Belts | ✓ | Head Rest | ✓ |
| Door Controls And Trim | ✓ | Grab Handle | ✓ |
| Carpet | ✓ | Headliner | ✓ |

Rear View Mirror



Toolkit



Tyres

Tyres Condition

Left Hand Side Front Tyre



Left Hand Side Rear Tyre



Right Hand Side Front Tyre



Right Hand Side Rear Tyre



Spare Tyre



Life remaining

LHS Front Tyre

<55%

LHS Rear Tyre

<55%

RHS Front Tyre

<55%

RHS Rear Tyre

<55%

Spare Tyre

<65%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE