



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2023 HONDA ACCORD

EXL | 38,398 KM

Car highlights



Manufacturer warranty

Till 10/10/2028 or 1,00,000 km (Verified)



Adaptive cruise control

Adaptive cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat, Memory Seats

Basic Details

 Kilometers	38398	 Specs	Yes
 Engine	1.5L	 Option Type	Fully Loaded
 Transmission	Automatic	 Drive	Front Wheel Drive
 Body Type	SEDAN	Fuel Efficiency	15.2 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Blue
 Interior Trim	Leather Trim	 Number of Airbags	10 Airbags
 Seating Capacity	5 Seats	 Number of keys	2 Keys
 VIN number	1HGCV1696PA600111		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Safety & Security			
Adaptive cruise control		Lane Departure Warning System	
Navigation		Parking Sensors Front	
Parking Sensors Rear		Reverse Camera	
Collision Warning System		Side Camera	
Airbag Curtain Shield		Airbag Knees	

Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓
 Comfort & Convenience			
Climate Control AC	✓	Cruise Control	✓
Memory Seats	✓	Rear Armrest with cupholder	✓
Steering Mounted Audio Controls	✓	Power Folding Mirrors	✓
Rear Defogger	✓	Central Armrest	✓
Remote Engine Start	✓	Automatic Headlights	✓
Steering Column Adjuster	✓		
 Exteriors			
Running Lights	✓	LED Headlights	✓
 Entertainment			
Bluetooth Player	✓	Apple Play	✓
Android Auto Play	✓	USB Charging Port	✓
Infotainment System	✓	USB player	✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door		Front right door	
-----------------	---	------------------	---

Rear left door		Rear right door	
----------------	---	-----------------	---

Fenders Condition

Left Fender		Right Fender	
-------------	---	--------------	---

Quarter Panels Condition

Left Quarter Panel		Right Quarter Panel	
--------------------	---	---------------------	---

Front Bumper Condition

Front Bumper	
--------------	---

Rear Bumper Condition

Rear Bumper	
-------------	---

Hood Condition

Hood	
------	---

Trunk Condition

Trunk	
-------	---

Trunk conditon

Trunk	
-------	---

Roof Condition

Roof	
------	---

Pillars Condition

Left A Pillar		Right A Pillar	
---------------	---	----------------	---

Left A to B Pillar Beading		Right A to B Pillar Beading	
----------------------------	---	-----------------------------	---

Right A to B Pillar		Left B Pillar	
---------------------	---	---------------	---

Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Antenna	✓	Grill Condition Light Scuffing < 50mm	!
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	OBD Connector	✓
Radar (If Equipped)	✓	Navigation System	✓
Music System	✓		
Sunroof Operation			
Sunroof	✓		
Camera	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓		
Rear Defogger	✓	USB Charging Port	✓
Power/ Manual Windows	✓	Memory Seats	✓



Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓

Seat Belts	✓	Head Rest	✓
Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<65%	LHS Rear Tyre	<55%
RHS Front Tyre	<65%	RHS Rear Tyre	<55%
Spare Tyre	<75%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE