



### Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

### 3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





**2022 CHEVROLET CAPTIVA**

**PREMIER | 53,729 KM**

VIN: LZWADAGA6NB033347

## Car highlights



### **Great condition**

Car has low imperfections



### **Cruise control**

Cruise control to drive with ease & comfort

### **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K  
applicable



### **Apple play**

Enjoy your drive with apple play



### **Amazing Comfort**

Power driver seat

Basic Details

|                                                                                                    |                   |                                                                                                     |                       |
|----------------------------------------------------------------------------------------------------|-------------------|-----------------------------------------------------------------------------------------------------|-----------------------|
|  Kilometers       | 53729             |  Specs             | Yes                   |
|  Engine           | 1.5L              |  Option Type       | Fully Loaded          |
|  Transmission     | Automatic         |  Drive             | Front Wheel Drive     |
|  Body Type        | SUV               | Fuel Efficiency                                                                                     | 10.2 km/L mileage     |
|  Wheel Type       | Alloy Wheels      |  Exterior Color    | Exterior Color Silver |
|  Interior Trim    | Fabric Trim       |  Number of Airbags | 4 Airbags             |
|  Seating Capacity | 7 Seats           |  Number of keys    | 2 Keys                |
|  VIN number     | LZWADAGA6NB033347 |                                                                                                     |                       |

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

|                                                                                                                          |  |                                                                                                |                             |                                                                                                  |
|--------------------------------------------------------------------------------------------------------------------------|--|------------------------------------------------------------------------------------------------|-----------------------------|--------------------------------------------------------------------------------------------------|
| <div> Exteriors</div>                 |  |                                                                                                |                             |                                                                                                  |
| Fog Light Front                                                                                                          |  | <div></div> | Roof Rails                  | <div></div> |
| Running Lights                                                                                                           |  | <div></div> | Halogen Headlights          | <div></div> |
| <div> Comfort &amp; Convenience</div> |  |                                                                                                |                             |                                                                                                  |
| Cruise Control                                                                                                           |  | <div></div> | Rear Armrest with cupholder | <div></div> |
| Steering Mounted Audio Controls                                                                                          |  | <div></div> | Power Folding Mirrors       | <div></div> |

|                                                                                                                |   |                      |   |
|----------------------------------------------------------------------------------------------------------------|---|----------------------|---|
| Rear Defogger                                                                                                  | ✓ | Central Armrest      | ✓ |
| Steering Column Adjuster                                                                                       | ✓ |                      |   |
|  <b>Safety &amp; Security</b> |   |                      |   |
| Parking Sensors Front                                                                                          | ✓ | Parking Sensors Rear | ✓ |
| Reverse Camera                                                                                                 | ✓ | Traction Control     | ✓ |
| Airbag Driver Front                                                                                            | ✓ | ABS                  | ✓ |
| Central Locking                                                                                                | ✓ | Child Safety Locking | ✓ |
|  <b>Entertainment</b>         |   |                      |   |
| Bluetooth Player                                                                                               | ✓ | Apple Play           | ✓ |
| Android Auto Play                                                                                              | ✓ | USB Charging Port    | ✓ |
| Infotainment System                                                                                            | ✓ | USB player           | ✓ |

# 150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

## Exterior

Doors condition

|                 |                                                                                   |                  |                                                                                     |
|-----------------|-----------------------------------------------------------------------------------|------------------|-------------------------------------------------------------------------------------|
| Front left door |  | Front right door |  |
| Rear left door  |  | Rear right door  |  |

Fenders Condition

|             |                                                                                   |                               |                                                                                     |
|-------------|-----------------------------------------------------------------------------------|-------------------------------|-------------------------------------------------------------------------------------|
| Left Fender |  | Right Fender                  |  |
|             |                                                                                   | Right Fender: Low Visual Dent |                                                                                     |

Quarter Panels Condition

|                    |                                                                                   |                     |                                                                                     |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|
| Left Quarter Panel |  | Right Quarter Panel |  |
|--------------------|-----------------------------------------------------------------------------------|---------------------|-------------------------------------------------------------------------------------|

Front Bumper Condition

|              |                                                                                     |
|--------------|-------------------------------------------------------------------------------------|
| Front Bumper |  |
|--------------|-------------------------------------------------------------------------------------|

Rear Bumper Condition

|             |                                                                                     |
|-------------|-------------------------------------------------------------------------------------|
| Rear Bumper |  |
|-------------|-------------------------------------------------------------------------------------|

Hood Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Hood |  |
|------|-------------------------------------------------------------------------------------|

Trunk Condition

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

Trunk conditon

|       |                                                                                     |
|-------|-------------------------------------------------------------------------------------|
| Trunk |  |
|-------|-------------------------------------------------------------------------------------|

Roof Condition

|      |                                                                                     |
|------|-------------------------------------------------------------------------------------|
| Roof |  |
|------|-------------------------------------------------------------------------------------|

Pillars Condition

|                            |                                                                                     |                             |                                                                                       |
|----------------------------|-------------------------------------------------------------------------------------|-----------------------------|---------------------------------------------------------------------------------------|
| Left A Pillar              |  | Right A Pillar              |  |
| Left A to B Pillar Beading |  | Right A to B Pillar Beading |  |
| Right A to B Pillar        |  | Left B Pillar               |  |

|                                       |   |                              |   |
|---------------------------------------|---|------------------------------|---|
| Left B Pillar Trim                    | ✓ | Left B to C Pillar Beading   | ✓ |
| Right C Pillar Trim                   | ✓ | Right B to C Pillar          | ✓ |
| Right B to C Pillar Beading           | ✓ | Left C Pillar                | ✓ |
| Running Board Condition               |   |                              |   |
| Left Running Board                    | ✓ | Right Running Board          | ✓ |
| Sunroof Glass Condition (If Equipped) |   |                              |   |
| Sun Roof Glass                        | ✓ |                              |   |
| Windshield Condition                  |   |                              |   |
| Front Windshield                      | ✓ | Rear Windshield              | ✓ |
| Structural Assessment                 |   |                              |   |
| Chassis Condition                     | ✓ | Apron                        | ✓ |
| Boot Floor                            | ✓ | Firewall Condition           | ✓ |
| Cowl Top                              | ✓ | Head Light Support Condition | ✓ |
| Cowl Top                              |   |                              |   |
| Cowl Top                              | ✓ |                              |   |
| Rear View Mirror Condition            |   |                              |   |
| Left Hand Side Mirror                 | ✓ | Left Side Mirror             | ✓ |
| Right Side Mirror                     | ✓ |                              |   |
| Alloy Wheel/ Rim                      |   |                              |   |
| Left Front Alloy/ Rim                 | ✓ | Left Rear Alloy/ Rim         | ✓ |
| Right Front Alloy/ Rim                | ✓ | Right Rear Alloy/ Rim        | ✓ |
| Spare Alloy/ Rim Condition            | ✓ |                              |   |
| Antenna                               | ✓ | Grill Condition              | ✓ |
| Monogram                              | ✓ | Window Glass                 | ✓ |
| Wiper                                 | ✓ |                              |   |
| Panel Condition                       |   |                              |   |
| Rear Trunk Panel                      | ✓ |                              |   |



## Engine & Transmission

### Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Turbocharger/ Supercharger



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



Transmission Fluid



## Steering, Suspension & Brakes

### Steering

Steering wheel



### Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



### Suspension

Shock Absorbers



## Electricals, Controls & Lights

### Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

|                       |   |                         |   |
|-----------------------|---|-------------------------|---|
| Airbags               | ✓ |                         |   |
| Controls              | ✓ | Cruise Control          | ✓ |
| Infotainment Display  | ✓ | OBD Connector           | ✓ |
| Music System          | ✓ |                         |   |
| Sunroof Operation     |   |                         |   |
| Sunroof               | ✓ |                         |   |
| Camera                | ✓ |                         |   |
| Lights                |   |                         |   |
| Headlight             | ✓ | Interior Lights         | ✓ |
| Tail Light Cluster    | ✓ | Daylight Running Lights | ✓ |
| License Plate Light   | ✓ | Fog Lights              | ✓ |
| Air Conditioning      |   |                         |   |
| AC Cooling            | ✓ | AC Switch               | ✓ |
| AC System Leaks       | ✓ | Center AC Vent          | ✓ |
| Front Right AC Vent   | ✓ | Heater                  | ✓ |
| Rear Blower Switch    | ✓ |                         |   |
| Rear Defogger         | ✓ | USB Charging Port       | ✓ |
| Power/ Manual Windows | ✓ |                         |   |

## Interiors & Luggage

|                                |   |                      |   |
|--------------------------------|---|----------------------|---|
| Dashboard And Instrument Panel | ✓ | Central Console      | ✓ |
| Cup Holder                     | ✓ | Glove Box            | ✓ |
| Steering Wheel                 | ✓ | Sunvisor             | ✓ |
| Seat Upholstery                | ✓ | Manual Seat Movement | ✓ |
| Seat Belts                     | ✓ | Head Rest            | ✓ |

|                                         |                                                                                   |             |                                                                                     |
|-----------------------------------------|-----------------------------------------------------------------------------------|-------------|-------------------------------------------------------------------------------------|
| Door Controls And Trim                  |   | Grab Handle |   |
| Carpet                                  |  | Headliner   |  |
| Front Left Floor Mat: Smudge/Burn/Crack |                                                                                   |             |                                                                                     |
| Rear View Mirror                        |  | Toolkit     |  |

## Tyres

### Tyres Condition

|                            |                                                                                   |                           |                                                                                     |
|----------------------------|-----------------------------------------------------------------------------------|---------------------------|-------------------------------------------------------------------------------------|
| Left Hand Side Front Tyre  |  | Left Hand Side Rear Tyre  |  |
| Right Hand Side Front Tyre |  | Right Hand Side Rear Tyre |  |
| Spare Tyre                 |  |                           |                                                                                     |
| Life remaining             |                                                                                   |                           |                                                                                     |
| LHS Front Tyre             | <65%                                                                              | LHS Rear Tyre             | <65%                                                                                |
| RHS Front Tyre             | <55%                                                                              | RHS Rear Tyre             | <65%                                                                                |
| Spare Tyre                 | <65%                                                                              |                           |                                                                                     |



## A whole new world of cars

---

Auto New Market Block - 008, Ras Al Khor Industrial  
Area 3, Al Aweer, Dubai, UAE