



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



2016 MITSUBISHI PAJERO GLS MID | 112,239 KM

VIN: JMYLYV95WGJ719269

Car highlights

Service History

Service history available



Cruise control

Cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable



Bluetooth


Enjoy your drive with bluetooth



Amazing Comfort


Power driver seat

Basic Details



Specs and features


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.



Fog Light Front	✓	Roof Rails	✓
Running Lights	✓	Rear Bumper Spoiler	•
Halogen Headlights	✓	HID Headlights	✓
Safety & Security			
Parking Sensors Rear	✓	Reverse Camera	•
Traction Control	✓	Airbag Driver Front	V
ABS	✓	Central Locking	•
Child Safety Locking	✓		
Performance			
Differential Locks	✓		
ଐ≉ Entertainment			
Bluetooth Player	✓	Infotainment System	•
USB player			

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality



Left A to B Pillar Beading	✓	Right A to B Pillar Beading	✓
Right A to B Pillar	✓	Left B Pillar	✓
Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor	✓	Firewall Condition	✓
Cowl Top	✓	Head Light Support Condition	✓
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Wheel cover	✓	Grill Condition	✓
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			
Rear Trunk Panel	✓		

Engine & Transmission			
Engine			
Engine Body	✓	Engine Performance	✓
Engine Oil (Condition & Level)	✓	Exhaust System	✓
Radiator Condition	✓	Radiator Coolant	✓
Fuel System			
Fuel Tank	✓		
Transmission Operation			
Gear Shifting	✓	Drive Axle	✓
4*4 Condition (If Applicable)	✓	Transmission Fluid	✓
Steering, Suspension & Brakes			
Steering			
Steering wheel	✓		
Brake System			
Parking Brake	✓	Brake Master Cylinder	✓
Brake Disc & Brake Pad	✓	Brake Fluid	✓
Suspension			
Shock Absorbers	✓		
Electricals, Controls & Lights			
Keys			
Master Key	✓	Spare Key(s)	✓
Door Locks			
Child Safety Locking	✓		
Dashboard			
Instrument Panel	✓		
Airbags			
Airbags	✓		

Controls	~	Cruise Control	•
Infotainment Display	✓	OBD Connector	•
Music System	✓	Camera	•
Lights			
Headlight	~	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	~	Fog Lights	✓
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	~	Center AC Vent	✓
Front Right AC Vent	~	Heater	✓
Rear Blower Switch	✓	Rear Left AC Vent	✓
Parking Sensors	✓	Rear Defogger	•
USB Charging Port	•	Power/ Manual Windows	✓
USB Charging Port Interiors & Luggage	y	Power/ Manual Windows	•
		Power/ Manual Windows Central Console	✓
🖺 Interiors & Luggage	***		✓✓✓
Interiors & Luggage Dashboard And Instrument Panel	****	Central Console	
Interiors & Luggage Dashboard And Instrument Panel Cup Holder	>>>	Central Console Glove Box	...!
Interiors & Luggage Dashboard And Instrument Panel Cup Holder Steering Wheel	>>>>	Central Console Glove Box Sunvisor Manual Seat Movement	
Interiors & Luggage Dashboard And Instrument Panel Cup Holder Steering Wheel Seat Upholstery	>>>>	Central Console Glove Box Sunvisor Manual Seat Movement Driver Seat: Seat Rail Rusting	
Interiors & Luggage Dashboard And Instrument Panel Cup Holder Steering Wheel Seat Upholstery Seat Belts	>>>>	Central Console Glove Box Sunvisor Manual Seat Movement Driver Seat: Seat Rail Rusting Head Rest	
Interiors & Luggage Dashboard And Instrument Panel Cup Holder Steering Wheel Seat Upholstery Seat Belts Door Controls And Trim	>>>>>	Central Console Glove Box Sunvisor Manual Seat Movement Driver Seat: Seat Rail Rusting Head Rest Grab Handle	

Tyres Tyres Condition Left Hand Side Front Tyre Left Hand Side Rear Tyre Right Hand Side Front Tyre Right Hand Side Rear Tyre Spare Tyre Life remaining LHS Front Tyre <65% LHS Rear Tyre <65% RHS Front Tyre <65% RHS Rear Tyre <65% Spare Tyre <75%



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE