



#### **Exceeding RTA standards**

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

#### **3 Months Warranty**

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

#### Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.



## **2023 NISSAN KICKS**

SL | 4,986 KM

VIN: 3N1CP5CP1PL521825

# **Car highlights**



#### **Manufacturer warranty**

Till 09/06/2026 or 1,00,000 km (Verified)



#### **Cruise control**

Cruise control to drive with ease & comfort

## **Convenience Fee Applicable**

Extra fee ranging from AED 2.5K-4K applicable



## Apple play


Enjoy your drive with apple play



## **Amazing Comfort**

Power driver seat

## **Basic Details**



# **Specs and features**


The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

| Safety & Security    |          |                               |          |
|----------------------|----------|-------------------------------|----------|
| 360 degree Camera    | •        | Lane Departure Warning System | •        |
| Parking Sensors Rear | <b>✓</b> | Reverse Camera                | <b>✓</b> |
| Blind Spot Monitor   | <b>~</b> | Collision Warning System      | <b>✓</b> |
| Traction Control     | <b>✓</b> | Front Camera                  | •        |
| Side Camera          | <b>✓</b> | Airbag Curtain Shield         | <b>✓</b> |

| Airbag Driver Front             | <b>✓</b> | ABS                      | <b>~</b> |
|---------------------------------|----------|--------------------------|----------|
| Central Locking                 |          | Child Safety Locking     | <b>✓</b> |
| <b>©</b> Comfort & Convenience  |          |                          |          |
| Climate Control AC              | <b>✓</b> | Cruise Control           | <b>✓</b> |
| Steering Mounted Audio Controls | <b>✓</b> | Rear Defogger            | •        |
| Central Armrest                 | <b>✓</b> | Remote Engine Start      | <b>✓</b> |
| Automatic Headlights            | <b>✓</b> | Steering Column Adjuster | <b>✓</b> |
| Exteriors                       |          |                          |          |
| Fog Light Front                 | •        | Roof Rails               | <b>✓</b> |
| Running Lights                  | •        | LED Headlights           | <b>✓</b> |
| <b></b> Entertainment           |          |                          |          |
| Bluetooth Player                | •        | Apple Play               | <b>✓</b> |
| Android Auto Play               | •        | USB Charging Port        | <b>✓</b> |
|                                 |          | USB player               |          |

## **150 Point Detailed Inspection Report**

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality




| Left B Pillar Trim          | <b>✓</b> | Left B to C Pillar Beading   | <b>✓</b> |
|-----------------------------|----------|------------------------------|----------|
| Right C Pillar Trim         | <b>✓</b> | Right B to C Pillar          | <b>✓</b> |
| Right B to C Pillar Beading | <b>✓</b> | Left C Pillar                | <b>✓</b> |
| Running Board Condition     |          |                              |          |
| Left Running Board          | <b>✓</b> | Right Running Board          | <b>✓</b> |
| Windshield Condition        |          |                              |          |
| Front Windshield            | <b>✓</b> | Rear Windshield              | <b>✓</b> |
| Structural Assessment       |          |                              |          |
| Chassis Condition           | <b>✓</b> | Apron                        | <b>✓</b> |
| Boot Floor                  | <b>✓</b> | Firewall Condition           | <b>✓</b> |
| Cowl Top                    | <b>✓</b> | Head Light Support Condition | <b>✓</b> |
| Cowl Top                    |          |                              |          |
| Cowl Top                    | <b>✓</b> |                              |          |
| Rear View Mirror Condition  |          |                              |          |
| Left Hand Side Mirror       | <b>✓</b> | Left Side Mirror             | <b>✓</b> |
| Right Side Mirror           | <b>✓</b> |                              |          |
| Alloy Wheel/ Rim            |          |                              |          |
| Left Front Alloy/ Rim       | <b>✓</b> | Left Rear Alloy/ Rim         | <b>✓</b> |
| Right Front Alloy/ Rim      | <b>✓</b> | Right Rear Alloy/ Rim        | <b>✓</b> |
| Spare Alloy/ Rim Condition  | <b>✓</b> |                              |          |
|                             |          |                              |          |
| Wheel cover                 | <b>✓</b> | Antenna                      | <b>~</b> |
| Grill Condition             | <b>✓</b> | Monogram                     | <b>✓</b> |
| Window Glass                | <b>✓</b> | Wiper                        | <b>~</b> |
|                             |          | ·                            |          |
| Panel Condition             |          |                              |          |
| Rear Trunk Panel            | <b>✓</b> |                              |          |
|                             |          |                              |          |

# **Engine & Transmission**

Engine





| Tyres Condition            |          |                           |          |
|----------------------------|----------|---------------------------|----------|
| Left Hand Side Front Tyre  | <b>✓</b> | Left Hand Side Rear Tyre  | <b>✓</b> |
| Right Hand Side Front Tyre | <b>✓</b> | Right Hand Side Rear Tyre | •        |
| Spare Tyre                 | ~        |                           |          |
| Life remaining             |          |                           |          |
| LHS Front Tyre             | <75%     | LHS Rear Tyre             | <75%     |
| RHS Front Tyre             | <75%     | RHS Rear Tyre             | <75%     |
| Spare Tyre                 | <75%     |                           |          |
|                            |          |                           |          |



# A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial Area 3, Al Aweer, Dubai, UAE