



Exceeding RTA standards

We tick all the RTA mandated boxes, and several more. Every car is checked on 150+ points, and is guaranteed to pass the RTA test.

3 Months Warranty

This car comes with 3 months or 5,000 km warranty, whichever is earlier.

Car has been Refurbished

We spend ~AED 4,000 to refurbish & inspect the car to ensure only quality cars get listed.





2022 GMC YUKON

AT4 | 57,612 KM

VIN: 1GKS27KL9NR100009

Car highlights



Great condition

Car has low imperfections



Adaptive cruise control

Adaptive cruise control to drive with ease & comfort

Convenience Fee Applicable

Extra fee ranging from AED 2.5K-4K applicable



Apple play

Enjoy your drive with apple play



Amazing Comfort

Power driver seat, Memory Seats & more

Basic Details

 Kilometers	57612	 Specs	Yes
 Engine	6.2L	 Option Type	Semi Loaded
 Transmission	Automatic	 Drive	Four Wheel Drive
 Body Type	SUV	Fuel Efficiency	8.7 km/L mileage
 Wheel Type	Alloy Wheels	 Exterior Color	Exterior Color Red
 Interior Trim	Leather Trim	 Number of Airbags	8 Airbags
 Seating Capacity	7 Seats	 Number of keys	2 Keys
 VIN number	1GKS27KL9NR100009		

Specs and features

The specification listed was standard for this model when supplied new. The exact specification of this car may vary. Please refer to car images for more details.

 Comfort & Convenience			
Heads up Display		Climate Control AC	
Cruise Control		Memory Seats	
Steering Mounted Audio Controls		Power Folding Mirrors	
Ventilated Seat		Power Tailgate/ Power Trunk	
Cool Box		Rear Defogger	

Central Armrest	✓	Remote Engine Start	✓
Automatic Headlights	✓	Steering Column Adjuster	✓
 Safety & Security			
Adaptive cruise control	✓	360 degree Camera	✓
Lane Departure Warning System	✓	Parking Sensors Front	✓
Parking Sensors Rear	✓	Reverse Camera	✓
Blind Spot Monitor	✓	Collision Warning System	✓
Traction Control	✓	Front Camera	✓
Side Camera	✓	Airbag Curtain Shield	✓
Airbag Driver Front	✓	ABS	✓
Central Locking	✓	Child Safety Locking	✓
 Exteriors			
Fog Light Front	✓	Roof Rails	✓
Running Lights	✓	Rear Bumper Spoiler	✓
Trailer Hook / Coupling	✓	LED Headlights	✓
 Entertainment			
Rear Seat Entertainment	✓	Bluetooth Player	✓
Apple Play	✓	Android Auto Play	✓
USB Charging Port	✓	Infotainment System	✓
USB player	✓		
 Performance			
Hydraulic Suspensions	✓	Hill Descent Control	✓

150 Point Detailed Inspection Report

We're quite picky about the cars we procure, so the very fact that you found your car on our platform is a testament to its quality

Passed 

Exterior

Doors condition

Front left door



Front right door



Rear left door



Rear right door



Fenders Condition

Left Fender



Right Fender



Quarter Panels Condition

Left Quarter Panel



Right Quarter Panel



Front Bumper Condition

Front Bumper



Rear Bumper Condition

Rear Bumper

Rear Bumper: Light Scuffing < 80mm



Hood Condition

Hood



Trunk Condition

Trunk



Trunk conditon

Trunk



Roof Condition

Roof



Pillars Condition

Left A Pillar



Right A Pillar



Left A to B Pillar Beading



Right A to B Pillar Beading



Right A to B Pillar



Left B Pillar



Left B Pillar Trim	✓	Left B to C Pillar Beading	✓
Right C Pillar Trim	✓	Right B to C Pillar	✓
Right B to C Pillar Beading	✓	Left C Pillar	✓
Running Board Condition			
Left Running Board	✓	Right Running Board	✓
Sunroof Glass Condition (If Equipped)			
Sun Roof Glass	✓		
Windshield Condition			
Front Windshield	✓	Rear Windshield	✓
Structural Assessment			
Chassis Condition	✓	Apron	✓
Boot Floor		Firewall Condition	✓
Condition: Light Scuffing < 80mm	!	Head Light Support Condition	✓
Cowl Top	✓		
Cowl Top			
Cowl Top	✓		
Rear View Mirror Condition			
Left Hand Side Mirror	✓	Left Side Mirror	✓
Right Side Mirror	✓		
Alloy Wheel/ Rim			
Left Front Alloy/ Rim	✓	Left Rear Alloy/ Rim	✓
Right Front Alloy/ Rim	✓	Right Rear Alloy/ Rim	✓
Spare Alloy/ Rim Condition	✓		
Antenna	✓	Grill Condition	!
		Light Scuffing < 50mm	
Monogram	✓	Window Glass	✓
Wiper	✓		
Panel Condition			

Rear Trunk Panel



Engine & Transmission

Engine

Engine Body



Engine Performance



Engine Oil (Condition & Level)



Exhaust System



Radiator Condition



Radiator Coolant



Fuel System

Fuel Tank



Transmission Operation

Gear Shifting



Drive Axle



4*4 Condition (If Applicable)



Transmission Fluid



Steering, Suspension & Brakes

Steering

Steering wheel



Brake System

Parking Brake



Brake Master Cylinder



Brake Disc & Brake Pad



Brake Fluid



Suspension

Shock Absorbers



Electricals, Controls & Lights

Keys

Master Key



Spare Key(s)



Door Locks

Child Safety Locking



Dashboard

Instrument Panel



Airbags

Airbags	✓		
Controls	✓	Cruise Control	✓
Infotainment Display	✓	OBD Connector	✓
Radar (If Equipped)	✓	Music System	✓
Sunroof Operation			
Sunroof	✓		
Lights			
Headlight	✓	Interior Lights	✓
Tail Light Cluster	✓	Daylight Running Lights	✓
License Plate Light	✓		
Air Conditioning			
AC Cooling	✓	AC Switch	✓
AC System Leaks	✓	Center AC Vent	✓
Front Right AC Vent	✓	Heater	✓
Rear Blower Switch	✓	Rear Left AC Vent	✓
Parking Sensors	✓	USB Charging Port	✓
Rear Entertainment	✓	Power/ Manual Windows	✓
Seat Heaters	✓	Memory Seats	✓

Interiors & Luggage

Dashboard And Instrument Panel	✓	Central Console	✓
Cup Holder	✓	Glove Box	✓
Steering Wheel	✓	Sunvisor	✓
Seat Upholstery	✓	Manual Seat Movement	✓
Seat Belts	✓	Head Rest	✓

Door Controls And Trim	✓	Grab Handle	✓
Carpet	✓	Headliner	✓
Rear View Mirror	✓	Toolkit	✓

Tyres

Tyres Condition

Left Hand Side Front Tyre	✓	Left Hand Side Rear Tyre	✓
Right Hand Side Front Tyre	✓	Right Hand Side Rear Tyre	✓
Spare Tyre	✓		
Life remaining			
LHS Front Tyre	<65%	LHS Rear Tyre	<55%
RHS Front Tyre	<75%	RHS Rear Tyre	<65%
Spare Tyre	<65%		



A whole new world of cars

Auto New Market Block - 008, Ras Al Khor Industrial
Area 3, Al Aweer, Dubai, UAE